

**C32- DUAL PORT MULTIFUNCTION CNC
BOARD Rev. 5.4**



JANUARY 2015

USER'S MANUAL

TABLE OF CONTENTS

Page #

Contents

1.0	FEATURES	1
2.0	SPECIFICATIONS	2
3.0	BOARD DESCRIPTION	3
4.0	POWER TERMINALS AND CONFIGURATION JUMPERS	4
4.1	Power terminals and configuration Jumpers for inputs isolation	4
4.2	Power terminals and Jumper for Driver monitor circuit	4
4.3	Controller selection jumpers (IEEE1284).....	5
4.4	Driver Fault Jumpers	5
5.0	CONFIGURATION DIPSWITCH	6
5.1	Position 1	6
5.2	Position 2.....	6
5.3	Position 3 and 4.....	8
6.0	LED INDICATOR	9
7.0	VARIABLE SPEED CONTROL	9
7.1	Operation Mode Selection Jumper.....	10
8.0	PINOUT	16
9.0	WIRING SAMPLE	18
10.0	CONNECTING A PENDANT	19
11.0	WIRING DIAGRAMS	20
12.0	DIMENSIONS	24

1.0 FEATURES

- **Connects directly to the Smooth Stepper (from Warp9).**
- **IEEE 1284 Standard compatible.**
- **Built-in PWM-Based Speed Control.**
- **Built-in Isolated DC-DC converter for analog output voltage.**
- **Two Built-in Electro mechanical Relays with NO and NC positions for spindle control.**
- **RJ45 Connector for Easy VFD Connection.**
- **Monitors E-Stop, Safety Charge Pump and Drivers.**
- **Monitors VFD alarm signal.**
- **Enables and disable the drivers.**
- **Electromechanical Relay with NO and NC positions for general purpose (Pin 2_16 or Pin 2_17, jumper-selectable).**
- **Microcontroller based SCHP.**
- **RJ45 connectors for all I/Os.**
- **Easy Connections with CNC4PC relay boards and speed control boards.**
- **Connects 4 and 6 axis pendants (MPG2, MPG12, and MPG8)**
- **Opt-isolated inputs.**
- **Works with regular parallel ports.**
- **All TTL 5VDC signals.**

- **Buffered outputs.**
- **Status LEDs on all inputs and output connections.**
- **Works directly with popular CNC hardware and software.**
- **34 inputs and outputs on 2 ports.**


PINS	PORT1	PORT2	TOTAL
INPUT	5	13	18
OUTPUT	12	4	16
TOTAL	17	17	34

2.0 SPECIFICATIONS

OPTOISOLATED DIGITAL INPUT SPECIFICATIONS	
Numbers of inputs	18
On-state voltage range	2 to 5V DC
Maximum off-state voltage	0.8V
Typical signal delay	2.8uS

DIGITAL OUTPUT SPECIFICATIONS	
Number of outputs	16
Maximum output voltage	(5V power supply voltage) + 0.5V
Typical output current	24mA
Maximum off-state voltage	0.44 V
Maximum supported frequency	4M
Typical signal delay	10 nS
Time of transition to high impedance state	120mS*


3.0 BOARD DESCRIPTION



4.0 POWER TERMINALS AND CONFIGURATION JUMPERS


Before connecting the power supplies, follow steps below.

4.1 Power terminals and configuration Jumpers for inputs isolation



4.2 Power terminals and Jumper for Driver monitor circuit

Connects power supply external (5V), when using drivers with error or alarm signal common to its power GND. In this case, set jumper in “REQ” position.





4.3 Controller selection jumpers (IEEE1284)


Some motion controllers are not IEEE1284 compatible, set the jumper select the compatibility.

Compatible (IEEE1284)

Not Compatible (IEEE1284)



4.4 Driver Fault Jumpers



Some C34 boards have a special circuit that allows to the C32 detecting when the C34 has been disconnected.

To enable this detection function is required set jumper of the axes to be used in 1-2 position. If the C34 does not include this disconnection detection circuit or this function is not going to be used, set all jumpers in 2-3 position (see the respective C34 User manual).

If this function is enabled and any C34 is disconnected, the C32 will go to standby mode and a driver error will be shown.

5.0 CONFIGURATION DIPSWITCH



DIPSWITCH allows activating or deactivating the SCHK detection function, and selecting the driver to use and delays an enable signal for external devices.

5.1 Position 1

The enable output (Pin 17-Port 2) will be activated when the driver enable process starts. A delay in the signal activation time could be added by selecting the OFF position in the DIPSWITCH.

The table below shows the delay time for each supported driver.

DRIVER	DELAY (Sec.)
G320/340	5
G203	2
G210/201/Keling	2
Viper Servo driver	5



SWITCH 1 OFF: Delayed enable output (Pin 17-Port 2).

SWITCH 1 ON: Non Delayed enable output (Pin 17-Port 2).

5.2 Position 2

Safety Charge Pump “SCHK”. (Pin 17 “Port 2”)



This board takes advantage of Mach ability to send a specific frequency through one of the pins of the parallel port when the program is in control of the system.

Selecting the SCHK operation mode

Onboard DIPSWITCH allows activating or deactivating the SCHK detection function.

SWITCH 2 ON: Activate the SCHK detection function.


SWITCH 2 OFF: Deactivate the SCHK detection function.



Note:When the Safety Charge Pump function is activated, 5V are present in the E-Stop terminal and a valid SCHP signal is present, Port 2 Pin 17 will go high. This high signal can be used to enable other external devices, such as enabling other Breakout Boards, or relays that would enable servos, VFDs, contactors, etc....Variable Speed Control (pin 14 "Port 1") and VFD connection.

For Configuring the Charge Pump in Mach X:

Use the dialog *Config / Ports and pins / Output Signals*. Enable the *Charge Pump* output and configure it as is shown in the Fig. 12 Next, press the *apply* button.



5.3 Position 3 and 4

Select the driver you will use according to the table below.

OPERATION MODE	COMPATIBLE DRIVER	DIP 3	DIP 4
Mode 1	G320/DG4S	0	0
Mode 2	G203	1	0
Mode 3	G210/201/Keling	0	1
Mode 4	Viper	1	1

This board includes a Microcontroller-based driver monitoring system. It performs enabling and monitoring functions for servo Drivers, and only enabling function for stepper drivers. It is required connect the driver ERR/RES (servo drivers) or EN (stepper driver) terminal to the pin 5 of each RJ45 driver connector.

Here is a brief description of how these functions are performed for each operation mode.

Operation Mode 1 (G320/DG4S)

When the system starts, the C32 error/reset pins go to a low state (0V), making sure the driver remains disabled. When SCHP and E-Stop function are checked and validated and there is no fault signal coming from any driver, the system sends a high (5V) to the driver's error/reset pins for about 5 seconds to enable the drivers. After that the system monitors the driver's err/res pins. If a fault occurs on any driver (0V in driver ERR/RES pin) or an external fault occurs (E-Stop or SCHP fault), the system stops and sends an e-stop signal (Active low) to the controller. All outputs on the board are disabled and the drivers will be disabled by sending a LOW (0V) to the drivers ERR/RES pin. The system will remain that way until the conditions to restart are present again.

Operation Mode 2 (G203)

When the system starts, the C32 enable pins go to a HIGH state (5V). When SCHP and E-Stop function are checked and validated, the system send a LOW (0V) to the driver's EN pin for about 2 Sec, enabling the drivers. If an external error occurs, the system stops, resets the CNC software and sends a HIGH (5V) to the drivers EN pin. The system will remain that way until the conditions to restart are present again.

Operation Mode 3 (G210/201)

When the system starts, the C32 enable pins go to a LOW state (0V). When SCHP and E-Stop function are checked and validated, the system send a HIGH (5V) to the Drivers EN pin for about 2 Sec, enabling the Drivers. If an external error occurs, the system stops, resets the CNC software and sends a LOW (0V) to the drivers EN pin. The system will remain that way until the conditions to restart are present again.


Operation Mode 4 (Viper, Teco and Delta)

When the system starts, the C32 enable pins go to a low state (0V). When SCHP and E-Stop function are checked and validated and there is no fault signal coming from any driver, the system sends a high (5V) to the driver Fault output pin, enabling the drivers. After that the system monitors the driver's Fault Output pin. If an error is generated in any driver (0V in driver Fault Output pin) or an external error occurs, the system stops, resets the CNC software and sends a LOW (0V) to the drivers to ensure they remain disabled.

6.0 LED INDICATOR

The **standby LED** lights to indicate that the system is ready but disabled. When **Status LED**, (Green LED) lights, it indicates that the system is enabled.

There are 4 possible error sources: a driver fault, E-STOP error, SCHP error or VFD alarm. An LED will light close to the source of the fault.



7.0 VARIABLE SPEED CONTROL

Variable Speed Control allows controlling the spindle with PWM and direction signals, as if it was an axis motor. It converts the PWM signal into an analog (0-10VDC) signal.

A Variable Frequency Drive or Inverter works by modifying the frequency for AC motors. You can control most of these devices with an external analog signal (0-10VDC). That is, if there is 5VDC control signal, the motor will run at 50% of full speed, if there is 10VDC, the motor will run at 100% of full speed. If there is no voltage, then the motor will stop.

This function can also be used on many DC motor controllers by replacing the potentiometer that controls the speed.



WARNING: You will require a voltmeter to fine tune your system. Before connecting anything, please be sure to read your VFD's manual and make sure you understand all the safety issues.

7.1 Operation Mode Selection Jumper

This jumper allows selecting the way how the relays are activated when a PWM signal and REV signal are present in the pins 1_14 and 1_16.

In US mode one relay is used to start on CW and the other one to start on CCW. In international mode one relay is used for on/off, and the other one to indicate the CW or CCW rotation of the spindle motor. This board uses the step and direction setting for the spindle motor under motor output in Mach3 to generate the required action on the relays. For both cases the presence of PWM will indicate spindle start.

See the tables below.

US MODE (INT)				
PIN		RELAYS		
1_14	1_16	REL 1	REL 2	OPERATION
PWM	1	OFF	ON	Spindle ON CCW
PWM	0	ON	OFF	Spindle ON CW
0	1	OFF	OFF	Spindle Off
0	0	OFF	OFF	Spindle Off

INTERNATIONAL MODE (INT)				
INPUTS		RELAYS		
1_14	1_16	REL 1	REL 2	OPERATION
PWM	1	ON	ON	Spindle ON CCW
PWM	0	ON	OFF	Spindle ON CW
0	1	OFF	OFF	Spindle Off
0	0	OFF	OFF	Spindle Off

Relay 1 and 2 (Pins 16 “Port 1”)

They can be used to control the VFD. The relay specifications are shown in the table below.

ELECTROMECHANICAL RELAYS SPECIFICATIONS	
Maximum Current (AC)	7A@240VAC; 10A@125VAC
Maximum Current (DC)	15A@24VDC; 10A@28VDC

RJ45 for VFD Connection

This RJ45 port let you make an easy connection between this board and the VFD.

RJ45 for VFD	
RJ45 PIN	Function
1	Analog GND
2	Analog Output
3	VFD Alarm
4	REL 1 Normally Open Contact
5	Logic GND
6	REL 2 Normally Open Contact
7	Ext. 12VDC or 24VDC
8	Relay Common

An. GND: Ground of the Analog output signal

Analog Output: Isolated Analog Output Signal (0-10V)


VFD Alarm: Alarm signal generated by the VFD. (See **VFD ALARM JUMPERS** section)

Logic GND: Ground of the logic output signal

Ext. 12VDC or 24VDC: External 12VDC or 24VDC power supply used to enable the VFD.

Relay Common: The signal or voltage wired to this terminal can be connected to the common terminals of the relay 1 and relay 2. Use the on-board RELAY COMMON JUMPERS to do this connection. Remove the jumper if this connection is not required.


VFD Connection and configuration jumpers




VFD Alarm jumpers

Many VFDs have general purpose relay that can be configured to generate an alarm (Use its N.C. contacts). This board takes advantage of this feature to monitor the VFD status.


Set jumper as shown below for VFD



For monitor the alarm of VFD, set jumper as show below




If the VFD alarm monitoring function is not performed, set jumper as shown below



Configuring the Control Software:


For configuring Mach X follow these steps:

Go to Config / Ports&Pins / Motor Outputs. Enable the spindle and select the port and pins you wired for step and direction.




Ports&Pins configuration screenshot

Go to Config / Ports&Pins / Spindle Setup. In the motor control box, check Use Spindle Motor Output and PWM Control with a frequency of 300Hz. If using an external motion controller, like the Smooth Stepper, this needs to be configured in the plugin too.




Under Pulley Ratios set the pulley ratios of the machine.



Spindle Setup screenshot


Go to Config / Motor Tuning / Spindle. Set the velocity and acceleration to the max.



Motor Tuning and Setup screenshot

After configuring the Mach, these steps should be followed.

Connect a multimeter to the analog output terminals to fine tune the analog output. Comment the spindle to go at max speed and make sure you get +10vdc. To adjust it you can play with the potentiometer or the max speed you have set under motor tuning.



Pot for fine tuning the analog 0-10vdc output

Replacing a Potentiometer:

This circuit can be used to replace a potentiometer of a DC motor speed control circuits. This speed controller circuits are very commonly used by SIEG, KB Electronics, and many other Asian machines. Before explaining how to do it, please first keep in mind that it can be done if the voltage that goes through the pot is +12vdc or less. This circuit cannot be used for AC currents.

In most cases the terminals that go to the potentiometer will carry these signals:

P1 = GND

P2 = WIPER

P3 = REFERENCE VOLTAGE


These are the steps for replacing a potentiometer:

Measure the voltage difference between P1 and P3. Make sure it measures under +12vdc.

Fine tune the analog output to the output voltage you got from step 1.

Connect the ground from the analog output to the ground of the potentiometer (P1).

Connect the analog output to the wiper connection of the potentiometer (P2).



8.0 PINOUT




Fig. 9 RJ45 Distribution

RJ45_1		RJ45_2		RJ45_3		RJ45_4		RJ45_5		RJ45_6	
RJ45 PIN	P.P. PIN										
1	NC										
2	1_2 (Step X)	2	1_4 (Step Y)	2	1_6 (Step Z)	2	1_8 (Step A)	2	1_1 (Step 5)	2	1_14 (Step 6)
3	NC										
4	GND										
5	Err/res X	5	Err/res Y	5	Err/res Z	5	Err/res A	5	Err/res 5	5	Err/res 6
6	1_3 (Dir. X)	6	1_5 (Dir. Y)	6	1_7 (Dir. Z)	6	1_9 (Dir. A)	6	1_17 (Dir. 5)	6	1_16 (Dir. 6)
7	NC										
8	5V										
Supported connection											
G320/G340											
G203											
G210/G201											
Viper Servomotor											
Servo or Stepper Driver											


RJ45_7		RJ45_8		RJ45_9		RJ45_10		RJ45_11	
RJ45 PIN	P.P. PIN	RJ45 PIN	P.P. PIN	RJ45 PIN	P.P. PIN	RJ45 PIN	P.P. PIN	RJ45 PIN	P.P. PIN
1	GND_EXT	1	GND_EXT	1	GND	1	GND	1	GND_EXT
2	1_13	2	NC	2	2_17	2	NC	2	2_15
3	1_12	3	E-STOP	3	2_16	3	NC	3	2_13
4	1_11	4	2_11	4	2_1	4	2_16	4	2_12
5	NC	5	1_15	5	2_14	5	2_17	5	2_10
6	NC	6	NC	6	NC	6	NC	6	NC
7	5V_EXT	7	5V_EXT	7	5V	7	5V	7	5V_EXT
8	2_16	8	NC	8	NC	8	NC	8	NC
Supported connection		Supported connection		Supported connection		Supported connection		Supported connection	
C16, A32, C45, A61		C3, C48		C19, C15, C5, C8, C9, C47, C41, C6, C36, C54, C55, C56		C15, C8, C9, C55, C56		General Purpose Isolated inputs	

M_N: Parallel port or Smooth Stepper pin, where M is the port number and N is the pin number.

* When connecting optoisolated boards, a connection between the ground of the C32 and the board must be used. This is the case for the C15 and C19.

9.0 WIRING SAMPLE

SAMPLE PRODUCT INTEGRATION C32




Note: This wiring is just to illustrate a sample product application. Specific wiring may vary from system to system. It is the user's responsibility to implement it correctly.
For More Information

http://www.cnc4pc.com/Store/osc/product_info.php?products_id=255

10.0 CONNECTING A PENDANT

Set the *pendant enable jumper* in ENABLE position if a pendant is connected to the DB25 connector.



Pins 2_10, 2_11, 2_12, 2_13 and 2_15 are able to be used with the pendant (DB25 connector) or as general use input pin (RJ45 connector). Set the *Pendant ON/OFF selection jumper* in ON position if a pendant is connected to the DB25 connector. Otherwise set jumpers in OFF position.





Fig. 9 Pendant ON/OFF selection jumper

Note: Pins (2_2 - 2_9) are configured as inputs and they are only accessible through the DB25 for Pendant.

CONNECTING A C48

RJ45_8 provides an easy way to wire an External Probe and an external (Secondary) E-Stop. Image below shows a wiring sample for this connection




Note: The primary E-stop can be connected to C32 E-Stop terminals or to the C48 E-Stop input terminals.

11.0 WIRING DIAGRAMS

This connection is for signals of 12 or 24VDC, allows what inputs signals can be to 12 or 24V. This requires limiting resistors.


For signal of 12v, the limiting resistors should be of 1k
 For signal of 24v, the limiting resistors should be of 2.4k




Wiring diagram to connect switches with 12 or 24VDC power supply

While this board supports only TTL +5VDC signals, different kind of sensors and switches using different voltages can be connected using the diagrams that follow:

Note: The below wiring diagrams are an example, any input can be used for the connections.




Wiring diagram to connect switches




Wiring diagram to connect NPN open collector proximity sensors


For a 24V or 12V sensor, the recommended value for the external resistor R1 is 4.7K Ohm.



Wiring diagram to connect in parallel NPN open collector proximity sensors




Wiring diagram to connect NPN proximity sensors with internal pull up resistor



Wiring diagram to connect PNP open collector proximity sensors

Connecting PNP open collector proximity sensor with the C32 Rev.3		
Board	R Value (12V)	R Value (24V)
C32 Rev. 3	470Ω	1KΩ

Table 15 R value to Connect PNP open collector proximity sensor with the C33.



Wiring diagram to do an "Auto Tool Zero"

