Keysight N9321C/22C/23C/24C Spectrum Analyzer



User's Guide

Notices

© Keysight Technologies, Inc. 2012-2021

No part of this manual may be reproduced in any form or by any means (including electronic storage and retrieval or translation into a foreign language) without prior agreement and written consent from Keysight Technologies, Inc. as governed by United States and international copyright laws.

Trademark Acknowledgments

Manual Part Number

N9322-90002

Edition

Edition 4, August 2021

Published in China

Published by: Keysight Technologies No 116 Tianfu 4th Street Chengdu, 610041, China

Warranty

THE MATERIAL CONTAINED IN THIS DOCUMENT IS PROVIDED "AS IS," AND IS SUBJECT TO BEING CHANGED, WITHOUT NOTICE, IN FUTURE EDITIONS. FURTHER, TO THE MAXIMUM EXTENT PERMITTED BY APPLICABLE LAW, KEYSIGHT DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED WITH REGARD TO THIS MANUAL AND ANY INFORMATION CONTAINED HEREIN, INCLUDING BUT NOT LIMITED TO THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. **KEYSIGHT SHALL NOT BE LIABLE** FOR ERRORS OR FOR INCIDENTAL OR CONSEQUENTIAL DAMAGES IN CONNECTION WITH THE FURNISHING, USE, OR PERFORMANCE OF THIS DOCUMENT OR ANY INFORMATION CONTAINED HEREIN, SHOULD KEYSIGHT AND THE USER HAVE A SEPARATE WRITTEN AGREEMENT WITH WARRANTY TERMS

COVERING THE MATERIAL IN THIS DOCUMENT THAT CONFLICT WITH THESE TERMS, THE WARRANTY TERMS IN THE SEPARATE AGREEMENT WILL CONTROL.

Technology Licenses

The hardware and/or software described in this document are furnished under a license and may be used or copied only in accordance with the terms of such license.

U.S. Government Rights

The Software is "commercial computer software," as defined by Federal Acquisition Regulation ("FAR") 2.101. Pursuant to FAR 12.212 and 27.405-3 and Department of Defense FAR Supplement ("DFARS") 227.7202, the U.S. government acquires commercial computer software under the same terms by which the software is customarily provided to the public. Accordingly, Keysight provides the Software to U.S. government customers under its standard commercial license, which is embodied in its End User License Agreement (EULA), a copy of which can be found at

http://www.keysight.com/find/sweula

The license set forth in the EULA represents the exclusive authority by which the U.S. government may use, modify, distribute, or disclose the Software. The EULA and the license set forth therein. does not require or permit, among other things, that Keysight: (1) Furnish technical information related to commercial computer software or commercial computer software documentation that is not customarily provided to the public; or (2) Relinquish to, or otherwise provide, the government rights in excess of these rights customarily provided to the public to use, modify, reproduce, release, perform, display, or disclose commercial computer software or commercial computer software

documentation. No additional government requirements beyond those set forth in the EULA shall apply, except to the extent that those terms, rights, or licenses are explicitly required from all providers of commercial computer software pursuant to the FAR and the DFARS and are set forth specifically in writing elsewhere in the EULA. Keysight shall be under no obligation to update, revise or otherwise modify the Software. With respect to any technical data as defined by FAR 2.101, pursuant to FAR 12.211 and 27.404.2 and DFARS 227.7102, the U.S. government acquires no greater than Limited Rights as defined in FAR 27.401 or DFAR 227.7103-5 (c), as applicable in any technical data.

Safety Notices

CAUTION

A **CAUTION** notice denotes a hazard. It calls attention to an operating procedure, practice, or the like that, if not correctly performed or adhered to, could result in damage to the product or loss of important data. Do not proceed beyond a CAUTION notice until the indicated conditions are fully understood and met.

WARNING

A WARNING notice denotes a hazard. It calls attention to an operating procedure, practice, or the like that, if not correctly performed or adhered to, could result in personal injury or death. Do not proceed beyond a WARNING notice until the indicated conditions are fully understood and met.

Overview

1

N932xC at a Glance 2 Features 2 Optimized Usability 3 Front Panel Overview 4 Display Annotations 7 Rear Panel Overview 9 Front and rear panel symbols 10

Getting Started 11

Check the Shipment and Order List 12 Options 12 Safety Notice 13 **Power Requirements** 14 AC Power Cord 14 Power On and Check 16 Check for Instrument Messages 17 Environmental Requirements 18 18 Ventilation Cleaning Tips 18 Rack Mount 19 **Electrostatic Discharge Protection** 21 HSA and BSA PC software 22 Helpful Tips 23 Perform Calibration 23 Using an External Reference 24 Enable an Options 24

Firmware Upgrade 25 **IO** Configuration 26 Timed Power On/Off 26 Power Preset Last 27 Data Securities 27 Probe Power Output 27 Functions and Measurements 29 Making a Basic Measurement 30 Using the Front Panel 30 Presetting the Spectrum Analyzer 31 Viewing a Signal 32 Measuring Multiple Signals 34 Comparing Signals on the Same Screen Using Marker Delta 34 Comparing Signals not on the Same Screen Using Marker Delta 36 Resolving Signals of Equal Amplitude 38 Resolving Small Signals Hidden by Large Signals 41 Measuring a Low-Level Signal 44 **Reducing Input Attenuation** 44 Decreasing the Resolution Bandwidth 46 Trace Averaging 47 Improving Frequency Resolution and Accuracy 49 Tracking Drifting Signals 51 Measuring a Source's Frequency Drift 51 Making Distortion Measurements 53 Identifying Analyzer Generated Distortion 53 Third-Order Intermodulation Distortion 56

Stimulus Response Transmission 59 Measuring Stop Band Attenuation of a Lowpass Filter 62 Channel Scanner 65 Top/Bottom N Channel Scanner 65 List N Channel Scanner 67 Channel Scanner Setup 69 Spectrum Monitor 70 **Reflection Measurement** 72 Preparation 72 Measuring Cable Reflection 73 Measuring Distance to Fault 73 Making a Power Measurement with USB Power Sensor 75 Making an Average Power Measurement 76 Making a Peak Power Measurement 79 Power Meter Settings 81 Demodulate the AM/FM signal 84 Demodulating an AM Signal 84 Demodulating an FM Signal 85 Analysis the Modulated Signals 87 AM/FM Modulation Analysis 87 ASK/FSK Modulation Analysis 90 Measuring Channel Power 93 Perform an EMC Measurement 95 Files Operation 97 Locating and Viewing Files in the Catalog 97

Saving a File98Loading a File100Copying a File101Deleting a File101

Key Reference 103

Amplitude 104
BW 108
Display 112
Enter 113
ESC <- 114
Frequency 115
Marker 118
Meas 123
Channel Power 123
Occupied BW 125
ACPR 127
Spectrum Emission Mask 128
MODE 134
Tracking Generator 134
Power Meter 137
Spectrum Monitor 140
Reflection Measurement 142
AM/FM Modulation Analysis 144
ASK/FSK Modulation Analysis 148

Peak Search 152 System 155 Span 158 Sweep 159 Limit 164 Trace/Det 167

Instrument Messages 173

Overview 174 Command Errors 175 Execution Conflict 177 Device-Specific Errors 179

Troubleshooting 183

Check the Basics 18	34	
Warranty and Service	e Options 185	5
Contact Keysight Tech	nologies 186	

Menu Maps 187

Amplitude Menu 188 BW Menu 189 Sweep Menu 190 Display Menu 191 File/Mode - Task Planner 192 Frequency Menu 193 Limit Menu 194

195 Marker Menu Peak Search Menu 196 Measure Menu (1 of 2) 197 Measure Menu (2 of 2) 198 Mode - Tracking Generator 199 Mode - Power Meter 200 Mode - AM/FM Modulation Analysis 201 Mode - ASK/FSK Modulation Analysis 202 Mode - Reflection Measurement 203 Name Editor Menu 204 System Menu 205 SPAN Menu 206 Trace/Det Menu 207

1 Overview

Keysight N932xC at a Glance2Front Panel Overview4Rear Panel Overview9Front and rear panel symbols10

This chapter provides a description of the Keysight N932xC spectrum analyzer and an introduction to the buttons, features, and functions of the front and rear instrument panels.

For the latest product information, please refer to the link below:

http://www.keysight.com/find/n9321c

http://www.keysight.com/find/n9322c

http://www.keysight.com/find/n9323c

http://www.keysight.com/find/n9324c

For the latest option information, please refer to the link below:

http://www.keysight.com/find/sa_upgrades



Overview N932xC at a Glance

N932xC at a Glance

The Keysight N932xC spectrum analyzer is a portable, swept spectrum analyzer with a maximum frequency from 4.0 GHz(N9321C) up to 20 GHz(N9324C). It can be widely used in an electronic manufacturing environment and in functional/final/QA test systems.

Features

The Keysight N932xC spectrum analyzer primary features and functions are described below:

Power Measurement Suite

The built-in one-button power measurement suite offers channel power, ACP, OBW, and TOI measurements, and contains a pass/fail testing capability with a mask for out-of-channel emissions measurement.

• Precision Frequency Reference (Option PFR)

The optional OCXO frequency reference provides the precise frequency measurement capability.

• Spectrum Monitor (Option MNT)

Provides the capability to analyze the stability of a signal over time. The analyzer can be used to monitor the signal capturing performance or intermittent event over extended periods of time.

• High Sensitive Measurement (Option P04/P07/P13/P20)

Includes an optional pre-amplifier to enable more sensitive measurements. This feature is a great help in analysis of low level signals.

High Accuracy Power Measurement

Supports Keysight U2000 series (option PWM) and U2020 series (option PWP) power sensors for high accuracy power measurement as a power meter.

Modulation Analysis Function

provides optional AM/FM and ASK/FSK modulation analysis function. (AM/FM: Option-AMA ASK/FSK: Option-DMA)

• Tracking Generator (Option TG4/TG7)

provides an RF source for scalar network analysis.

• Baseband Channel (Option BB1 for N9321C/22C)

Provides superior DANL and SSB between 9 kHz to 10 MHz.

• Cable & Antenna Test (Option RM4/7; requires option TG4/7)

Provides VSWR, return loss, cable loss and distance-to-fault function for reflection measurement. This option is only available for N9321C/N9322C.

• Task Planner (Option TPN)

Provides task planner function to integrate different measurements for test automation.

• Time-gated Spectrum Analysis (Option TMG)

Measures any one of several signals separated in time and exclude interfering signals.

Channel Scanner (Option SCN)

provide the channel scan function in spectrum monitoring, coverage test, and band clearance.

• EMI filters and quasi-peak detector (Option EMC)

provide the EMI filters function and quasi-peak detector to make CISPR compliant EMI measurements.

Optimized Usability

The analyzer provides the enhanced usability as below:

- · Socket/Telnet remote control via USB, and LAN port.
- The BSA PC Software provides further editing and data analysis functions.
- The GPIB interface (option G01) makes the unit easily compatible with your GPIB test system.
- Security features (Option SEC) allows user to erase all customized files and data in analyzer for security.

Overview Front Panel Overview

Front Panel Overview



- 1 **Screen** 6.5 inch TFT color screen shows information of the current function, including the signal traces, status indicators, and instrument messages. Labels for softkeys are located on the right-hand side of the screen.
- 2 **Softkeys** are the unlabeled keys next to the screen. They activate functions displayed to the left of each key.
- 3 **Amplitude** activates the reference level function and accesses the amplitude softkeys, with which you set functions that affect data on the vertical axis.
- 4 **SPAN** sets the frequency range symmetrically about the center frequency. The frequency-span readout describes the total displayed frequency range.
- 5 **Frequency** activates the center-frequency function, and accesses the menu of frequency functions.
- 6 Function Keys relate directly to the following main functions:
 - **BW** activates the resolution bandwidth function and accesses the softkeys that control the bandwidth functions and averaging.
 - **Trace/Det** accesses the softkeys that allow you to set up the trace settings and detector functions.

- **Disp User** accesses the submenu to recall the frequently used user-defined state, or control what is displayed on the analyzer, including the display line, graticule and annotation after pressing **Shift**.
- **Mode** selects the measurement mode according to the activated options.
- **Marker** accesses the marker control keys that select the type and number of markers and turns them on and off.
- Limit Sweep accesses the softkeys that allow you to set the sweep time, select the sweep mode and trigger mode, or to set the limit functions after pressing Shift.
- Peak Search places a marker on the signal peak.
- **Meas** accesses the measurements mode selection submenu in spectrum analyzer mode or the measurement submenu in other optional modes.
- 7 Utility Keys relate directly to the following utilities:
 - Preset resets the analyzer to a known state
 - **System** accesses the submenu to configure a series of system settings, such as ports, option and languages.
 - Shift switches alternate upper blue function of the hardkeys.
 - Save File accesses the file operation submenu or activate the quick-save function after pressing Shift.
- 8 Arrow Keys The up and down arrow keys shift the selected item when you press [Mode] hardkey; you can also change the mode by rotating the knob.
- 9 Knob The knob increases or decreases a value, a numeric digit, or scrolls up and down to select an item in a list.
- 10 Data Control Keys includes the numeric keypad, **ENTER** key and backspace key, change the numeric value of an active function such as center frequency, start frequency, resolution bandwidth, and marker position. if the analyzer is in the remote mode, pressing **ENTER** key returns the analyzer to the local mode and enables front-panel control.

Overview Front Panel Overview

- **RF IN** connector receives the signal input. The maximum damage level is average continuous power +33 dBm or DC voltage 50 VDC. The impedance is 50 W. (N-type female).
- **PROBE POWER** connector provides power for high-impedance AC probes or other accessories (+15 V, -12 V, 150 mA maximum).
- **CAL OUT** connector provides an amplitude reference signal output of 40 MHz at -25 dBm (BNC female).
- **TG SOURCE** connector N-type female, is the source output for the built-in tracking generator. The maximum damage level is average continuous power +30 dBm or DC voltage 50 VDC. The impedance is 50 W. (for Option TG4/TG7)
- **Standby Switch** switches on all functions of the analyzer. To switch the analyzer off, press the switch for at least 2 seconds. This deactivates all the functions but retains power to internal circuits so long as the analyzer is connected to line power.
- **On LED** (green) lights when the analyzer is switched on.
- **Standby LED** lights when the analyzer is connected to the line power.
- **Remote LED** lights when the analyzer is remotely controlled by a PC via the USB host interface on the rear panel.
- **USB Device** connector provides a connection between an external USB devices and the analyzer, such as a USB memory device.

Display Annotations



Item	Description	Notes (Associated function key)	
1	Average Type	[BW] > Average Type	
2	Reference Offset	[Amplitude] > Ref Offset	
3	Amplitude scale	[Amplitude] > Scale Type	
4	Reference level	[Amplitude] > Ref Level	
5	Display Line	[Disp] > Display Line	
6	Time and date display	[System] > Time/Date	
7	RF attenuation	[Amplitude] > Attenuation	
8	Marker frequency	[Marker]	
9	Marker amplitude	[Marker]	
10	Indicator	S - Shift R - Remote Control	
11	USB disk indicator	The USB memory device is in use.	
12	Key menu title	Dependent on key selection.	

Overview Front Panel Overview

13	Softkey menu	Refer to Key Reference for details. Dependent on current function key selection.	
14	Frequency span	[SPAN]	
15	Sweep time	[Sweep] > Sweep Time	
16	Frequency offset	[Frequency] > Freq Offset	
17	Video band wid th	[BW] > Video BW	
18	Display status line	Display status and instrument messages.	
19	Resolution band wid th	[BW] > Res BW	
20	Center Frequency	[Frequency] > Center Freq	
21	Active function block	The function in use	
22	Low frequency channel	[Frequency] > LowFrqChannel	
23	Sweep time rule	[Sweep] > Sweep Setup > Swp Time Rule	
24	Sweep type	[Sweep] > Sweep Setup > Sweep Type	
25 - right	Trigger/Sweep F - free run trigger V - video trigger E - external trigger C - continuous sweep S - single sweep	[Sweep] > Trigger	
25 - left	Internal preamp	[Amplitude] > Int Preamp	
26	Trace mode W - clear write M - maximum hold m - minimum hold V - view S - store blank	[Trace]	
	Detect mode N - Normal A - Average P - Positive peak S - Sample N - Neg Peak	[Trace] > Detector	

Rear Panel Overview



- 1 Kensington Lock lock the instrument and keep its safety.
- 2 **USB Host connector** provides a connection between the analyzer and an PC for remote control.
- 3 LAN port A TCP/IP Interface used for remote operation.
- 4 EXT TRG IN (TTL) connector accepts an external voltage input, the positive edge of which triggers the analyzer sweep function. (BNC female)
- 5 **REF IN connector** accepts an external timebase with a frequency of 10 MHz, amplitude of –5 to +10 dBm. (BNC female)
- 6 **REF OUT connector** provides a frequency of 10 MHz, amplitude of -10 dBm reference output. (BNC female)
- 7 **REF OUT connector** (Option PFR) is an optional connector for precision 10 MHz reference from OCXO.
- 8 AC Power Receptacle accepts a three-pin line power plug.
- 9 **Power switch** isolates the analyzer from the AC line power. After switch on, the analyzer enters into standby mode and the orange standby LED on the front panel lights.
- 10 **GPIB connector** (Option G01) is an optional interface. This GPIB connector supports remote operation.

Overview Front and rear panel symbols

Front and rear panel symbols



The instruction manual symbol: indicates that the user must refer to specific instructions in the manual.

The CE mark: a registered trademark of the European Community.

ISM1-A

Shows that this is an Industrial Scientific and Medical Group 1 Class A product. (CISPR 11, Clause 4)



The CSA mark: a registered trademark of the Canadian Standards Association International.

ICES/NMB-001

The ISM device complies with Canadian Interference-Causing Equipment Standard-001.

Cet appareil ISM est conforme à la norme NMB-001 du Canada.



New Zealand by Responsible Suppliers must be marked with the Regulatory Compliance Mark (RCM Mark).

All Level 1, 2 or 3 electrical equipment offered for sale in Australia and



marks the "on/standby" position of the switch.



indicates that the instrument requires AC power input.



indicates this product complies with the WEEE Directive(2002/96/EC) marking requirements and you must not discard this equipment in domestic household waste. Do not dispose in domestic household waste.



indicates the time period during which no hazardous or toxic substance elements are expected to leak or deteriorate during normal use. Forty years is the expected useful life of the product.



KC mark: as Korea Certification. This equipment is Class A suitable for professional use and is for use in electromagnetic environments outside of the home.

```
A급 기기
(업무용 방송통신기자재)
이 기기는 업무용(A급) 전자파직합기기로서 관
매자 또는 사용자는 이 점을 주의하시기 바라
며, 가정외의 지역에서 사용하는 것을 목적으
로 합니다.
```

2 Getting Started

Check the Shipment and Order List12Safety Notice14Power Requirements15Power On and Check17Environmental Requirements19Electrostatic Discharge Protection22Helpful Tips23

This chapter helps you in preparing the spectrum analyzer for use and provides the information to start using the spectrum analyzer correctly.



Getting Started Check the Shipment and Order List

Check the Shipment and Order List

After receiving the shipment, first check the shipment and your order list. Inspect the shipping container and the cushioning material for signs of stress. Retain the shipping materials for future use, as you may wish to ship the analyzer to another location or to Keysight Technologies for service. Verify that the contents of the shipping container are complete.

Shipping Problems?

If the shipping materials are damaged or the contents of the container are incomplete, please contact the nearest Keysight Technologies office to arrange for repair or replacement. You will not need to wait for a claim settlement. If you must return an analyzer to Keysight Technologies, use the original (or comparable) shipping materials.

Options

Verify if that the shipment includes your ordered options by checking the option label on the shipping container.

Unless specified otherwise, all options are available when you order a spectrum analyzer; some options are also available as kits that you can order and install/activate after you receive the analyzer. Order kits through your local Keysight Sales and Service Office.

At the time of analyzer purchase, options can be ordered using your product number and the number of the option you are ordering. For example, if you are ordering option TG7, you would order N9322C-TG7.

If you are ordering an option after the purchase of your analyzer, you will need to add a K to the product number and then specify which option you are ordering. For example, N9322CK-TG7.

Safety Notice

	Read the following warnings and cautions carefully before powering on the spectrum analyzer to ensure personal and instrument safety.
WARNING	Always use a well-grounded, three-pin AC power cord to connect to power source. Personal injury may occur if there is any interruption of the AC power cord. Intentional interruption is prohibited. If this product is to be energized via an external auto transformer for voltage reduction, make sure that its common terminal is connected to a neutral (earthed pole) of the power supply.
WARNING	Personal injury may result if the spectrum analyzer covers are removed. There are no operator-serviceable parts inside. To avoid electrical shock, refer servicing to qualified personnel.
WARNING	Electrical shock may result if the spectrum analyzer is connected to the power supply while cleaning. Do not attempt to clean internally.
CAUTION	Prevent damage to the instrument and ensure protection of the input mixer by limiting average continuous power input to +33 dBm, DC voltage to 50 VDC with \geq 10 dB input attenuation. Instrument damage may result if these precautions are not followed.
CAUTION	To install the spectrum analyzer in other racks, note that they may promote shock hazards, overheating, dusting contamination, and inferior system performance. Consult your Keysight customer engineer about installation, warranty, and support details.

Power Requirements

The spectrum analyzer has an auto-ranging line voltage input. The AC power supply must meet the following requirements:

Voltage:	100 to 240 VAC	
Frequency:	50 to 60 Hz	
Power:	Maximum 100 W	

AC Power Cord

The analyzer is equipped with a three-wire power cord, in accordance with international safety standards. This cable grounds the analyzer cabinet when connected to an appropriate power line outlet. The cable appropriate to the original shipping location is included with the analyzer.

Various AC power cables are available that are unique to specific geographic areas. You can order additional AC power cables for use in different areas. The table **AC Power Cords** lists the available AC power cables, the plug configurations, and identifies the geographic area in which each cable is appropriate.

The detachable power cord is the product disconnecting device. It disconnects the mains circuits from the mains supply before other parts of the product. The front panel switch is only a standby switch and do not disconnect instrument from LINE power.

AC Power Cords

Plug Type	Cable Part Number	Plug ^a Description	For use in Country & Region
250V 10A	8121-1703	BS 1363/A	Option 900 United Kingdom, Hong Kong, Singapore, Malaysia
250V 10A	8120-0696	AS 3112:2000	Option 901 Australia, New Zealand
250V 16A	8120-1692	IEC 83 C4	Option 902 Continental Europe, Korea, Indonesia, Italy, Russia
125V 10A	8120-1521	CNS 10917-2 /NEMA 5-15P	Option 903 United States, Canada, Taiwan, Mexico
250V 10A	8120-2296	SEV 1011	Option 906 Switzerland
230V 15A	8120-4600	SABS 164-1	Option 917 South Africa, India
125V 15A	8120-4754	JIS C8303	Option 918 Japan
250V 16A	8120-5181	SI 32	Option 919 Israel
250V 10A	8120-8377	GB 1002	Option 922 China

a. Plug description describes the plug only. The part number is for the complete cable assembly.

Power On and Check

1 Connect the AC power cord into the instrument. Insert the plug into a power socket provided with a protective ground. Set the tilt adjusters for your preference.



Figure 1 Plug in and angle adjustment

- 2 Press the AC line switch 🔂 on the rear panel. The standby LED on the front panel will light and the spectrum analyzer is in standby mode (AC power applied).
- 3 Press the standby switch 🕁 on the front panel. The On LED will light, and the spectrum analyzer boots up.

Self-initialization takes about 25 seconds; the spectrum analyzer then defaults to the menu mode. After power on, let the spectrum analyzer warm up for 45 minutes for stabilization.

NOTE The front panel switch is a stand by switch only; it is not a power switch. To completely disconnect the spectrum analyzer from the AC line power, shut off the power switch on the rear panel.

Check for Instrument Messages

The spectrum analyzer has two categories of instrument messages: error and warning messages. A error message is triggered by operation errors, for example, parameter setting conflicts or data input that is out of the range of a parameter. An warning message may be triggered by hardware defects which could result in damage to instrument.

Here are some tips to check the instrument messages.

- Check the display to see if any messages display in the status bar. Press [System] > System Info > Error History to review each message. Refer to Chapter 5, "Instrument Messages" for detailed system message descriptions.
- 2 When you have reviewed and resolved all of the error messages, press [System] > System Info > Error History > Clear error queue to delete the messages.
- 3 Cycle the power to the analyzer and re-check to see if the instrument messages are still there.
- 4 If the error messages cannot be resolved, please contact the Keysight customer contact center for assistance or service.

Environmental Requirements

Keysight Technologies has designed this product for use in Installation Category II, Pollution Degree 2, per IEC 61010-1. Keysight has designed the spectrum analyzer for use under the following conditions:

- Indoor use
- Altitude < 3,000 meters
- Operating temperature range: +5 to +45°C;
 Storage temperature range: -20 to +70°C
- Relative humidity range 15% to 95 % at 40°C

NOTE

This equipment is Class A suitable for professional use and is for use in electromagnetic environments outside of the home.

Ventilation

Ventilation holes are located on the rear panel and one side of the spectrum analyzer cover. Do not allow these holes to be obstructed, as they allow air flow through the spectrum analyzer.

When installing the spectrum analyzer in a cabinet, do not restrict the convection of the analyzer. The ambient temperature outside the cabinet must be less than the maximum operating temperature of the spectrum analyzer by 4 °C for every 100 watts dissipated within the cabinet.

Cleaning Tips

To prevent electrical shock, disconnect the spectrum analyzer from line power before cleaning. Use a dry cloth or one slightly dampened with water to clean the external case parts. Do not attempt to clean internally.

Rack Mount

It is recommended to use the Keysight rack mount kit (option 1CM) to install the spectrum analyzer into a rack.

Do not attempt to rack mount the spectrum analyzer by the front panel handles only. This rack mount kit allows mounting of the spectrum analyzer with or without handles.

Refer to the following instructions when installing the rack mount kit on the spectrum analyzer.

- 1 Remove feet, key-locks and tilt stands.
- 2 Remove side trim strips and one middle screw per side.



Getting Started Environmental Requirements

3

per side.

Attach rackmount flange and front handle assembly with 3 screws

4 Attach the spectrum analyzer to the rack using the rackmount flanges with two dress screws per side.

CAUTION

Installing the spectrum analyzers into other racks may promote shock hazards, overheating, dust contamination, and inferior system performance. Consult your Keysight customer engineer about installation, warranty, and support details.

Electrostatic Discharge Protection

Electrostatic discharge (ESD) damages or destroys electronic components (the possibility of unseen damage caused by ESD is present whenever transported, stored, or while the instrument is in use).

This product contains components that are easily damaged by electrostatic discharge. To help reduce the possibility of ESD damage that can occur while using test equipment, follow these guidelines:

- 1 Before connecting any coaxial cable to the spectrum analyzer connector for the first time each day, momentarily short the center and outer conductors of the cable together to eliminate any potential electrostatic charges that may exist.
- 2 Personnel should be grounded with an approved type, 1 MW resistor-isolated ESD wrist-strap before touching the center pin of any connector, and before removing any assembly from the spectrum analyzer.
- 3 Be sure that all instruments are properly earth grounded to prevent build-up of static charges.

For more information about ESD and how to prevent ESD damage, contact the Electrostatic Discharge Association (*http://www.esda.org*). The ESD standards developed by this agency are sanctioned by the American National Standards Institute (ANSI).

HSA and BSA PC software

Keysight HSA and BSA PC software is an easy-to-use, PC-based remote control tool for the N932xC spectrum analyzer.

It is able to be discretely used as a spectrum monitor to display and control the trace scans simultaneously with the analyzer, or a file manager to send/get files between the analyzer and PC. It also provides some data analysis function for your further use.

You can get this software from the URL below: http://www.keysight.com/find/n9321c.

NOTE To connect the analyzer in the PC software via the USB/LAN port, please configure the analyzer in the Keysight IO libraries suite first. Please download and install the IO libraries suite from http://www.keysight.com/find/iolib

For the further description of the Keysight HSA and BSA PC software, please refer to the on-line help embedded in this software.

Helpful Tips

The following contains information to help in using and maintaining the instrument for optimum operation, including alignment, external reference, firmware update and option activation.

Perform Calibration

The N932xC provides three manual calibration function to calibrate the time base and amplitude. The analyzer should warm up for 30 minutes before calibration.

Time Base Calibration

Perform a time base calibration to guarantee the frequency accuracy. The analyzer should warm up for approximately 30 minutes before calibration.

When the calibration is triggered, the current measurement is interrupted and a gauge displays on the LCD. The gauge simply indicates calibration is in process. When it is finished, the interrupted measurement restarts.

Please refer to the operation procedures as below:

- 1 Input a 10 MHz, 0 dBm signal to EXT TRIG IN.
- 2 Press [System] > Service > Calibration > Time Base by Ext to initiate the calibration.

Time base calibration takes only a short time when the inner temperature is stable. When the inner temperature is increasing, calibration takes a long period of time or will fail. If the input reference signal is abnormal, the calibration cycle will take a long and unpredictable time to exit, and the LCD displays an error message. Getting Started Helpful Tips

Amplitude Calibration

The analyzer provides the internal amplitude calibration function. Please refer to the procedures below to perform an amplitude calibration:

- 1 Press [System] > More > Service > Calibration > Amp Alignment
- 2 Connect the CAL OUT and RF IN connector with a N-BNC cable. Then Press [Enter] to continue.

The calibration will start immediately. The calibration will be completed in several minutes.

Using an External Reference

To use an external 10 MHz source as the reference frequency, connect the external reference source to the REF IN connector on the rear panel. An EXT REF indicator will display in the upper bar of the display. The signal level must be in the range of -5 to +10 dBm. When the reference signal is ready, the instrument switches the reference from time base to the external reference.

Enable an Options

Option license key information is required to enable product options. Contact your nearest Keysight office for purchasing a license. Refer to the procedures below to activate the options you have purchased.

- 1 Press [System] > More > Service > Add Option
- 2 Enter the option number to be enabled. Press [Enter] to confirm your input.
- 3 Enter the license key in the on-screen window. Press [Enter] to confirm your input and terminate the license key input.
- 4 Press Activate License. The option will be enabled immediately.

The analyzer provides the trial license with limited time usage(15/270/365 days) of the wanted options.

Firmware Upgrade

Press **[System] > System Info > Show system** to view the firmware revision. If you call Keysight Technologies regarding your analyzer, it is helpful to have this revision and the analyzer serial number available.

Follow this procedure to finish the firmware update:

- 1 Download the firmware package from www.keysight.com/find/n9321c. Extract and copy the file to the *folder "N932xDATA"* into the root directory of a USB stick.
- 2 Plug the USB stick into the connector. Press [System] > Service > Upgrade Firmware

The analyzer will perform the update process automatically. The upgrade procedure will take several minutes. Once the upgrade is completed, please follow the instruction to reboot.

- **CAUTION** Any interruption during the update process will result in update failure and system data lost. Do not remove the USB storage device until the update is finished.
- **CAUTION** Abnormal power off may result in system reboot failure. A system boot failure note will be shown on the screen. Press [ESC] to reboot with the current firmware. If the reboot fails again, you need update the firmware by the on-screen instructions.

IO Configuration

The N932xC spectrum analyzer provides three types of IO connection: USB, LAN and optional GPIB interface. Press [System] > More > Port Setting to set the corresponding interface as your need.

USB

Select USB to enable the USB connection for remote control.

LAN

The N932xC supports LAN port connection for remote control. Press **[System] > {More} > {Port Setting} > {IP Config}** to set the IP parameters for the network connection.

Press {IP Address Static} to manually set the IP address, gateway and subnet mask with the proper LAN information, or just press {IP Address DCHP} to set the IP address in LAN dynamically according DCHP. Press {Apply} to enable the LAN connection according to the IP configuration you set.

GPIB

Press [System] > {More} > {Port Setting} > {GPIB Address} to set the GPIB address for the analyzer. This softkey is only valid after the option G01 is installed.

Timed Power On/Off

Pressing [System] > {Power On/Off Preset} > {Timed Pwr On} or

(Timed Pwr Off) sets the time switch to power on/off the N932xC in a user-defined time and date. This function requires the power supply connected.

Press {Repeat Mode Once/Everyday} to set the N932xC boot up/off in the pre-saved time everyday. The pre-saved date is invalid in this mode.

Power Preset Last

Press [System] > {Pwr On/Preset} > {Power On Last} to activate this function. For the standard N932xC, this operation only save the last state if the analyzer is turned off by the front panel power switch.

Data Securities

The N932xC offers the optional memory erase function for data security. Press [System] > {More} > {Securities} > {Erase Memory} to erase all the user data in internal memory. Press Enter as a terminator to start the erase process immediately.

The memory erase process takes about 15 minutes. During the time, there must be a constant power supply to ensure the successful erase. If the erase process is interrupted, please reboot the instrument and erase memory again.

Probe Power Output

The Probe Power provides power for high-impedance AC probes or other accessories (+15 V, -12V, 150 mA maximum).

The Probe Power is set to off as default. Press [System] > {More} > {Port Setting} > {Probe Power On} to switch on the probe power output.

Getting Started Helpful Tips
3 Functions and Measurements

Making a Basic Measurement 30 Measuring Multiple Signals 34 Measuring a Low-Level Signal 44 Improving Frequency Resolution and Accuracy 49 Tracking Drifting Signals 51 Making Distortion Measurements 53 Stimulus Response Transmission 59 Measuring Stop Band Attenuation of a Lowpass Filter 62 Channel Scanner 65 Spectrum Monitor 70 72 Reflection Measurement Making a Power Measurement with USB Power Sensor 75 Demodulate the AM/FM signal 84 Analysis the Modulated Signals 87 Measuring Channel Power 93 Perform an EMC Measurement 95 Files Operation 97

This chapter provides information on the analyzer functions and specific measurements capabilities of the spectrum analyzer.



Making a Basic Measurement

This section provides information on basic operations. It assumes that you are familiar with the front and top panel buttons and keys, and display annotations of your analyzer. If you are not, please refer to **"Front Panel Overview" on page 4** and **"Rear Panel Overview" on page 9**.

For more details on making measurements, please refer to **"Key Reference" on page 103**".

Using the Front Panel

This section provides you with the information on using the front panel of the spectrum analyzer.

Entering Data

When setting the measurement parameters, there are several ways to enter or modify the value of the active function:

Knob	Increments or decrements the current value.
Arrow Keys	Increments or decrements the current value by a step unit.
Numeric Keys	Enters a specific value. Then press the desired terminator (either a unit softkey, or [Enter] hardkey).
Unit Softkeys	Terminate (enter) a value with a unit softkey from the menu.
Enter Key	Terminates an entry when no unit of measure is required, or the instrument uses the default unit.
ESC Key	To delete the current input digit prior to entering the value.
	Using Softkeys
	The softkeys are used to modify the analyzer function parameter settings. Some examples of softkey types are:
Toggle	Turn on or off an instrument state.
Submenu	Displays a secondary menu of softkeys, {More}.
Choice	Selecting from a list of standard values or filenames.

Adjust Highlights the softkey and sets the active function.

Presetting the Spectrum Analyzer

Preset function provides a known instrument status for making measurements. There are two types of presets, DFT (default), user and last:

Press System > Pwr on/Off Preset > Preset Type to select the preset type.

When **Preset Type** is set to **DFT**, pressing **Preset** triggers a factory preset condition. The instrument will immediately return to the factory default instrument parameter setting.

When **Preset Type** is set to **User**, pressing **Preset** triggers a user preset condition. The instrument will immediately return to the user defined instrument parameter setting.

When **Preset Type** is set to **Last**, pressing **Preset** triggers a last power-off condition. The instrument will immediately return to the parameter setting when it is power off last time.

Setting up a User Preset

To quickly return to instrument settings that are user defined, perform the following steps to save the instrument state as the user-defined preset:

- 1 Set the instrument parameters to the values and settings necessary for the user preset state. This would include the frequency, span, amplitude, BW, and measurement type and any other setup details desired.
- 2 Press System > Pwr on/off Preset > Save User, to save the current instrument settings as the 'user preset' state. The user preset will not affect the default factory preset settings. User preset settings can be changed and saved at any time.

Viewing a Signal

Refer to the procedures below to view a signal.

- 1 Press System > Pow on/off Preset > Preset Type > DFT to enable the factory-defined preset state.
- 2 Press **Preset** to restore the analyzer to its factory-defined state.
- **3** Connect the 10 MHz **REF OUT** on the rear panel to the front-panel **RF IN**.

Setting the Reference Level and Center Frequency

- 1 Press Amplitude > 10 > dBm to set 10 dBm reference level.
- 2 Press Frequency > 30 > MHz to set 30 MHz to center frequency.

Setting Frequency Span

Press **Span > 50 > MHz** to set 50 MHz frequency span.

NOTE Changing the reference level changes the amplitude value of the top graticule line. Changing the center frequency changes the horizontal placement of the signal on the display. Increasing the span will increase the frequency range that appears horizontally across the display.

Reading Frequency and Amplitude

1 Press **Peak Search** to place a marker (labeled 1) on the 10 MHz peak.

Note that the frequency and amplitude of the marker appear both in the active function block, and in the upper-right corner of the screen.



Figure 3-1 10 MHz Internal Reference Signal Marker Annotation

2 Use the knob, the arrow keys, or the softkeys in the **Peak Search** menu to move the marker. The marker information will be displayed in the upper-right corner of the screen.

Changing Reference Level

- 1 Press **Amplitude** and note that reference level **(Ref Level)** is now the active function.
- 2 Press Marker > Marker To > Mkr-> Ref Lvl.

NOTE Changing the reference level changes the amplitude value of the top graticule line.

Measuring Multiple Signals

This section provides the information on how to measure multiple signals.

Comparing Signals on the Same Screen Using Marker Delta

The delta marker function allows the user to compare two signals when both appear on the screen at the same time.

In the following example, harmonics of the 10 MHz reference signal available are used to measure frequency and amplitude differences between two signals on the same screen. Delta marker is used to demonstrate this comparison.

1 Preset the analyzer:

Press Preset (With Preset Type of DFT)

- 2 Connect the rear panel **REF OUT** to the front panel **RF IN**.
- **3** Set the analyzer center frequency, span and reference level to view the 10 MHz signal and its harmonics up to 50 MHz:

Press Frequency > 30 > MHz

Press Span > 50 > MHz

Press Amplitude > 10 > dBm

4 Place a marker at the highest peak on the display (10 MHz):

Press Peak Search

The marker should be on the 10 MHz reference signal. Use the **Next Right Pk** and **Next Left Pk** softkeys to move the marker from peak to peak.

5 Anchor the first marker and activate a second marker:

Press Marker > Mode > Delta

The label on the first marker now reads **1R**, indicating that it is marking the reference point.

6 Move the second marker to another signal peak using the front-panel knob or by using **Peak Search**.

Press Peak Search > Next Peak or

Press **Peak Search > Next Right Pk** or **Next Left Pk**. Continue pressing the **Next Pk** softkeys until the marker is on the correct signal peak.

The amplitude and frequency differences between the markers are displayed in the active function block.



Figure 3-2 Delta pair marker with signals on the same screen

NOTE

To increase the resolution of the marker readings, turn on the frequency count function. For more information, refer to "Improving Frequency Resolution and Accuracy" on page 49.

Comparing Signals not on the Same Screen Using Marker Delta

The analyzer will compare the frequency and amplitude differences between two signals which are not displayed on the screen at the same time. (This technique is useful for harmonic distortion tests.)

In this example, the analyzer's 10 MHz signal is used to measure frequency and amplitude differences between a signal on screen, and another signal off screen. Delta marker is used to demonstrate this comparison.

1 Preset the analyzer:

Press Preset (With Preset Type set to DFT)

- 2 Connect the rear panel **REF OUT** to the front panel **RF IN**.
- **3** Set the center frequency, span and reference level to view only the 50 MHz signal:

Press Frequency > 50 > MHz

Press Span > 25 > MHz

Press Amplitude > 10 > dBm

4 Place a marker on the 50 MHz peak and then set the center frequency step size equal to the marker frequency (10 MHz):

Press Peak Search

Press Marker > Marker To > To Center

Press Frequency > More > CF Step > 10 > MHz

5 Activate the marker delta function:

Press Marker > Mode > Delta

6 Increase the center frequency by 10 MHz:

Press Frequency, 💽

The first marker moves to the left edge of the screen, at the amplitude of the first signal peak.

Figure 3-3 shows the reference annotation for the delta marker (**1R**) at the left side of the display, indicating that the marker set at the 50 MHz reference signal is at a lower frequency than the frequency range currently displayed.



Figure 3-3 Delta Marker with Reference Signal Off-Screen

The delta marker appears on the peak of the 100 MHz component. The delta marker annotation displays the amplitude and frequency difference between the 50 and 100 MHz signal peaks.

7 Press Marker > Mode > Off to turn the markers off.

Resolving Signals of Equal Amplitude

In this example a decrease in the resolution bandwidth (RBW) is used in combination with a decrease in video bandwidth (VBW) to resolve two signals of equal amplitude with a frequency separation of 100 kHz.



Figure 3-4 Setup for obtaining two signals

Notice that the final RBW selection to resolve the signals is the same width as the signal separation while the VBW is slightly narrower than the RBW.

- 1 Connect two sources to the analyzer input as shown above.
- 2 Set one source to 300 MHz. Set the frequency of the other source to 300.1 MHz. Set both source amplitudes to –20 dBm.
- **3** Setup the analyzer to view the signals:

Press Preset (With Preset Type of DFT)

Press Frequency > 300 > MHz

Press BW > 300 > kHz

Press Span > 2 > MHz

A single signal peak is visible. See **Figure 3-5** for example.

If the signal peak is not present on the display, increase the frequency span out to 20 MHz, turn signal tracking on, decrease the span back to 2 MHz and turn signal tracking off:

Press Span > 20 > MHz

Press Peak Search

Press Span > 2 > MHz



Figure 3-5 Unresolved Signals of Equal Amplitude

4 Change the resolution bandwidth (RBW) to 100 kHz so that the RBW setting is less than or equal to the frequency separation of the two signals:

Press BW > 100 > kHz

Notice that the peak of the signal has become flattened indicating that two signals are present.

5 Decrease the video bandwidth to 3 kHz:

Press BW > Video BW > 3 > kHz

Two signals are now visible as shown in **Figure 3-6**. Use the front-panel knob or arrow keys to further reduce the resolution bandwidth and better resolve the signals.

Functions and Measurements Measuring Multiple Signals

Decreasing the resolution bandwidth improves the resolution of the individual signals and increases the sweep time.



Figure 3-6 Resolving Signals of Equal Amplitude

For fastest measurement times, use the widest possible resolution bandwidth. Under factory preset conditions, the resolution bandwidth is coupled to the span.

Resolving Small Signals Hidden by Large Signals

This example uses narrow resolution bandwidths to resolve two RF signals that have a frequency separation of 50 kHz and an amplitude difference of 60 dB.

- 1 Connect two sources to the **RF IN** as shown in Figure 3-4.
- 2 Set one source to 300 MHz at -10 dBm. Set the other source to 300.05 MHz at -70 dBm.
- **3** Set the analyzer as follows:

Press Preset. (With Preset Type of DFT)

Press Frequency > 300 > MHz

Press BW > 30 > kHz

Press Span > 500 > kHz

4 Set the 300 MHz signal to the reference level:

Press Peak Search

Press Marker > Marker To > To Reference

NOTE

The 30 kHz filter shape factor of 15:1 has a band width of 450 kHz at the 60 dB point. The half-band width (225 kHz) is NOT narrower than the frequency separation of 50 kHz, so the input signals can not be resolved.

Functions and Measurements Measuring Multiple Signals



Figure 3-7 Unresolved small signal from large signal

5 Reduce the resolution bandwidth filter to view the smaller signal. The smaller signal will be hidden by the larger signal when the bandwidth settings are wider. Reducing the RBW setting will allow less of the larger signal to pass through the analyzer and the smaller signals peak will then rise out of the noise floor. Place a delta marker on the smaller signal:

Press BW > 1 > kHz

Press Peak Search

Press Marker > Mode > Delta



NOTE

The 1 kHz filter shape factor of 15:1 has a band width of 15 kHz at the 60 dB point. The half-band width (7.5 kHz) is narrower than the frequency separation of 50 kHz, so the input signals can be resolved.

Measuring a Low-Level Signal

This section provides information on measuring low-level signals and distinguishing them from spectrum noise.

Reducing Input Attenuation

The ability to measure a low-level signal is limited by internally generated noise of the spectrum analyzer. The analyzers input attenuator affects the level of a signal passing through the analyzer. If a signal power level is close to the noise floor, reducing the analyzer input attenuation will help raise the signal so that it can be seen rising out of the noise.

CAUTION Ensure that the total power of all input signals at the analyzer RF input does not exceed +30 dBm (1 Watt).

1 Preset the analyzer

Press Preset (With Preset Type of DFT)

2 Set the source frequency to 300 MHz, amplitude to -70 dBm. Connect the source **RF OUT** to the analyzer **RF IN**.

Figure 3-9 Setup for obtaining one signal



3 Set the center frequency, span and reference level:

Press Frequency > 300 > MHz

Press Span > 2 > MHz

Press Amplitude > 40 > –dBm.

4 Move the desired peak to the center of the display:

Press Peak Search

Press Marker > Marker To > To Center

5 Reduce the span to 500 kHz, if necessary re-center the peak:

Press Span > 500 > kHz

6 Set the attenuation to 20 dB:

Press Amplitude > Attenuation > 20 > dB



Figure 3-10A signal closer to the noise level

Note that increasing the attenuation moves the noise floor closer to the signal level.

7 To allow more of the signal power to pass through the analyzer, decrease the attenuation to 0 dB.

Functions and Measurements Measuring a Low-Level Signal

A lower attenuation value will mean that more of the signal strength will be displayed on screen:

Press Amplitude > Attenuation > 0 > dB

Figure 3-11 Measuring a low-level signal using 0 dB Attenuation



Decreasing the Resolution Bandwidth

Resolution bandwidth settings affect the level of internal noise but have little affect on the displayed level of continuous wave (CW) signals. Decreasing the RBW by a decade (factor of ten) reduces the noise floor by 10 dB.

- 1 Refer to the procedure "Reducing Input Attenuation" on page 44 and follow steps 1, 2 and 3.
- 2 Decrease the resolution bandwidth:

Press BW and 🔽

The low-level signal appears more clearly due to the noise level being reduced by the decrease in RBW (see Figure 3-12).





A "#" mark appears next to the Res BW annotation in the lower left corner of the screen, indicating that the resolution bandwidth is uncoupled.

Uncoupled indicates that the function is in manual control mode, not auto control mode. Manual control mode allows the user to change the parameter value for that function without affecting any other settings.

NOTE

The analyzer allows you to change the RBW in a 1-3-10 sequence by the data control keys. The RBWs below 1 kHz are digital and have a selectivity ratio of 5:1 while RBWs at 1 kHz and higher have a 15:1 selectivity ratio. The maximum RBW is 3 MHz and minimum is 10 Hz.

Trace Averaging

Averaging is a digital process in which each sweep of the trace returns measurement values for each point in the trace. These values are then mathematically averaged with the previous sweep trace data which has been stored in the analyzer. The amount of averaging is selected by choosing the number of trace sweeps to be included in the process. The averaging function uses the most recent trace sweep values so that the display shows any signal changes.

Selecting averaging, when the analyzer is auto-coupled, changes the detection mode to **Sample**, smoothing the displayed noise level.

NOTE This is a trace processing function and is not the same as using the average detector (as described on page 47).

- 1 Refer to the procedure "Reducing Input Attenuation" on page 44 of this chapter and follow steps 1, 2 and 3.
- 2 To turn averaging on, toggle the softkey menu labeled Average:

Press BW > Average (On)

3 Set the number of averages to 20, using the number keypad, up and down arrows, or the knob:

Press 20, Enter

The averaging process smooths the viewed trace, low level signals become more visible (see Figure 3-13). Changes to the average number will restart the averaging process.



Figure 3-13Trace Averaging

Improving Frequency Resolution and Accuracy

This section provides information on using the frequency counter function to improve frequency resolution and accuracy.

- 1 Press Preset (With Preset Type of DFT)
- 2 Connect a cable from the front panel **CAL OUT** to **RF IN**;

Press **System > Service > Calibration > CAL OUT ON** to toggle on and enable the 50 MHz amplitude reference signal.

3 Press **Frequency > Auto Tune**.

The analyzer will detect the signal peak and locate it to the center of the display (Refer to "Auto Tune" on page 115).

4 Turn the frequency counter on:

Press Marker > Function > Counter.

5 Move the marker, with the front-panel knob, half-way down the skirt of the signal response.



Figure 3-14Using Frequency Counter

NOTE

The frequency and amplitude of the marker appears in the active function area (this is not the counted result). The counted result appears in the upper-right corner of the display to the right-side of C1.

The marker readout in the active frequency function changes while the counted frequency result (upper-right corner of display) does not. For an accurate count, the marker need not be placed at the exact peak of the signal response.

- **NOTE** The Frequency counter properly functions only on stable, CW signals or discrete spectral components. The marker power level must be greater than 40 dB above the displayed noise level.
 - 6 To turn off the marker counter:

Press Marker > Function > Off.

NOTE When using the frequency counter function, the ratio of the resolution band width to the span must be greater than 0.02.

Tracking Drifting Signals

This section provides information on measuring and tracking signals that drift in frequency.

Measuring a Source's Frequency Drift

The analyzer will measure source stability. The maximum amplitude level and the frequency drift of an input signal trace can be displayed and held by using the maximum hold function. Using the maximum hold function you can measure and determine how much of the frequency spectrum a signal occupies. For more information, refer to "Max Hold" on page 167.

Use signal tracking to return a signal drifting in frequency to the center of the display. The drifting is captured by the analyzer using the maximum hold function.

- 1 Connect the signal generator to the analyzer **RF IN**.
- 2 Output a signal with the frequency of 300 MHz and amplitude of -20 dBm.
- **3** Set the analyzer center frequency, span and reference level.

Press Preset. (With Preset Type of DFT)

Press Frequency > 300 > MHz

Press Span > 10 > MHz

Press Amplitude > -10 > dBm

4 Place a marker on the peak of the signal:

Press Peak Search

Press Marker > Marker To > To Center

Press Span > 1 > MHz

The signal is in the center of the display.

6 Measure the excursion of the signal with maximum hold:

Press Trace/Det > Max Hold

Functions and Measurements Tracking Drifting Signals

As the signal varies, maximum hold maintains the maximum responses of the input signal. Annotation on the left side of the screen indicates the trace mode. For example, **M1 S2 S3 S4**, indicates trace 1 is in maximum-hold mode, trace 2, trace 3, and trace 4 are in store-blank mode.

7 Activate trace 2 and change the mode to continuous sweep:

Press Trace/Det > Select Trace > Trace 2

Press Clear Write

Trace 1 remains in maximum hold mode to show any drift in the signal.

8 Slowly increase the frequency of the signal generator. Your analyzer display should look similar to Figure 3-15.

Figure 3-15 Viewing a Drifting Signal With Max Hold and Clear Write



Making Distortion Measurements

This section provides information on measuring and identifying signal distortion.

Identifying Analyzer Generated Distortion

High-level input signals may cause analyzer distortion products that could mask the real distortion measured on the input signal. Use trace and the RF input attenuator to determine which signals, if any, are internally generated distortion products.

In this example, we use the RF output of a signal generator to determine whether the harmonic distortion products are internally generated by the analyzer.

- 1 Connect the signal generator to the analyzer **RF IN**.
- 2 Set the source frequency to 200 MHz, amplitude to 0 dBm.
- **3** Set the analyzer center frequency and span:

Press Preset

Press Frequency > 400 > MHz

Press Span > 500 > MHz

Figure 3-16Harmonic Distortion



Functions and Measurements Making Distortion Measurements

The signal produces harmonic products (spaced 200 MHz from the original 200 MHz signal) in the analyzer input mixer as shown in **Figure 3-16**.

4 Change the center frequency to the value of the first harmonic:

Press Peak Search > Next Peak

Press Marker > Marker To > To Center

5 Change the span to 50 MHz and re-center the signal:

Press Span > 50 > MHz

Press Peak Search

Press Marker > Marker To > To Center

6 Set the attenuation to 0 dB:

Press Amplitude > Attenuation > 0 > dB

7 To determine whether the analyzer generates harmonic distortion products, first display the trace data in trace 2 as follows:

Press Trace/Det > Select Trace > Trace 2

Press Clear Write

8 Allow trace 2 to update (minimum two sweeps), then store the data from trace 2 and place a delta marker on the harmonic of trace 2:

Press Trace/Det > View

Press Peak Search

Press Marker > Mode > Delta

The analyzer display shows the stored data in trace 2 and the measured data in trace 1. The **Marker** Δ indicator reads the difference in amplitude between the reference and active markers.

9 Increase the RF attenuation to 10 dB:

Press Amplitude > Attenuation > 10 > dB

Notice the **Marker** amplitude readout. This is the difference of the distortion product amplitude between 0 dB and 10 dB input attenuation settings. If the **Marker** absolute amplitude is approximately ≥ 1 dB for an input attenuator change, the analyzer is generating, at least in part, the distortion.





1) Increased input attenuation causes poorer signal-to-noise ratio. This causes the ${\it Marker} \Delta$ to be positive.

2) The reduced contribution of the analyzer circuits to the harmonic measurement causes the Marker Δ to be negative.

Large **Marker** Δ readout indicates significant measurement errors. Set the input attenuator to minimize the absolute value of **Marker** Δ .

Third-Order Intermodulation Distortion

Two-tone, third-order intermodulation distortion is a common specification in communication systems. When two signals are present in a non-linear system, they may interact and create third-order intermodulation distortion (TOI) products that are located close to the original signals. System components such as amplifiers and mixers contribute to the generation of these distortion products.

This example will test a device for third-order intermodulation through the use of markers. Two sources are used, one set to 300 MHz and the other to 301 MHz.

1 Connect the equipment as shown in figure below. This combination of signal generators, low pass filters, and directional coupler (used as a combiner) results in a two-tone source with very low intermodulation distortion. Although the distortion from this setup may be better than the specified performance of the analyzer, it is useful for determining the TOI performance of the source/analyzer combination. After the performance of the source/analyzer combination has been verified, the device-under-test (DUT) (for example, an amplifier) would be inserted between the directional coupler output and the analyzer input.



NOTE

The coupler should have a high degree of isolation between the two input ports so the sources do not intermodulate each other.

- 2 Set one source (signal generator) to 300 MHz and the other source to 301 MHz, for a frequency separation of 1 MHz. Set the sources equal in amplitude as measured by the analyzer (in this example, they are set to -5 dBm).
- **3** Set the analyzer center frequency and span:

Press Preset (With Preset Type of DFT)

Press Frequency > 300.5 > MHz

Press Span > 5 > MHz

4 Reduce the RBW until the distortion products are visible:

Press **BW** and 🔄

5 Move the signal to the reference level:

Press Peak Search

Press Marker > Marker To > To Reference

6 Reduce the RBW until the distortion products are visible:

Press **BW** and 📀

7 Activate the second marker and place it on the peak of the distortion product (beside the test signal) using the **Next Peak**:

Press Marker > Mode > Delta

Press Peak Search > Next Peak

8 Measure the other distortion product:

Press Marker > Mode > Normal

Press Peak Search > Next Peak

Functions and Measurements Making Distortion Measurements

9 Measure the difference between this test signal and the second distortion product (see Figure 3-17):

Press Marker > Mode > Delta

Press Peak Search > Next Peak



Figure 3-17Measuring the Distortion Product

Stimulus Response Transmission

The procedure below describes using the built-in tracking generator of the analyzer to measure the rejection of a low pass filter. A type of transmission measurement.

1 To measure the rejection of a low pass filter, connect the equipment as shown in Figure 3-18. A 370 MHz low pass filter as the DUT.

Figure 3-18Transmission Measurement Test Setup

- 2 Press Preset. (With Preset Type of DFT)
- **3** Set the start and stop frequencies and resolution bandwidth:

Press Frequency > Start Freq > 100 > MHz

Press Frequency> Stop Freq > 1 > GHz

Press Bw > 3 > MHz

4 Turn on the tracking generator and if necessary, set the output power to -10 dBm:

Press Mode > Tracking Generator > Amplitude (On) > -10 > dBm

CAUTION

Excessive signal input may damage the DUT. Do not exceed the maximum power that the device under test can tolerate.

NOTE	To reduce ripples caused by source return loss, use 6 dB or greater output attenuation. Tracking generator output attenuation is normally a function of the source power selected. However, the output attenuation may be controlled in the Tracking Generator menu.
F	To increase measurement consitivity and smooth the point:
5	To increase measurement sensitivity and smooth the hoise.
	Press BW > 30 > kHz
	Press BW > Video BW > 300 > kHz
	A decrease in displayed amplitude is caused by tracking error.
6	Connect the cable from the tracking generator output to the analyzer input. Store the frequency response in trace 3 and normalize:
	Press Meas > Normalize > Store Ref $(1 \rightarrow 4)$ > Normalize (On)
7	Reconnect the DUT to the analyzer and change the normalized reference position:
	Press Meas > Normalize > Norm Ref Posn > 8
8	Measure the rejection of the low pass filter:
	Press Marker > 370 > MHz,
	Press Mode > Delta > 160> MHz

The marker readout displays the rejection of the filter at 160 MHz above the cutoff frequency of the low pass filter. See Figure 3-19 as below.



Functions and Measurements Measuring Stop Band Attenuation of a Lowpass Filter

Measuring Stop Band Attenuation of a Lowpass Filter

When measuring filter performance, it is useful to look at the stimulus response over a wide frequency range. Setting the analyzer y-axis (amplitude) to Log scale type presents the measurement data in a usable format for determining filter characteristics.

The following example uses the tracking generator to measure the stop band attenuation of a 370 MHz low pass filter.

1 To measure the response of a low pass filter, connect the equipment as shown in Figure 3-20. This example uses a 370 MHz low pass filter.

Figure 3-20Transmission Measurement Test Setup



- 2 Press Preset. (With Preset Type of Factory)
- **3** Set the start and stop frequencies and resolution bandwidth:

Press Frequency > Start Freq > 100 > MHz

Press Frequency > Stop Freq > 1 > GHz

Press Amplitude > Scale Type > Log

4 Set the resolution bandwidth to 10 kHz:

Press BW > 10 > KHz

CAUTION Excessive signal input may damage the DUT. Do not exceed the maximum power that the device under test can tolerate.

5 Turn on the tracking generator and, if necessary, set the output power to -10 dBm:

Press Mode > Tracking Generator > Amplitude (On) > -10 > dBm

6 Connect the test cable (but not the DUT) from the tracking generator output to the analyzer input. Store the frequency response into trace 3 and normalize:

Press Meas > Normalize > Store Ref (1 → 4) > Normalize (On)

- 7 Reconnect the DUT to the analyzer. Note that the units of the reference level have changed to dB, indicating that this is now a relative measurement.
- 8 To change the normalized reference position:

Press Meas > Normalize > Norm Ref Posn > 8

9 Place the reference marker at the specified cutoff frequency:

Press Marker > Mode > Delta Pair (Ref) > 370 > MHz

10 Place the second marker at 37 MHz:

Press Delta Pair (Delta) > 37 > MHz

11 In this example, the attenuation over this frequency range is -17.98 dB/octave (one octave above the cutoff frequency).

Functions and Measurements

Measuring Stop Band Attenuation of a Lowpass Filter

12 Use the front-panel knob to place the marker at the highest peak in the stop band to determine the minimum stop band attenuation. In this example, the peak occurs with Delta of 563 MHz. The attenuation is -60.93 dB. See Figure 3-21.



Figure 3-21 Minimum Stop Band Attenuation
Channel Scanner

The channel scanner - option SCN is a tool for coverage test, band clearance, and spectrum monitoring. It measures the channel power of multiple transmitted channels. The power is displayed via either the graphic bar chart or time bar chart. It allows you to set maximum 20 channels for your test. You can continuously log the scanned channel data as CSV file for post processing on your PC.

Top/Bottom N Channel Scanner

Top/Bottom N channel scan is used for searching the top/bottom channels from specified channel range according channel power.

Unit:d	lBm	Ref:-1	00.00		0.00
Att 20.00	10	FREQ (Hz)	BW (Hz)	CHP (dBm)	
ab	6	65.000M	10.000M	-3.080	
	14	135.000M	10.000M	-4.359	
	7	75.000M	10.000M	-12.715	
LgAv	13	125.000H	10.000M	-13.701	
-	8	85.000M	10.000M	-23.046	
W	12	115.000H	10.000M	-23.563	
С	10	100.000H	10.000M	-28.541	
	11	105.000H	10.000M	-30.110	
	9	95.000M	10.000M	-30.476	
	20	200.000H	10.000M	-46.668	
	19	190.000H	10.000M	-48.936	
	1	10.000M	10.000M	-49.005	
	17	170.000H	10.000M	-49.114	
	15	150.000H	10.000M	-49.154	
	16	160.000M	10.000M	-49.292	
	18	180.000M	10.000M	-49.471	
	5	50.000M	10.000M	-49.943	
	4	40.000M	10.000M	-50.234	
	3	30.000M	10.000M	-50.267	
	2	20.000M	10.000M	-50.432	
Index	6				

Figure 3-22 Top N Channel Scanner Measurement

Please refer to the procedures below to perform a Top N channel scanner measurement.

- 1 Connect the antenna to RF IN connector.
- 2 Turn on the channel scanner function.

Press Meas > Channel Scanner

- 3 Press Meas > Scan Mode > Top N to set the scan mode to TOP N channel mode. Input the channel number you need to monitoring. Press Enter as a terminator.
- 4 Press **Range Edit** to access the submenu to edit the scan range.

Functions and Measurements Channel Scanner

Toggle **Edit Method** to underline **Std**. It allows you to set the range according to the embedded communication standard, such as CDMA and GSM which is used specifically in different countries. Press **Signal Std** to select the standard. Press **Recall** as a terminator. Press **Begin Chn** and **End Chn** to set the begin and end channel for scanning. Press **Apply** to apply all the range settings.

If you toggle **Edit Method** to underline **Custom**, it allows you to set the customer-defined scan as your need.

Press **Start Freq** to set the scan start frequency.

Press **Freq Step Size** to set the frequency interval for adjacent channels.

Press **Bandwidth** to set the bandwidth of each frequency channel which is used to calculate the channel power.

Press **Number of Chn** to set the number of frequency channels which will be scanned.

Press **Apply** as a terminator to apply all the settings above.

- 5 Press **Scan Start** to initiate the channel scan function.
- 6 Press **Logging Start** to start recording the scan process which includes the channel power and related channel bandwidth value to a CSV file. Press **Logging Stop** to end the logging. The CSV file will be saved immediately.

List N Channel Scanner

The List N channel scan is used for listing the frequency channels from specific channel standard or customized frequency bandwidth.

Please refer to the procedures below to perform a List N channel scanner measurement.

- 1 Connect the antenna to RF IN connector.
- 2 Turn on the channel scanner function.

Press Meas > Channel Scanner}

- 3 Press Meas > Scan Mode > List to set the scan mode to List N channel mode. Input the channel number you need to monitoring. Press Enter as a terminator.
- 4 Press **List Edit** to access the submenu to edit the scan range. Press **Insert** to insert a channel and access the channel setting submenu to customize the channel parameters.

Press **Edit Method Std**. It allows you to set the range according to the embedded communication standard, such as CDMA and GSM which is used specifically in different countries. Press **Signal Std** to load a standard file as your need. Please refer to "Loading a File" on page 100 for details. Press **Chn ID** to select the specific channel according to the signal standard

Or press **Edit Method Custom**. It allows you to set the customer-defined scan as your need.

Press **Freq** to set the center frequency of the current channel.

Press **Bandwidth** to set the bandwidth of each frequency channel which is used to calculate the channel power.

The first channel editing is completed. Press **Return > Insert** to add more channels as your need.

If there is a need to further edit the channel set previously, press **Index**, rotate the knob to highlight the channel as your need for further editing.

Press **Apply** as a terminator to apply all the settings above.

5 Press **Scan Start** to initiate the channel scan function.

NOTE

6 Press **Logging Start** to start recording the scan process which includes the channel power and related channel bandwidth value to a CSV file. Press **Logging Stop** to end the logging. The CSV file will be saved immediately.

Please make sure the file catalog is set to INT or USB unless the logging file can not be saved successfully. When the logging file exceeds the maximum volume of the storage catalog, the logging will automatically pause and the file will be saved immediately.

Display

In channel scanner mode, the **[Disp]** hardkey is used to adjust the channel scanner display to review the customized scan result.

Press **{Freeze}** to pause the display refresh but the scan is still running.

You can sort the channel by ID or power, in ascending or descending order. Or you can press **{Disp Mode}** to toggle the display mode between bar mode and time mode.

Att FREQ BAND CHP	111111
50.00 No (MHz) (MHZ) (dBm) 5.62	10.34
GD 0fst 1 934.987 1.250 -75.00	
10 00 2 935.012 1.250 -66.00	
dB 3 935.037 1.250 -64.00	
LgAv 4 935.063 1.250 -75.00	
9999 5 935.087 1.250 -57.00	
₩ <u>6</u> 935.112 1.250 -64.00	
PA C 7 935.137 1.250 -41.00	
Speed 8 935.162 1.250 -38.00	
9 935.188 1.250 -37.00	
10 935.212 1.250 -27.00	
11 935.237 1.250 -38.00	
12 935.262 1.250 -27.00	
13 935.287 1.250 -20.00	
	_

Figure 3-23 Time display mode in List N channel scanner

Channel Scanner Setup

To customized the channel scan process, you can press **Meas > Channel Scanner > Setup** to set the measurement interval and rule in the submenu.

The **Meas Interval** is a value of time/distance during which the every two scan process is triggered. When it is set to off, the channel will be scanned with default settings.

The **Interval Type** is toggled between time and distance. When it is set to **Time**, the minimum interval time is 100 ms. When it is set to **Distance**, it allows you to measure the channel with the specific distance on the road test. The minimum interval distance is 1 meter.

The Measure Rule and Search Rule is toggled between Speed and Accuracy.

For each scan process, the analyzer will first search and find out the available channels according to the selected scan mode. Then, a precise measurement will perform to get the scan result.

The accuracy mode in measurement rule is set as default to get the precise measurement for the searching-out channels.

The speed mode will speed the measurement but reduce the measurement accuracy. It is set to default in search rule to search out the available channels approximately.

The **Top Cycle** number is the searching times for each measurement. It allows you to measure the specific searching-out channels continuously.

Spectrum Monitor

The scrolling three-dimensional display is noted for its ability to track the frequency and power behavior over the time, particularly intermittent signals. The spectrum monitor is used to analyze the stability of a signal over the time, or to identify intermittent interference signals in communications systems.

The X-axis represents frequency, and amplitude is represented by color; red for a strong signal and blue for noise floor. The Y-axis represents time, with the trace from the newest sweep displayed at the bottom of the screen. Earlier traces move up toward the top with each new sweep. Two coupled markers allow the user to place a marker on any trace in the Spectrum Monitor and view the normal spectrum for the time of that sweep. The time interval between sweeps can be adjusted, and up to 1500 traces can be displayed and saved.





Please refer to the procedures below to perform a spectrum monitor measurement.

- 1 Connect the omni antenna to RF IN connector.
- 2 Set the center frequency and span.

Press Frequency > 1.8052 > GHz

Press SPAN > 5 > MHz

3 Turn on the spectrum monitor function.

Press Meas > Spectrum Monitor.

4 Set the update interval time between two frames.

Press **Update Int. On**, rotating the knob or pressing numeric keypads to set the update interval time.

5 Turn on Marker 1 and Marker 2.

Press Marker 1 > State On, Marker 2 > State On.

- 6 Press **Frequency**, rotate knob to change the frequency of marker as you want.
- 7 Press Meas > File Logging > Start Save to save the spectrogram data. After pressing Stop Save, the spectrogram will be saved into a trace or CSV data file for your future use.

Please refer to "Loading a File" on page 100 to load the saved spectrogram trace file.

Spectrum Monitor Audio Alert

The spectrum monitor provides an audio alert with a frequency dependent on the different control parameters. This alert needs two markers to specify the measure channel. The **Band Power** of the channel specified by two markers is measured without the audio alert. The **Alert Limit** is set to specify the lowest band power that makes the buzzer beep.

Please refer to the procedures below to turn on the audio alert.

- 1 Press Meas > Spectrum Monitor to access into the spectrogram mode.
- 2 Press Marker > More > Audio Alert to enable the audio alert.

Reflection Measurement

Press **MODE > Reflection Measurement** to access the cable and antenna measurement submenu. There are three different measurement modes for your selection:

- Reflection measurement
- One port cable loss
- Distance to fault

Preparation

Before making a measurement in a specific mode, the HSA requires a calibration to make sure the measurement accuracy. A new calibration must be performed if any components used in the calibration setup are changed. For example, a short coaxial cable used to connect the tester to the DUT

Press **Frequency** and **Span** to set the measurement frequency range. It is best to keep the calibration frequency range as close as possible to the actual sweep frequencies necessary for the measurements. Calibrating over a larger frequency range than the actual measurement range will reduce the accuracy of the test results.

Calibrate with a T-combo calibrator

T-combo calibrator This is a T-shaped mechanical calibrator. It consists of a calibrated open, short and 50 Ω load. Using the T-combo calibrator will result in a more accurate calibration than when using the an electronic calibrator.

Using a T-combo calibrator is a three step process requiring the user to manually change the open-short-load components. The default order of the calibration process is open-short-load.

1 Press **Frequency > Calibrate** to bring up the dialog box for calibration instruction. Follow the on-screen instruction to

connect the Open component of the T-combo calibrator to the RF OUT connector of the analyzer. Press **ENTER** to start the open calibration.

- 2 Follow the instruction to connect the short component of the T-combo calibrator to the RF OUT connector of the tester. Press **ENTER** to start the short calibration.
- Connect the Load component of the T-combo calibrator to the RF OUT connector.
 Press ENTER to start the load calibration.

A **Calibrated** indicator is shown on the upper left corner of the screen when the calibration is completed. Then, the analyzer is ready for your further cable measurement.

Measuring Cable Reflection

Press **Mode > Reflection Measurement > Reflection Measurement** to select the Reflection Measurement Mode. It allows you to set the Y axis of the graticule as return loss, VSWR or reflection coefficient value.

Measuring Distance to Fault

For this measurement, an internally generated signal emits from the RF OUT port of the tester and is transmitted to the cable and antenna system (DUT). The tester receives and processes the signal power reflected from faults and imperfections. In performing a DTF measurement, the tester uses frequency domain reflectometry. The transmitted and reflected signals contain information about the distance to the faults. This information is used to determine the physical distance to the faults. The tester displays the physical distance to the probable faults, corrected for cable loss and the velocity propagation factor of the cable. Functions and Measurements Reflection Measurement

Perform a DTF measurement

To make a DTF-return loss measurement over a frequency range of 50 to 400 MHz, perform the following steps:

- 1 Press the **MODE > Reflection Measurement > Distance To Fault** to select the DTF mode.
- 2 Press FREQ > Start > 50 > MHz to set the start frequency to 50 MHz.
- 3 Press **Stop > 400 > MHz** to set the stop frequency to 400 MHz.
- 4 Press **Calibrate** to bring up the calibration process guidance. Follow the instructions to perform a calibration. For more information about calibration, refer to "**Preparation**" on page 72.
- 5 Remove the calibrator and connect the cable under test (DUT) to the RF OUT connector on the top panel of the tester.

The DTF measurement starts and the results are displayed on the screen. A peak in the horizontal trace indicates a defective location.

Making a Power Measurement with USB Power Sensor

The N932xC spectrum analyzer supports the U2000 and U2020 series USB power sensors.

The U2000 series USB power sensors do not need manual calibration and zero routines performed. Calibration and zeroing are performed without removing the power sensor from the source, through internal zeroing. With internal zeroing of U2000 series USB power sensors, there is no need to disconnect the sensor or power-off the DUT. The U2000 series do not require 50 MHz reference signal calibration, allowing the factory calibration to ensure measurement accuracy. For best accuracy, users are recommended to perform external zeroing for input signals below -30 dBm for best accuracy.

CAUTION The maximum power for the RF IN port and the RF OUT port of the analyzer is +30 dBm (1 W). The maximum power for the U2000 Series Power Sensor port is +25 dBm (316 mW). When directly coupled to a base station, the test set can be damaged by excessive power applied to any of these three ports.

To prevent damage in most situations when directly connect an analyzer to a base station, use a high power attenuator between the analyzer and the BTS.

NOTE If you suspect other signals may be present, it is recommended that you turn off all the other channels and measure average power only on the signal of interest. Another option is to measure channel power (which is less accurate), that filters out all other channels (signals).

Making an Average Power Measurement

The average power measurements provide a key metric in transmitter performance.

Base station transmit power must be set accurately to achieve optimal coverage in wireless networks. If the transmit power is set too high due to inaccurate power measurements, undesired interference can occur. If the transmit power is set too low, coverage gaps or holes may occur. Either case affects system capacity and may translate into decreased revenue for service providers. Average power can be measured for the channel of interest while the base station is active. All other channels should be inactive. Average power is a broadband measurement. If other signals are present the analyzer will also measure their power contributions.



Figure 3-25Connection with base station

To make an average power measurement, you connect the power sensor and cable, zero and calibrate the meter, before making a measurement. Zeroing of the power meter will occur automatically:

- Every time you use the Power Meter.
- When a 5 degree C. change in temperature occurs.
- Whenever you change the power sensor.
- Every 24 hours.
- Before measuring low level signals—for example, 10 dB above the lowest specified power for your power sensor.

Functions and Measurements

Making a Power Measurement with USB Power Sensor

Calibrating the power meter every time you cycle the power on and off.

In most situations, you can press **Zero** to complete the two steps (zero and cal) together.

Follow the steps below to make a basic average power measurement.

- 1 Press Preset. (With Preset Type of DFT)
- 2 Press Mode > Power Meter to access the power meter mode.
- **3** Zero and calibrate the meter. Press **Zero** to make a Zero operation of the power sensor followed by a calibration operation.
- **4** Connect the power sensor to the USB port of N932xC. The analyzer will recognize the power sensor automatically.

CAUTION To prevent damage to your sensor, do not exceed the power levels below. U2000/1/2A +25 dBm (320 mW) average, 20 VDC

+33 dBm (2 W) peak, <10 ms

For more information on the maximum power of U2000 series power sensors, please refer to the *Operating and Service Guide* of Keysight U2000 Series USB Power Sensors.

- **5** Connect the external attenuation, if required, with the power sensor used.
- 6 Connect the analyzer to the base station. Connect the power sensor to the signal to be measured. A typical BTS connection is after the output of the power amplifier and duplexer. The connection requires a cable and two Type-N barrel connectors, in addition to the power sensor and external attenuator.
- 7 Press Meas Setup > Disp Range to set the display range of the measurement. when it is set to **On**, the display range will be adjusted automatically according to the signal power dynamic range. When it is set to Off, press **Top** and **Bottom** to set the display range manually.

Making a Power Measurement with USB Power Sensor

- 8 Press **General Setup > Freq** to set the power frequency for the DUT. The current frequency will display in the bottom line.
- 9 Press Power Range > Auto Power to toggles the measurement range between On and Off. When it is set to On, the power range will be adjusted automatically. Use auto range when you are not sure of the power level you are about to measure. When it is set to Off, press Range to select the upper range or lower range. The lower range uses the more sensitive path and the upper range uses the attenuated path.

Sensor	Lower range	Upper range
U2000/1/2/4A	-60 dBm to -7 dBm	-7 dBm to +20 dBm
U2000/1/2H	-50 dBm to +3 dBm	+3 dBm to +30 dBm
U2000/1B	-30 dBm to +23 dBm	+23 dBm to +44 dBm

Table 1Power Sensor Range

10 Press Meas > Meas Seup > Disp Mode to set the display in meter. chart or trace display. the measurement result will displays on the screen as shown.



Figure 3-26 Power Measurement

Making a Peak Power Measurement

The Keysight U2020 X-series USB peak and average power sensors enable peak power measurements that have the same accuracy as measurements obtained using traditional peak power meters, while providing the advantages of being a very compact and portable form factor.

Follow the steps below to make a peak power measurement.

- 1 Press **Mode > Power Meter** to access the power meter mode.
- 2 Connect the power sensor to the USB port of N932xC. The sensor will automatically initialize, perform zeroing (While remaining connect to the device under test), and calibrate without connecting to an external source.

NOTE You can manually perform zeroing and calibration by perssing **Zeroing** > **Zeroing** and **Calibration** at any time after the sensor is connected and initialized.

3 Press **General Setup > Freq** to set the frequency of the signal under test.

As a wideband device, the power sensor has a frequency response. The power sensor utilizes a complex correction algorithm to remove power measurement error due to linearity error, frequency response, and temperature drift to generate a more accurate measurement.

Functions and Measurements Making a Power Measurement with USB Power Sensor

The analyzer provide the customer preset function with U2020 X-series power sensor. Press **Meas > Preset** and the predefined protocol list will pop up. Select the wanted item and press **Preset** as a terminator. The related settings will be set automatically.



Figure 3-27 Customized Preset the U2020 Power Sensor

4 Press Meas Disp > Disp Mode > Trace to find the measurement results as Figure 3-28 below.



Figure 3-28 Peak Power Measurement

Power Meter Settings

Please find the sections below to find the general power meter measurement settings.

Setting the Power Meter Top and Bottom End-Points

Setting the end points (Disk Range) close to expected measurement value changes the sensitivity of the Power Meter scale resolution. This is an advantage in viewing small changes in power. However, this will not affect the overall range of the sensor. This is only available for Meter and Chart display mode. For Trace display, please press **Meas > Peak Setup > Trace Setup** to set the X and Y scale.

- 1 Press Meas > Meas Disp > Dis Range to access the end-points menu.
- 2 Press **Top** and enter the maximum scale value using the numeric keypad. Then press **dBm** to complete the setup.
- **3** Press **Bottom** and enter the minimum scale value desired using the numeric keypad. Then press **dBm** to complete the setup.

Setting Power Meter Resolution

There are four levels of power meter resolution. Higher resolutions provide more accuracy but slow the measurement speed. The resolution is only available for U2000 series power meter and free-run trigger mode in U2020 series power meter.

Press **Meas > Meas Disp > Resolution**. Select 1,2,3 or 4. The four options represent different resolution as follow:

- [1] = 1
- · [2] = 0.1
- [3] = 0.01
- [4] = 0.001

Functions and Measurements Making a Power Measurement with USB Power Sensor

Set the Step Detection

Press **Meas > General Setup > Average > Step Detect** to set the step Detect On and Off. When it is set to on, the filter will re-initialize upon detection of a step increase or decrease in the measured power to reduce the filter settling time after a significant step in the measured power, Step detection can be set in both manual and automatic filter modes.

Set the Measurement Gate

Press **Meas > Peak Setup > Gate Setup** to set the start time and gate length for a measurement gate. A measurement gate allows measurements to be performed on particular sections of the input signal. The gate is defined by a start time relative to the trigger instant and a duration. Signal samples acquired during the time interval specified by the gate are used for the measurements in that gate. A system of up to four independent gates is provided.

Set the Trigger

Press **Meas > Peak Setup > Trig/Acq** to set the trigger parameters listed below for the measurement gate.

Acqn Set the single, free run or continuous trigger mode. Select to enable trace and auto trigger delay for the single and continuous trigger modes. For the free run mode, only auto trigger delay can be enabled.

Source Set the trigger source to internal channel or an external source.

Mode Enable auto level or manually set the trigger level if the internal trigger source is selected.

Level sets the trigger level manually when the Mode is set to manual.

Delay Set the delay time to be applied between the trigger event and all the gate start times. This allows you to time-shift all the gates by the same amount with one setting change.

Slope Select the positive or negative slope type to determine if the trigger event is recognized on the rising or falling edge of a signal respectively.

Holdoff Set the holdoff time to disable the trigger mechanism after a trigger event occurs.

Hysteresis Set the hysteresis to help generate a more stable trigger by preventing triggering unless the RF power level achieves the trigger level and the additional hysteresis value. It can be applied to both rising and falling edge trigger generation.

Hysteresis is only available for the internal trigger source and manual trigger level.

Demodulate the AM/FM signal

The N932xC spectrum analyzer provides the AM/FM demodulation function for the AM/FM signal demodulation.

Demodulating an AM Signal

The demodulation function allows you to demodulate and hear signal information displayed on the analyzer.

Simply place a marker on a signal of interest, set the analyzer in zero span, activate AM demodulation, turn the speaker on, and then listen.

- 1 Press Preset. (With Preset Type of DFT)
- 2 Connect an antenna to the RF IN connector.
- 3 Select a frequency range on the analyzer. For example, the frequency range for AM broadcasts in the United States is 550 to 1650 kHz:

Press Frequency > Start Freq > 550 > kHz > Stop Freq > 1650> kHz.

4 Place a marker on the signal of interest:

Press Peak Search > Next Right Pk or Next Left Pk

5 Set the frequency of interest to center frequency:

Press Marker > Marker To > To Center.

6 Change the resolution bandwidth to 100 kHz:

Press BW > 100 > kHz.

- 7 Press Span > Zero Span
- 8 Press Sweep > Sweep Time > 10 s to set the sweep time.
- 8 Set the detector type and turn on AM demodulation:

Press Trace/Det > Detector > Sample.

Press Marker > Function > Demod

Press Demod Setting > Demod Type AM

Demodulating an FM Signal

This section demonstrates how to demodulate and listen to an FM signal using the built-in FM demodulator.

Using the built in FM demodulator you can tune to an FM signal and view the results of the detector output as displayed in the time-domain.

- 1 Press Preset. (With Preset Type of DFT)
- 2 Use a signal source or connect an antenna to recieve FM signal. In this example the signal is modulated at 300 MHz with FM deviation of 10 kHz and FM rate of 1 kHz.

NOTE If you are using a broadcast FM signal, the FM channels are broadcasting between 87.7 MHz to 107.7 MHz.

3 Set the center frequency to the center of the FM signal (in this case 300 MHz):

Press Frequency > 300 > MHz.

4 Set the analyzer to zero span for time-domain analysis:

Press Span > Zero Span.

Press Sweep > Sweep Time > 5 > s.

5 Set the resolution bandwidth to capture the full bandwidth of the FM signal.

Press BW > 100 > kHz.

6 Turn on the optional pre-amplifier to detect small signals:

Press Amplitude > Preamp On.

7 Turn on the FM demodulator:

Press Marker > Function > Demod

Press Demod Setting > Demod Type FM

Functions and Measurements Demodulate the AM/FM signal

8 Listen to the FM signal:

Press **Demod Setting > Speaker Vol**, rotate the knob to adjust the speaker volume.

The headphone jack is available for the audio signal output alternatively.

Analysis the Modulated Signals

The N932xC spectrum analyzer provides the optional AM/FM (Option AMA) and ASK/FSK (Option-DMA) modulation analysis function for analysis the modulated signals. These functions can be activated by license keys.

AM/FM Modulation Analysis

Optional AM/FM demodulation analysis provides modulation metrics, including carrier power, modulation rate, AM depth/FM deviation, SINAD and carrier frequency offset. User definable limits provide Pass/Fail indicators of four types:

Maximum carrier power, Maximum AM modulation index or FM deviation, Minimum AM modulation index or FM deviation, and Minimum carrier frequency offset.

This mode allows you saving the waveforms with metrics for reporting as well as the set-up parameters for future measurements or analysis. In the following example, you can use any source available (such as AM/FM radio) as long as it has AM/FM signal generation capability.

AM Modulation Analysis

Please refer to the procedures below for the AM modulation analysis:

- 1 Connect the signal generator to RF IN connector and turn on the signal generator's AM and RF output.
- 2 Turn on the AM demodulation analysis function.

Press MODE > Modulation Analysis > AM.

- 3 Press Frequency > Carrier Freq > 100 > MHz to set the carrier frequency.
- 4 Set the attenuation state to Auto (default):

Press Amplitude > Attenuation Auto

5 Press Shift > Disp > Y Scale > Scale Coupling On to set the Y scale auto coupling.

Functions and Measurements Analysis the Modulated Signals

6 Set the AM depth limit and turn on the limit function:

Press Shift > Limit > AM Depth UP > 51 > % > AM Depth Low > 49 > % > Limits on

The red value in the result indicates the demodulated AM depth exceeds the limits set as above.



Figure 3-29 AM demodulation analysis

FM Modulation Analysis

Please refer to the procedures below for the FM modulation analysis:

- 1 Connect the signal generator to RF IN connector and turn on the signal generator's FM and RF output.
- 2 Turn on the FM demodulation analysis function.

Press MODE > Modulation Analysis > AM.

- 3 Press Frequency > Carrier Freq > 100 > MHz to set the carrier frequency.
- 4 Set the attenuation state to Auto (default):

Press Amplitude > Attenuation Auto

5 Press Shift > Disp > Y Scale > Scale Coupling On to set the Y scale auto coupling.

6 Set the FM deviation limit and turn on the limit function:

$\mathsf{Press}\$ Shift > Limits > FreqDev UP > 11 > % > FreqDev Low > 9.9 > % > Limits on

The red value in the result indicates the demodulated FM deviation exceeds the limits set as above.

FM	Att:8 dB	CarrFreq:100	.000000 MHz
10. 27 kHz			
0.000	lime (ms	5/	10.000
Carrier Power: Modulation Rate: Frequency Deviation	Current -10.95 dBm 1.00 kHz :9.96 kHz	MAX -10.90 dBm 1.00 kHz 9.99 kHz	MIN -10.97 dBm 999.95 Hz 9.95 kHz
SINAD: Carr Freq Offset:	38.61 dB -100.73 Hz	39.64 dB -80.61 Hz	37.57 dB -101.47 Hz

Figure 3-30 FM modulation analysis

ASK/FSK Modulation Analysis

The ASK/FSK modulation analysis function supports four display modes:

- Symbol
- Waveform
- ASK/FSK Error
- Eye Diagram.

User definable limits provide Pass/Fail indicators of four types:

- Maximum carrier power
- Maximum ASK modulation depth/FSK frequency deviation
- Minimum ASK modulation depth/FSK frequency deviation
- Maximum carrier frequency offset.

The metrics includes carrier power, ASK/FSK error, ASK depth/FSK frequency deviation, and ASK index etc. The waveform with metrics and setup parameters can be saved for reports and future Measurements.

In the following example, you can use any source available (such as your remote key of the car) as long as it has ASK/FSK generation capability. For ASK/FSK signal, its Filter is Nyquist and Alpha is 0.35.

ASK Modulation Analysis

Please refer to the procedures below to analysis the ASK modulation.

- 1 Connect the signal generator to RF IN connector and turn on the signal generator's ASK modulation and RF output.
- 2 Turn on the ASK demodulation analysis function.

Press MODE > Modulation Analysis > ASK.

- 3 Press Frequency > Carrier Freq > 100 > MHz to set the carrier frequency.
- 4 Press Meas > Symbol Rate > 10 > MHz to set the symbol rate.
- 5 Press Filter Setup > Ref Filter > Nyquist to set the filter type.
- 6 Set the attenuation state to Auto (default):

Press Amplitude > Attenuation Auto

- 7 Press Shift > Disp > Y Scale > Scale Coupling On to set the Y scale auto coupling.
- 8 Setting the ASK depth limit and turn on the limit function:

 Press Shift > Limits > ASK Depth UP > 71 > % > ASK Depth Low > 70 > % > Limits on

9 Press Shift > Disp > Display > Eye Diagram to view the eye diagram.



Figure 3-31 ASK Eye Diagram

FSK Modulation Analysis

Please refer to the procedures below to analysis the FSK modulation.

- 1 Connect the signal generator to RF IN connector and turn on the signal generator's FSK modulation and RF output.
- 2 Turn on the ASK demodulation analysis function.

Press MODE > Modulation Analysis > FSK.

Functions and Measurements Analysis the Modulated Signals

- 3 Press Frequency > Carrier Freq > 100 > MHz to set the carrier frequency.
- 4 Press Meas > Symbol Rate > 10 > ksps to set the symbol rate.
- 5 Press Filter Setup > Ref Filter > Nyquist to set the filter type.
- 6 Set the attenuation state to Auto (default):

Press Amplitude > Attenuation Auto

7 Setting the FSK deviation limit and turn on the limit:

Press Shift > Limit > FreqDev UP > 85 > kHz > FreqDev Low > 80 > kHz > Limits on

The figure below shows the FSK symbol and the measurement result.

Figure 3-32 FSK Symbol View

FSK	Att:0 dB	CarrFreq:100	0.000000 MHz
			SYMB
1: 0010101001	1100110001 (0001001101 11110111	01 1001000001
51: 1001110010	0000110001 1	1011111001 10001111	11 0011000110
101: 1111000100	1101111100 1	1110010100 00011000	11 1111011101
151: 0001111100	0101110000 (0010000001 00000100	01 0111101011
201: 1100111000	0011101101 1	011111000 00010101	00 1011000000
251: 1010100111	1010100101 (0100110101 10101111	10 0110001111
301: 1111010001	1011110001 1	1101000011 00111001	10 1000011011
351: 0111111001	0011010001 (0110100100 00001000	00 0111011011
	Current	#AX	11 I N
Carrier Power:	-13.09 dB	m −13.09 dBm	-13.11 dBm
Deviation:	40.01 kHz	40.01 kHz	39.99 kHz
FSK Error:	1.19 %	1.22 %	1.13 %
Mag Error:	0.59 %	0.81 %	0.59 %
Carr Freq Offset:	-78.78 Hz	-78.78 Hz	-149.47 Hz

Measuring Channel Power

Channel Power measures the power and power spectral density in the specified channel bandwidth. A white frame on the display indicates the edge limits of the channel bandwidth. The user must specify the center frequency, reference level, and channel bandwidth to be used for the measurement.

The power calculation method used to determine the channel power is a traditional method known as the integration bandwidth (IBW) method. A swept spectrum is used as the basis for this calculation. Therefore, it is important to set the resolution bandwidth correctly before making this measurement using the following formula:

$$RBW = \frac{(k(span))}{n}$$

Please refer to the procedures below to set a channel power measurement.

- 1 Press Meas > Channel Power to select the channel power measurement mode
- 2 Press Standard Customize to choose the radio standard.
- **3** There are four wireless standard options: WCDMA, CDMA, LTE, GSM. Press **WCDMA** as an example.

Once the standard is set, the integration bandwidth and span will be automatically set according to the standard.

4 Press Center Freq to change the center frequency of the current signal channel. Adjust the center frequency to measure other channel power in the same standard.



Please follow the similar procedure as above to measure the channel power in the CDMA and LTE standard.

To measure the channel power in GSM standard, the default setting is 10 MHz span, 300 kHz RBW, and the continuous peak search is enabled. The instrument will measure the channel power after the center frequency is changed.

Perform an EMC Measurement

Please refer to the procedures below to perform an EMC measurement (Option EMC required). This procedure contains the primary four parts as below:

- · Scan in CISPR band with CISPR RBW and peak detector
- Load a CISPR limit with pass/fail test
- Use peak search to locate the out-of-limit points
- Measure with quasi-peak detector in zero span
- 1 Press Preset (With Preset Type of DFT)
- 2 Press [Freq] > {Start Freq} > [30] > {MHz} to set the start frequency at 30 MHz
- 3 Press [Freq] > {Stop Freq} > [1] > {GHz} to set the stop frequency at 1 GHz
- 4 Press [Amplitude] > {Y axis unit} > {dBuV} to set the Y axis unit to dBuV
- 5 Press {Attenuation} > [10] > {dB} to set the attenuation to 10 dB
- 6 Press [BW] > {File type} > [120 kHz CISPR} to set the analyzer with CISPR RBW
- 7 Press {VBW} > [1] > {MHz} to set the VBW wider than CISPR RBW

NOTE After these steps, you can save the instrument status to a *.STA file, and store it in directory: /USER/STATE. Then it will be shown as one of the softkey under **[User]** hardkey, which provides one-button access from the front panel.

8 Press [Trace/Det] > {Detector} > {Pos Peak} to set the positive peak detector.

9 Press [Shift] > [Limit/Sweep] > {Limit 1} > {Recall Limit} to load a CISPR limit line from memory.

You can edit a limit line file by pressing [Shift] > {Limit} > {Limit 1} > {Edit limit}, or in HSA and BSA PC software by clicking {File} > {New} > {Limit}

10 Toggle {Limit On/Off} to On to set the positive peak detector.



- **11** Press **[Peak Search]** to place a marker on the signal which is out of limit.
- 12 Press [Marker] > {Marker To} > {To Center}
- 13 Press [Span] > {Zero Span}
- 14 Press [Trace/Det] > {Detector} > {Quasi peak} to set the quasi peak detector.
- 15 Press [Marker] > {Marker To} > {To Center}



Files Operation

The analyzer will store and retrieve data files similar to using a PC. The analyzer allows you to view and save files in the internal storage of the analyzer or to a USB storage device. This section provides information on how to locate catalogs (file types) and to save files.

Locating and Viewing Files in the Catalog

The analyzer has four types of files:

- **State** records the current controls and settings of the analyzer. Use this file type for saving test parameters for future recall, such as frequency and BW settings. (file extension: .STA).
- **Trace** stores trace information (file extension: .TRA).
- **Setup** records the system setting information, such as language, date/time, and power saving mode. This file type is not used for test parameter setup information. (file extension: .SET).
- **Screen** stores screen captures of the display (file extension: .JPG).
- **Limits** which stores data sets to determine whether a trace has exceeded preset specifications (file extension: .LIM)
 - **CSV** records the trace data and available for review on PC. (file extension: .CSV)
- **Task Planner** contains the user-defined measurement tasks in sequence which make the test task easier in field test. (file extension: .TPF).
 - **Correction** The amplitude correction file is used for trace amplitude offset compensation. Please refer to "Corrections" on page 106 to edit and save the correction file on BSA PC software. (file extension: .TPF).
 - **Standard** contains the frequency range and corresponding parameters for a specific communication standard. It allows you to recall those default settings for the singal searching and testing in that range. (file extension: .STD).

Saving a File

The analyzer allows you to save files (states, traces, limits or screens) to a USB storage device (**USB**/), or internal storage (**INT**/). The following is an example of how to save a trace to internal storage (**INT**/).

1 Select the save destination for the file. This example will select the internal storage (**INT**/):

Press File > Directory > Memory Type INT

- 2 Press **Return > Save as**, the pop-up window displays for your further setting.
- **3** Edit a file name.

A file name can consist of letters and digits. A single key stroke on the numerical keypad inputs a digital number; and consecutive key stroke selects and inputs a letter.

- 4 Rotate the knob to choose the file type you need.
- 5 Press **Enter** to save the file. The file will be saved immediately and "**File saved**" will be shown in the status bar.

CAUTION When saving a file to a USB storage device, do not disconnect the USB device during the save operation. To do so may cause unexpected data loss.

Quick Saving a File

Press **[Save]** to quickly save a trace or a screen to either the local memory or an external USB device, depending upon the setup of the save path.

Refer to the steps for saving a trace/screen:

- 1 Press File > Setup > Qsave Type to set the quick save file type.
- 2 Press File > Directory > Media Type to select the file directory.
- 3 Press **Return** > **Save** to save a trace or a screen copy to the pre-defined memory. The trace or screen will be automatically assigned with a default file name. A trace will be assigned with a file name, such as *HYTRACE*, *HYTRACE*_1, and consecutive

decimal numbers appended to the alphabetic file name, such as *HYSCREEN*, *HYSCREEN_1* and consecutive decimal numbers appended to the alphabetic file name.

Saving a User State

The analyzer allows you to recall the frequently used state file with **User** hardkey. Please follow the steps below to create the user menu.

- **1** Follow the file saving procedure above to save a state file in internal memory.
- 2 Rotate the knob to highlight the saved file.
- 3 Press Files Operation > Copy to
- 4 Rotate the knob to highlight the folder named *USER*. Press **Browse Folder** to access into this folder.
- 5 Rotate the knob to highlight the folder named *State*. Press **Browse Folder** to access into this folder.
- 6 Press **Copy** to copy the file into the *User/State* folder.

The state file is available for your quick recall by pressing **User**.

Loading a File

This feature will recall (load) onto the displayed screen a previously saved filename and type compatible with this analyzer. The file types are described above.

- 1 Press File > Directory > {Memory Type} to select a directory.
- 2 Rotate the knob to highlight a file.
- **3** Press **Recall** to recall this file.

The wanted file will be loaded immediately.

Loading a Task Planner File

Please refer to the following procedures to load a task planner file.

- 1 Press **Mode > Task Planner** or **File > View FileType > TPF** to view the task planner file list.
- 2 Rotate the knob to highlight the task planner file which you need.
- **3** Press **Recall** to load the task planner file. The measurement task will list in sequence.
- 4 Press **Run** to initiate the measurement in sequence.

NOTE The task planner file is created by the BSA PC software. For the task planner saving and editing, please refer to the software online help for details.

For the automatic task, all the measurement tasks are executed automatically without interruption. For the manual task, the program is paused and releases a result report when each measurement is finished. The program will be continued once you input the next instruction.

For the manual-if-failed task, the measurement tasks are executed continuously unless there is a failed result.
Copying a File

To copy a file from internal storage to a USB storage device, follow this procedure:

- 1 Connect a USB storage device to the USB connector.
- 2 Press File > Directory > Memory Type to select the path to INT.
- **3** Select the type of file. Assume you need to copy a trace file:

Press Return > View FileType > Trace

- 4 Using the knob or arrow keys to highlight the file name you need.
- 5 Press File Operation > Copy To to access the copy submenu. Chose the location for copy destination, then press Copy to copy the file immediately.

Deleting a File

Perform the following process to delete a specific file. Note that once a file is deleted from local memory, it cannot be recovered.

- 1 Press File > Directory > Memory Type to select the path
- **2** Using the knob or arrow keys to highlight the file name you want to load.
- 5 Press File Operation > Delete. Press Enter as a terminator and the file will be deleted immediately.

Functions and Measurements Files Operation

4 Key Reference

This chapter describes each front panel hardkey and their associated softkeys (menus). The front panel key descriptions are organized alphabetically. The lower level softkeys are listed as they appear in the softkey menus.



Key Reference Amplitude

Amplitude

Press **Amplitude** hardkey to activate the reference level function and access the amplitude softkey menu. The softkey menu selections are described as follows:

Ref Level Sets the reference level. This function is activated when **Amplitude** is pressed. The reference level is the amplitude power or voltage represented by the top line of the graticule on the display. Setting the reference level changes the absolute amplitude level (in the selected amplitude units) of the top graticule line.

Key access: Amplitude > Ref level

AttenuationToggles the input attenuation between Auto and Man. The
attenuation level can be set in as little as 1 dB increments when
Man is selected. The analyzer input attenuator is normally coupled
to the reference level control, it reduces the power level of the input
signal at the input mixer. Selecting Auto re-couples the attenuator.
Change the attenuation by using the arrow keys, the knob, or the
numeric keypad.

Key access: Amplitude > Attenuation

Preamp (Option P07) Toggles the internal pre-amplifier function between on and off. Pressing Preamp (On) results in a correction being applied to compensate for the gain of the preamp. Amplitude readings then represent the signal value at the input connector. When the preamp is on, a "PA" indication appears on the left side of the display. The preamp operates over a range of 100 kHz to 7 GHz.

Key access: Amplitude > Preamp

Scale/Div Sets the logarithmic units per vertical graticule division on the display. The valid logarithmic units are 1, 2, 5 and 10 dB per division. The Scale/Div function is available only when the Scale Type key is set to Log.

Key access: Amplitude > Scale/Div

Scale Type
Log LinScales the vertical graticule divisions in logarithmic units when Log
is selected. The valid logarithmic units are 1, 2, 5 and 10 dB per
division. When Lin is underlined, the vertical divisions are linearly
scaled with default amplitude units of volts. The top of the
graticule represents the reference-level value; the bottom of the
graticule represents zero volts. (Each division is one-tenth of the
reference level.)

Key access: Amplitude > Scale Type

Y Axis Unit Accesses the softkeys that change the amplitude units (logarithmic or linear). Change the amplitude units by pressing dBm, dBmV, dBuV, dBuA, Watts, Volts, and Amps.
 Key access: Amplitude > Y Axis Unit

Hi-Sensitivity Set this softkey to **On** to set 0 dB attenuation, -50 dBm reference level and turn the preamplifier on. It's very helpful to observe the low-level signals with this settings.

Key access: Amplitude > More > Hi-Sensitivity

Ref Offset Adds an offset value which ranges from -327.6 dB to +327.6 dB, to the displayed reference level. Reference-level offsets are only entered by using the numeric keypad. Entering an offset does not affect the trace or the attenuation value. Reference-level offsets are used when gain or loss occurs between a device under test and the analyzer input. Thus, the signal level measured by the analyzer may be referred to as the level at the input of an external amplitude-conversion device. When an amplitude offset is entered, its value appears on the left side of the display under Offset (as opposed to frequency offsets which appear at the bottom of the display). To eliminate an offset, press **Ref Offset > 0 > dB**.

Key access: Amplitude > More > Rel Offset

- **Corrections** Accesses the corrections submenu to enable the corrections function for amplitude compensation. The amplitude correction is used to compensate the gain/attenuation from antenna/cable. Please refer to the procedures below to use the amplitude correction function.
 - 1 Please refer to the procedures below to create a correction file in BSA PC software.
 - a Open the PC software.
 - b Press File > New > Correction to access the correction file editing pop-up menu.
 - c Refer to the figure below to add the point data with frequency and amplitude offset value.

Figure 4 Editing correction file in PC software

	Frequen	icy(Hz)	Amplitude(dB)
1	500,000,000.00		0
2	600,000,000.00		-2
3	700,000,000.00		-5
4	800,000,000.00		-8
5	900,000,000.00		-5
6	1,000,000,000.00		-2
* 7	1,100,000,000.00		0
	Freque	ency(Hz): 1100000	0000
	Freque	ency(Hz): 1100000 ude(dB): 0	Cancel

d When the editing is completed, press **Save/Save As** to save the correction file.

2	Set a folder named N932xDATA in a USB disk and put the saved
	correction file in. Insert the USB disk on top panel for further
	loading.

- 3 Press Amplitude > More > Corrections to access the correction function.
- 4 Press Cable/Antenna/Other/User to select the correction type.
- 5 Press Recall to load this correction fie. The correction file name will be shown on the Correction1 softkey and the **Apply Corrections** is set to On automatically which indicates the amplitude compensation has been applied to the displayed trace.

Press **Apply Corrections off** to turn off all the corrections.

Set **Antenna Unit** to **On** to switch to graticule unit from dBm to dBmV/m for field strength measurement.

Key access: Amplitude > More > Correction

ImpedanceToggles the computational input impedance between 50ohm and
75ohm. This is only software function in which sets the input
impedance for unit conversions. This set affects the results when
the y axis unit is voltage or current units (dBmV, dBμV, dBμA, V, A)
but does not affect the results when it is power units (dBm, W). The
selected impedance is for computational purposes only, since the
actual impedance is set by internal hardware to 50 ohm.

Key access: Amplitude > More > Impedance

PSD Function On Off Press this softkey to turn on the power spectral density function. When it is set to On, the measurement result and amplitude parameters will be shown in power spectral density. The PSD function can only be enabled in Spectrum Analysis and Spectrum Monitor mode.

Key access: Amplitude > More > PSD Function

Key Reference BW

BW

This hardkey activates the resolution bandwidth function and accesses the softkey menus that control the bandwidth and averaging functions.

Res BW controls the 3 dB resolution bandwidth of the analyzer from 10 Hz to 3 MHz using the knob or arrow keys. There are four available bandwidths less than 1 kHz are 10, 30, 100 Hz or 300 Hz. If an invalid bandwidth is entered using the numeric keypad, the analyzer chooses the closest acceptable bandwidth. As the resolution bandwidth is decreased, the sweep time is modified in order to maintain amplitude accuracy. Resolution bandwidth is also coordinated with the frequency span. As the span is decreased, the resolution bandwidth decreases. When the VBW/RBW is set to **AUTO**, if the resolution bandwidth changes, the video bandwidth changes to maintain the VBW/RBW ratio.

A "#" mark appears next to "**Res BW**" on the display when it is not coupled. To recouple the resolution bandwidth, press **Res BW** (Auto).

Key access: **BW > RBW**

Video BWchanges the analyzer post-detection filter from 1 Hz to 3 MHzAuto Manusing the knob or arrow keys. If an invalid bandwidth is entered,
the analyzer chooses the closest available bandwidth. As the video
bandwidth decreases, the sweep time will increase to maintain
amplitude accuracy.

A "#" mark appears next to "VBW" on the bottom of the analyzer display when it is not coupled. To couple the video bandwidth, press **Video BW (Auto)**.

Key access: **BW > VBW**

VBW/RBW
 Auto Man
 Auto Man
 Sets the ratio between the video and resolution bandwidths. When a signal is weak and is visually masked by the noise floor, set the ratio to less than 1 to lower the noise. When the Preset Type is set to Factory and Preset is pressed, the ratio is set to 1. Change the

ratio by using the arrow keys, knob, or numeric keypad. When **VBW/RBW (Auto)** is selected, the ratio is determined automatically by the rules in Figure 5.

Figure 5VBW/RBW Ratio Auto Rules



Key access: **BW > VBW/RBW**

Average Type Chooses one of the following averaging scales: log power (video), power (RMS), or voltage averaging. When trace average is on, the average type is shown on the left side of the display. Selecting an average type manually causes the analyzer to use that type without regard to other analyzer settings.

Key access: **BW > Average Type**

Key Reference BW

> **Voltage** Selects the logarithmic (decibel) scale for all filtering and averaging processes. This scale is "Video" because it is the most common display and analysis scale for the video signal within a spectrum analyzer. This scale is excellent for finding CW signals near noise. When this type of averaging is selected, LgAv appears on the left side of the display.

> **Power** In this average type, all filtering and averaging processes work on the power (the square of the magnitude) of the signal, instead of its log or envelope voltage. This scale is best for measuring the true time power of complex signals. When this type of averaging is selected, PAvg appears on the left side of the display.

Log Pwr In this Average type, all filtering and averaging processes work on the voltage of the envelope of the signal. This scale is good for observing rise and fall behavior of AM or pulse-modulated signals such as radar and TDMA transmitters. When this type of averaging is selected, VAvg appears on the left side of the display.

There are actually four types of averaging processes within a N932xC. All, except VBW filtering, are affected by this setting. They are listed as follows:

Trace averaging

Averages signal amplitudes on a trace-to-trace basis. (Press **Log Pwr** or **Pwr**)

Average detector

Averages signal amplitudes during the time or frequency interval and represents the result as a single measurement point.

Noise marker

Averages signal amplitudes across measurement points to reduce variations for noisy signals.

VBW filtering

Performs a form of averaging of video signal.

Filter Type When CISPR RBW is selected, the RBW is set to normal RBW as below. The VBW couples with RBW.

EMC RBW	3 dB RBW
200 Hz	100 Hz
9 kHz	10 kHz
120 kHz	100 kHz
1 MHz	1 MHz

When **Filter Type** is set to Normal, Res BW is normally coupled to Span.

Sweep time is coupled to RBW in a non-zero span. If Sweep Time is set to Auto, then the sweep time is changed as the RBW changes, to maintain amplitude calibration.

Video bandwidth (VBW) is normally coupled to RBW. If VBW is set to Auto, then the VBW is changed as the RBW changes.

When 200Hz CISPR filter is selected and Quasi-Peak detector is set to off, the sweep mode is FFT.

If CISPR RBW is selected, the marker counter and gated sweep function are disabled.

Key access: **BW > Filter Type**

Display

Press **Shift > Disp** to control detector and display functions.

Graticule	Press this softkey to turn on the graticule display for the trace.
	Key access: Shift > Disp
Y Scale	Press this softkey to turn on the amplitude scale unit display on the left of the graticule. The unit is determined by the Y Axis Unit softkey.
	Key access: Shift > Disp
Display Line	Activates an adjustable horizontal line that is used as a visual reference line.
	The display line, used for trace arithmetic, has amplitude values that correspond to its vertical position when compared to the reference level. The value of the display line appears in both the active function block and on the softkey. The arrow keys, knob, or numeric keypad may be used to adjust the display line. Pressing any digit, 0 through 9, on the numeric keypad brings up the selected terminator menu. To deactivate the limit line, press Display Line (Off)

Key Reference Enter

Enter

Terminates a front-panel keypad numeric entry and enters that value into the analyzer. (For most applications, it is better to use the units softkeys to terminate value entry.) When in **File** menu, the **Enter** key is used to terminate filename entries.

When the analyzer is in the remote mode, pressing **Enter** returns the analyzer to the local control mode and enables front-panel inputs.

Key Reference ESC <-

ESC <-

This hardkey provides mainly two types of functions:

Clear

- · Clears any numeric entry and cancels the active function.
- Clears any title entry and cause the title to revert to the previous name.
- Clears input or output overloads
- Clears error messages from the status line along the bottom of the display.

Association with other functions

Provides a permitted setting for triggering other functions such as:

- Activates LIMIT function for pass/fail judgement.
- Activates **SAVE** function for current trace saving.

CAUTION

When pressing [ESC <-], the current parameter annotation in the lower left corner, which is an indicator of available settings of Limit and Save, disappears.

Frequency

	The hardkey activate the center frequency function, and access the menu softkeys for frequency functions. The center frequency, or start and stop frequency values appear below the graticule on the display.
NOTE	When changing both the center frequency and span, change the frequency first. The frequency value may limit the span.
Auto Tune	performs the following functions automatically: 1 Run Peak Search in full span
	 Run Mkr -> CF Select the appropriate reference level according to the amplitude of searching signal.
	4 Set span to 1 MHz and all auto couple to view the signal.
NOTE	The Auto Tune functions in the frequency range of 5 MHz to 7 GHz. The minimum detectable amplitude is –65 dBm.
	For more information about Peak Search , refer to "Peak Search" on page 152.
	Key access: Frequency > Auto Tune
Center Freq	activates the center frequency function and sets the horizontal center of the display to a specific frequency.
	Key access: Frequency > Center Freq
Start Freq	sets the frequency starting at the left side of the graticule. The left and right sides of the graticule correspond to the start and stop frequencies.
	Key access: Frequency > Start Freq

Key Reference Frequency

Stop Freq sets the frequency at the right side of the graticule. The left and right sides of the graticule correspond to the start and stop frequencies.

Key access: Frequency > Stop Freq

CF Step changes the step size for the center frequency function. On **Auto Man** selecting a step size and activating the center frequency function, the arrow keys change center the frequency by the step-size value. The step size function is useful for finding harmonics and sidebands beyond the current frequency span of the analyzer. Selecting auto-couple sets the center frequency step size to one division (10 percent of the span).

Key access: Frequency > CF Step

Channel Std. The Channel Standard softkey is a shortcut to loada factory-preset standard file (*.STD) which is located in system memory as default. The standard file list includes most communication protocol standards which is used in several countries. Please refer to "Loading a file" on page 72 for how to recall a file.

Key access: Frequency > Channel Std.

Freq Offset inputs a frequency offset value added to the frequency readout of the marker, to account for frequency co versions external to the analyzer. Offset entries are added to all frequency readouts including marker, start frequency, and stop frequency. Offsets may only be entered using the numeric keypad. Offsets are not added to the span or frequency count readouts. Entering an offset does not affect the trace display. When a frequency offset is entered, its value appears on the bottom of the display. To eliminate an offset, perform a **Factory Preset**, or press **Freq Offset**, **0**, **Hz**.

When a frequency offset is entered, its value appears on the bottom of the display (as opposed to reference level offsets, which appear on the left side of the display). To eliminate an offset, press **Freq Offset, 0**, and **Enter**. Pressing **Preset** also sets the offset to zero.

Key access: Frequency > CF Step

Low Frequency Channel
This softkey toggles the baseband channel on and off. When it is set to On, the SSB and DANL performance will be better from 3 kHz to 12 MHz. This softkey is only visible when the option BB1 has been installed and only available in Spectrum Analysis, Spectrum Monitor mode.

Key access: Frequency > CF Step

Key Reference Marker

Marker

	This hardkey accesses the marker control softkeys to select the type and number of markers. Markers are diamond-shaped characters that identify points of traces. Up to six pairs of markers may appear on the display simultaneously; only one pair can be controlled at a time. The marker that is controlled is called the "active" marker. Pressing MARKER activates the Normal menu key.
Marker	Selects one of the twelve possible markers. If a marker has already been selected it will become the active marker.
	Key access: Marker > Select Marker
Marker Trace Auto 1 2 3 4	Places a marker on the selected trace, if no markers have been previously turned on. If a marker is currently active, press Marker Trace until 1 , 2 , 3 , or 4 is underlined: the active marker moves to the selected trace.
	Selecting Auto mode moves the marker to the automatically selected trace. The trace selection will search for the lowest numbered trace in the following mode order: Clear-write , Max-hold , Min-hold and View . If there are no traces in any of these modes, it selects trace 1 .
	Key access: Marker > Marker Trace
Mode	Normal Activates a single frequency marker at the center of the active trace if not already displayed.
	Displaying a marker before enabling the Normal function enables the marker at the position of the selected marker. The marker number shows above the marker. The knob and/or arrow keys move the marker left or right. Entering a value from the numeric keypad moves the marker to the trace point nearest to that value. Annotation in the active function block and in the upper-right corner indicates the frequency and amplitude of the marker (time and amplitude, if in zero span.) Pressing Normal turns off the Delta function and moves the active marker to the delta marker position.

Key access: Marker > Mode > Normal

Delta activates a second marker at the position of the first marker. If no marker is present, two markers with the same identification number will appear at the center of the display. The marker number is indicated above the delta marker, and the same number is indicated with an **R** (for example, **1R**) above the reference marker. The amplitude and frequency (or time) of the first marker is fixed. Use the data control keys to position the delta marker. Annotation in the active function block and in the upper-right corner indicates the differences between the two markers, frequency/time and amplitude.

Key access: Marker > Mode > Delta

Delta Pair Toggles the **Delta Pair** between the reference (start) and delta (stop) markers. The start marker number is indicated with a number and an **R** (reference) above the marker (for example, **1R**). The delta marker is identified with the marker number only.

Key access: Marker > Mode > Delta Pair

Span Pair Toggles the **Span Pair** function between the span and center markers. The start marker number is indicated with a number and an **R** above the marker (such as **1R**) and the stop marker is indicated with only the marker number. Adjusting the span changes the frequency difference between the two markers while maintaining the midpoint at a fixed frequency. Selecting **Center** changes the center point between the two markers while maintaining the frequency difference.

Key access: Marker > Mode > Span Pair

NOTE Ref and Delta markers maintain their displayed x-axis location. But, the frequency values will change if the frequency or span parameters define the x-axis scale are changed. Reset these markers, if necessary, when parameters such as span or center freq are changed.

Off Turns off the active function markers. Key access: Marker > Mode > Off

Marker To	Accesses the following marker function menu keys:
	To Center Sets the center frequency of the analyzer to the marker frequency. In Delta mode, this softkey sets the center frequency to the marker delta value. The function is not available in zero span.
	To Start Changes the start frequency so that it is equal to the frequency of the active marker. In Delta mode, this softkey sets the start frequency to the marker delta value. To Start is not available in zero span.
	To Stop Changes the start frequency so that it is equal to the frequency of the active marker. In Delta mode, this softkey sets the stop frequency to the marker delta value. To Stop is not available in zero span.
	To Reference Changes the reference level to the active marker value, moving the marked point to the reference level (top line of the graticule). In Delta mode, this softkey sets the reference level to the amplitude difference between the markers.
	Key access: Marker > Marker To
Function	Accesses the marker function softkeys listed below.
	Normal Activates the default readout mode. This function is set to default marker function.
	Counter Activates a frequency counter mode.
	Noise Activates a noise readout mode for evaluating power density.
	Band Power Indicates the power over that part of the trace between the reference and active markers.
	Demod Activates the demodulation mode.
	Demod Setting Accesses the menu keys to select AM demodulation, FM demodulation or demodulation Off. It also accesses the Speaker Vol, and Delay Time menu keys described below.

Key access: Marker > Function

Marker Table Compresses the graticule and displays marker information in a table. The information includes the marker number, trace number, marker type, X axis value, and the amplitude.

Key access: Marker > Marker Table

Read Out Accesses the following menu keys that allow you to change the active marker readout. This function is only available in non-zero span.

Frequency Sets the marker to **Frequency**. The default selection in non-zero spans, displays the absolute frequency of a normal marker or the frequency of the delta marker relative to the reference marker.

Period Sets the marker readout to **Period**. Displays the reciprocal of the above frequency.

Time Sets the marker readout to Time. The default selection in zero span, displays the time interval between a normal marker and the start of the sweep or the time of the delta marker relative to the reference marker.

Key access: Marker > More > Read Out

- **Zoom In/Out** Activates the marker zoom in/out function which triggers a series of operation as below:
 - Save current state as a backup state file.
 - Set center frequency as current marker frequency value.
 - narrow the span to 1/10 as previous span.
 - If RBW is set to Auto, the RBW will be coupled with span automatically. If RBW is set to manual, the RBW will be narrowed as 1/10.

Zoom out resumes the state before Zoom in is pressed.

Key access: Marker > More > Read Out

Delta Ref Adjusts the delta marker reference level manually. This function is exclusive when marker mode is set to delta.

Key access: Marker > More > Delta Ref

 All Off Turns off all markers, including markers used for signal track, and marker annotations. Key access: Marker > More > All Off
 Logging Press this softkey to start recording the marker value to a CSV file. The frequency and amplitude value of the marker will be continuously recorded in the file. Press this softkey (Logging Stop) again to stop logging and save the CSV file immediately. Key access: Marker > More > Logging Start/Stop

Meas

In the **Spectrum Analyzer** mode (see **MODE**), **Meas** key displays a menu for measurements such as adjacent channel power, occupied bandwidth, channel power, spectrum emission mask and TOI. Press **Measure Off** to turn the measurement off.

Channel Power

Channel Power measures the power and power spectral density in the specified channel bandwidth. A white frame on the display indicates the edge limits of the channel bandwidth. The user must specify the center frequency, reference level, and channel bandwidth to be used for the measurement.

- Center Freq Sets the center frequency of display. Key access: Meas > Channel Power
 - **Integ BW** Specifies the range of integration used in calculating the power in a channel. For example, set the main (center) channel bandwidth. Note that the white frame indicates the integration bandwidth. Be sure the span is set between 1 and 10 times the integration bandwidth. Change integration bandwidth by using the knob and the arrow keys.

Key access: Meas > Channel Power

- Span Sets the sweep span of display. Key access: Meas > Channel Power
- **Span Power** Set the integrated bandwidth to the sweep span of display. The channel power and power spectral density display on the screen simultaneously.

Key access: Meas > Channel Power

Disp Mode	This softkey toggles the display mode between chart and Meter.
	Key access: Meas > Channel Power
Disp Mode	This softkey is only available when the display mode is set to Meter. Pressing Auto Range toggles the display mode between On and Off . When Auto Range is set to off (manual), press Top and Bottom to set the display range of the channel power meter.
	Key access: Meas > Channel Power
RRC Filter	This softkey is a combined key to set the Root-Raised Cosine filter state and the filter Alpha value. When the filter is set to On, there will be an annotation "RRC ON" on the display.
	Key access: Meas > Channel Power
Filter BW	Press this softkey to set the filter bandwidth of the RRC filter. The default value is 2 MHz.
	Key access: Meas > Channel Power

Occupied BW

	Occupied Bandwidth integrates the power of the displayed spectrum. The power-bandwidth routine first computes all signal power contained in the trace, then calculates the span containing the power of the specified percentage. The percentage value default is 99% of the occupied bandwidth power.
	For 99% occupied power bandwidth, Markers are placed at the frequencies on either side of 99% of the power. 1% of the power is evenly distributed outside the markers. The difference between the marker frequencies is the 99% power bandwidth.
	This is the main menu of occupied bandwidth measurement including all related parameters and measurement results.
	The occupied bandwidth function also indicates the difference between the center frequency and the center frequency of the channel. This "Transmit Freq Error " is defined
	as the difference between the $(f_1 + f_2)/2$ and the tuned center frequency of the signal.
NOTE	To get the correct measurement result, first set the center frequency, reference level, and channel spacing.

• Selecting a Method

Press **MEAS > OBW > Method** to toggle the occupied bandwidth measurement mode between **percentage (%)** and **dBc**.

• Setting Percentage (%)

Press **{OBW > Method > Percent** to edit the percentage of signal power used when determining the occupied bandwidth. Press **{%}** to set the percentage ranging from 10.00% to 99.99%.

Key Reference Meas

• Setting dBc

Press **{OBW} > {Method} > {dBc}** to specify the power level used to determine the emission bandwidth as the number of dB down from the highest signal peak, within the occupied bandwidth span. This function is an independent calculation from the OBW calculation. The x dB bandwidth result is also called the emissions bandwidth (EBW). This sets the green frame (f1 and f2 are the two cross points of the signal and the pair of vertical lines of the displayed green frame) to your specified dB value below the maximum power, and compute the total power in the frame. The emission bandwidth is then calculated ranging from 0.1 dB to 100 dB (the default value is set to 26 dB).

ACPR

	Adjacent Channel Power Ratio (ACPR) measures the power present in adjacent transmit channels. The span is automatically set according to the six available offsets and their associated integration bandwidths as defined by the user.
Center Freq	Sets the center frequency of the main channel power.
	Key access: Meas > ACP
Main Channel	Specifies the range of integration used in calculating the power in the main channel. Use the knob, the arrow keys, or the numeric keypad to set the bandwidth. Key access: Meas > ACP
Adjacent Chn State	Press Adjacent Chn to choose the number of the adjacent channel. There are optional 6 adjacent channels. Press adjacent Chn State to turn on/off each adjacent channel power display. Key access: Meas > ACP
Adjacent Channel BW	Specifies the range of integration used in calculating the power in the adjacent channel. Use the knob, the arrow keys, or the numeric keypad to set the bandwidth.
	Key access: Meas > ACP
Adj Chn Space	Sets the space value between the center frequency of main channel power and that of the adjacent channel power.
	Key access: Meas > ACP
RRC Filter	This softkey is a combined key to set the Root-Raised Cosine filter state and the filter Alpha value. When the filter is set to On, there will be an annotation "RRC ON" on the display.
	Key access: Meas > ACP
Filter BW	Press this softkey to set the filter bandwidth of the RRC filter. The default value is the integrated bandwidth.
	Key access: Meas > ACP

Key Reference Meas

Spectrum Emission Mask

	Spectrum En out-of-banc this is the po certain offse expressed as and the spec power is tak are also the power.	mission Mask measurement includes the in-band and I spurious emissions. As it applies to W-CDMA (3GPP), ower contained in a specified frequency bandwidth at ets relative to the total carrier power. It may also be is a ratio of power spectral densities between the carrier cified offset frequency band. For WLAN, the reference en as the peak PSD in the signal, and all offset results peak PSD in that offset as opposed to the integrated		
Avg Number On Off	Set Avg Number to On to specify the number of measurement averages used when calculating the measurement result. The average will be displayed at the end of each sweep. Setting Avg Number to Off disables measurement averaging.			
Meas Type	Displays a m Ref or PSD R	Displays a menu to select a measurement reference type, Total Pwr Ref or PSD Ref		
	Key access:	Key access: Meas > SEM		
	Total Pwr Ref	When Total Pwr Ref is selected, the power in the carrier is used as the reference in computing the relative power values for the offsets.		
	PSD Ref	When PSD Ref is selected, the mean power spectral density of the carrier is used in computing the relative power spectral density values for the offsets.		
Ref Channel	Accesses th	e softkeys to change the reference channel settings.		
	Key access: Meas > SEM			
	Chan Integ BV	VSpecifies the integration bandwidth used in calculating the power in the main channel.		
	Chan Span	Specifies the span used in measuring the power in the main channel.		
	Sweep Time Auto Man	Specifies the sweep time used in measuring the power in the main channel.		

Key Reference Meas

Res BW Auto Man	Specifies the resolution bandwidth used in measuring and the power in the main channel.
Total Pwr Ref (PSD Ref)	Displays the type of power measurement reference selected by Measure Type.
Auto Man	Total Pwr Ref is the power in the carrier that is used as the reference in computing the relative power values for the offsets. When Man is selected, this can be set by the user. When Auto is selected, this is the measured power in the reference carrier.
	PSD Ref is the mean power spectral density in the carrier that is used as the reference in computing the relative power spectral density values for the offsets. When Man is selected, this can be set by the user. When Auto is selected, this is the measured mean power spectral density in the reference carrier. Key access: Meas > Spectrum Emission Mask > Ref Channel

Offset/Limits Displays the menus to change the following parameters for offset frequency settings and pass/fail tests: Offset, Start Freq, Stop Freq, Sweep Time, Res BW, and Limits. Refer to the tables below for default settings of particular radio standards of interest.

Key access: Meas > Spectrum Emission Mask

Table 2 Offsets & Limits Defaulted for W-CDMA (3GPP) Base Station Measurements^a

Offset	Start Freq (MHz)	Stop Freq (MHz)	Res BW (kHz)	Abs Start (dBm)	Abs Stop (dBm)	Abs Couple	Rel Start (dBc)	Rel Stop (dBc)	Meas BW
A. On	2.515	2.715	30.00	-14.00	-14.00	Couple	-30.00	-30.00	1
B. On	2.715	3.515	30.00	-14.00	-26.00	Man	-30.00	-30.00	1
C. On	3.515	4.000	30.00	-26.00	-26.00	Couple	-30.00	-30.00	1
D. On	4.000	8.000	1000.00 30.00	-13.00	-13.00	Couple	-30.00	-30.00	1 33
E. On	8.000	12.500	1000.00	-13.00	-13.00	Couple	-30.00	-30.00	1

a. Fail Mask is set to Absolute and Rel Stop is set to Couple.

Offset	Start Freq (MHz)	Stop Freq (MHz)	Res BW (kHz)	Abs Start (dBm)	Abs Stop (dBm)	Rel Couple	Rel Start (dBc)	Rel Stop (dBc)	Meas BW
A. On	2.515	3.485	30.00	-71.07	-71.07	Man	-35.23	-49.78	1
B. On	4.000	7.500	1000.0	-55.84	-55.84	Man	-35.50	-39.00	1
C. On	7.500	8.500	1000.00	-55.84	-55.84	Man	-39.00	-49.00	1
D. On	8.500	12.000	1000.00	-55.84	-55.84	Couple	-49.00	-49.00	1
E. Off	12.500	15.000	1000.00	-55.84	-55.84	Couple	-49.00	-49.00	1

Table 3 Offsets & Limits Defaulted for W-CDMA (3GPP) Mobile Station Measurements^a

a. Abs Stop is set to Couple and Fail Mask is set to Abs AND Rel.

Table 4 Offsets & Limits Defaulted for 802.11a and HiperLAN/2 Radio Standards^a

Offset	Start Freq (MHz)	Stop Freq (MHz)	Abs Start (dBm)	Abs Stop (dBm)	Abs Couple	Rel Start (dBc)	Rel Stop (dBc)	Rel Couple	Meas BW
A. On	9.00	11.00	16.00	-4.00	Man	0.00	-20.00	Man	1
B. On	11.00	20.00	-4.00	-12.00	Man	-20.00	-28.00	Man	1
C. On	20.00	30.00	-12.00	-24.00	Man	-28.00	-40.00	Man	1
D. On	30.00	50.00	-24.00	-24.00	Couple	-40.00	-40.00	Couple	1
E. Off	50.00	100.00	-24.00	-24.00	Couple	-40.00	-40.00	Couple	1

a. Res BW is set to 100 kHz and Fail Mask is set to Rel.

Offset	Start Freq (MHz)	Stop Freq (MHz)	Abs Start (dBm)	Abs Stop (dBm)	Rel Start (dBc)	Rel Stop (dBc)	Meas BW
A. On	11.00	22.00	-10.00	-10.00	-30.00	-30.00	1
B. On	22.00	50.00	-30.00	-30.00	-50.00	-50.00	1
C. Off	50.00	70.00	-30.00	-30.00	-50.00	-50.00	1
D. Off	70.00	90.00	-30.00	-30.00	-50.00	-50.00	1
E. Off	90.00	100.00	-30.00	-30.00	-50.00	-50.00	1

 Table 5
 Offsets & Limits Defaulted for 802.11b Radio Standard^a

a. Res BW is set to 100 kHz, Fail Mask is set to Rel, and Abs Stop and Rel Stop are both set to Couple.

OffsetSelect the offset pairs (upper and lower) that the softkeys will affect,
and displays the memory selection menu from A to E (the analyzer
can store up to 5 sets of values for Start Freq, Stop Freq, Sweep Time,
Res BW, Meas BW, Abs Start, Abs Stop, etc.). Press Offset to select
the letter of the desired offset is underlined. Only one selection at a
time is shown on this key label.

Key access: Meas > SEM > Offset/Limits

Start FreqSpecifies the inner limit (frequency closest to the carrier) for bothOn Offsegments of the specified offset pair. When Start Freq (Off) is
selected, the offset pair is not measured.

Key access: Meas > SEM > Offset/Limits

Stop FreqSpecifies the outer limit (frequency furthest from the carrier) for
both segments of the specified offset pair. The minimum frequency
difference between Start Freq and Stop Freq is limited to 100 Hz.

Key access: Meas > SEM > Offset/Limits

Sweep TimeSpecifies the sweep time for the currently selected offset, and
toggles this function between Auto and Manual for each offset.

Key access: Meas > SEM > Offset/Limits

Res BW Auto Man	Specifies the resolution bandwidth used in measuring the offse pair. When set to Auto , the Res BW are used. When set to Mar allowed range is 1 kHz to 1MHz.					
	Key access:	Meas > SEM > Offset/Limits				
Abs Start	To enter an selected offs	absolute level limit at Start Freq for the currently set ranging from –200.00 to +50.00 dBm with 4 ligits.				
	Key access:	Meas > SEM > Offset/Limits > More				
Abs Stop Couple Man	To enter an selected offs significant o Man . If set t line. If set to values to ma	absolute level limit at Stop Freq for the currently set ranging from -200.00 to +50.00 dBm with 4 ligits, and to toggle this function between Couple and o Couple , this is coupled to Abs Start to make a flat limit Man , Abs Start and Abs Stop the user can enter different ake a sloped limit line.				
	Key access: Meas > SEM > Offset/Limits > More					
Rel Start	Enters a relative level limit at Start Freq ranging from –150.00 to +50.00 dBc with 4 significant digits.					
	Key access:	Meas > SEM > Offset/Limits > More				
Rel Stop Couple Man	Enters a rela +50.00 dBc between Co to make a fla can enter di	ative level limit at Stop Freq ranging from -150.00 to with 4 significant digits, and to toggle this function uple and Man . If set to Couple , this is coupled to Rel Start at limit line. If set to Man , Rel Start and Rel Stop the user fferent values to make a sloped limit line.				
	Key access:	Meas > SEM > Offset/Limits > More				
Fail Mask	Displays the conditions b Absolute , Re	e menu to select one of the following logic keys for fail between the measurement results and the test limits: lative , Abs AND Rel , and Abs OR Rel .				
	Key access:	Meas > SEM > Offset/Limits > More > More				
	Absolute	Sets the limit test to show Fail if one offset is larger than the corresponding limit for Abs Start and/or Abs Stop . This is the default selection for each offset for BTS measurements.				
	Relative	Sets the limit test to show Fail if one offsets spectrum emission mask measurement results is larger than the corresponding limit for Rel Start and/or Rel Stop .				

- Abs AND Rel Set the limit test to show Fail if one offset's spectrum emission mask measurement results is larger than both the corresponding limit for Abs Start and Abs Stop and the limit for Rel Start and Rel Stop.
- Abs OR RelSet the limit test to show Fail if one offset's the
absolute spectrum emission mask measurement
results is larger than the corresponding limit for Abs
Start and Abs Stop or the limit for Rel Start and Rel Stop.
- Meas BW Specifies the bandwidth to use when measuring the offset. When using the front panel, only the currently selected offset is affected. All the offsets are affected when remote control. This is the multiplier applied to the resolution bandwidth to determine the bandwidth to integrate when calculating the power. Meas BW is restricted to be 1 and not changeable.

Key access: Meas > SEM > Offset/Limits > More > More

Key Reference MODE

MODE

Selects the measurement mode of your analyzer. **Spectrum Analyzer** mode is the default mode and is for general purpose measurement use.

Tracking Generator

Accesses the tracking	generator functions.	(Option TG3)
Key access: Mode		

Amplitude Toggles the tracking generator output between on and off. The power level can then be adjusted using the numeric keypad, arrow keys or knob. Pressing any digit, 0 through 9, on the numeric keypad brings up the selected terminator menu. The output level range is –30 dBm to 0 dBm. When Amplitude (Off) is selected, the output attenuation is set to the maximum attenuation.

Key access: Mode > Tracking Generator

CAUTION Power-level sensitive devices connected to the tracking generator output may be accidentally damaged. This is because the actual source amplitude will be greater than the amplitude indicated on the analyzer, when the power sweep function is being used. The source amplitude value is used as the starting amplitude for a power sweep. The ending amplitude for a power sweep is higher then the source amplitude value and it may actually be set to values beyond specified output levels. Therefore, exercise caution when connecting a power-level sensitive device to the tracking generator output.

Amptd StepSets the step size of the power level range of the tracking
generator. The default setting is one vertical scale division when in
a logarithmic amplitude scale.

Key access: Mode > Tracking Generator

Amptd Offset offsets the displayed power of the tracking generator. Using the amplitude offset capability of the tracking generator allows you to take system losses or gains into account, thereby displaying the actual power delivered to the device under test.

Key access: Mode > Tracking Generator

Normalize	access a submenu to set the parameters as below.					
	Store Ref (1->3)	Copies trace 1 into trace 3. Softkey menu Store Ref (1->3) must be pressed before pressing Normalize (On).				
	Normalize On Off	Activates the normalize function. On each sweep, the normalized trace (Trace 3) is subtracted from Trace 1 and the result is added to the normalized reference level.				
		The trace data is normalized with respect to the normalized reference level, even if the value of the normalized reference level is changed. This function remains in effect on all subsequent sweeps until it is turned off.				
		The normalize function is most useful for applying correction data to a trace while making a stimulus response measurement with a tracking generator. For example, connect the cables and a thru line, in place of the device to be measured, between the tracking generator and the analyzer input. Notice that the frequency response is not perfectly flat, showing the response of the cables, as well as the flatness of both the tracking generator and the analyzer. Now press Store Ref (1->3) , Normalize (On) . Notice that the displayed trace is now flat, or normalized. The position of the normalized trace can now be moved to a different position on the display by changing the normalized reference position. This may be useful if the device to be tested has positive gain, such as an				

Key Reference MODE

		amplifier. Now, replace the thru line with the device under test, and an accurate measurement of the gain or loss can be made.
	Norm Ref Lvl	Sets the level (in dB) of the normalized reference.
	Norm Ref Posr	Offsets the displayed trace without affecting the instrument gain or attenuation settings. This allows the displayed trace to be moved without decreasing measurement accuracy. The normalized reference position is indicated with a (>) character on the left side of the display and a (<) character on the right side of the display.
	Ref Trace View Blank	Allows you to view or blank the reference trace on the display.
NOTE	The minimum mode.	resolution band wid ths is 3 kHz in the tracking generator
Power Meter

Press **Mode > Power Meter** to access the optional power meter functions. When this mode is selected, the power meter related softkey menu will be displayed and many of the instrument hardkeys will be disabled as they are not necessary for this mode.

Mode toggles the measurement between AVG and Peak. When it is set to AVG, the result shown in screen is the power sensor's measurement result. When it is set to Peak, the result shown in screen is the power sensor's gate measurement result.

Key access: Mode > Power Meter

Zeroing Accesses the associated Zeroing submenu.

Key access: Mode > Power Meter

Zeroing Makes a Zero operation of the power sensor. The U2000 Series USB Power Sensors have their sensor calibration tables stored in non-volatile memory which means that the reference calibration factor is automatically loaded upon power-up. Kev access: Mode > Power Meter > Zero/Cal Zero Type Toggles the zeroing type of the Power Sensor between internal and external. When this type is set to EXT, pressing Zero will bring up a message which indicates the external signal need be pulled out. This setting is not affected by the preset in Power Meter menu. Key access: Mode > Power Meter > Zero/Cal Calibration Toggles the zeroing type of the Power Sensor between internal and external. When this type is set to EXT, pressing Zero will bring up a message which indicates the external signal need be pulled out. This setting is not affected by the preset in Power Meter menu.

Key access: Mode > Power Meter > Zero/Cal

Meas Disp	Accesses the Meas Disp submenu for defining the display range and resolution while in Power Meter mode.			
	Key access: Mode > Power Meter			
	Disp Range	Accesses the associated Disp Range submenu. Key access: Mode > Power Meter > Meas Disp		
		Auto Range	Toggles the auto range function between On and Off. When the Auto Range is set to On, the Top and Bottom value of the power meter's display range will be set automatically according to the measurement data: Top = Max. data + 0.5 Bottom = Min. data - 0.5 The default setting is Off.	
		Тор	Sets the top value of the power meter' display range. Range from (Bottom + 0.01) to 200 dBm. The default value is 20 dBm.	
		Bottom	Sets the bottom value of the power meter' display range. Range from - 200 to (Top - 0.01) dBm. The default value is - 70 dBm.	
	Resolutio n 1 2 3 4	Accesses	the associated Resolution submenu.	
		When the measurement suffix is W or %, this parameter represents the number of significant digits. When the measurement suffix is dB or dBm, 1 through 4 represents 1, 0.1, 0.01, and 0.001 dB respectively. The default value is 3.		
		Key acces	ss: Mode > Power Meter	
General Setup	Accesses	the powe	r meter measurement setup submenu.	
	Key access: Mode > Power Meter			

Key Reference MODE

Di Mi	s Mode eter Chart	Changes the display mode between Meter and Chart . The default mode is Meter.			
		Кеу асс	cess: Mode > Power Meter > Meas Setup		
Cł	art View	Accesses the Chart View submenu. This soft key is disabled when the measurement is in process or if the display mode is set to Meter .			
		This su	bmenu is used to view the measurement chart.		
		Key acc	Key access: Mode > Power Meter > Meas Setup		
		Home	View the first 21 points of current measurement chart.		
		End	View the last 21 points of current measurement chart.		
		Prev	View the previous points of the chart.		
		Next	View the next points of the chart.		
Pause/ Continue	Continu	ues or pauses the current measurement.			
	When the measurement is in process, this softkey is displayed as "Pause"; when the measurement is paused, the softkey is displayed as "Continue".				
		Key acc	cess: Mode > Power Meter > Meas Setup		
Preset	Sets the p condition preset lim	oower me s. For exa nit values	eter softkey menu options to the preset ample, the upper and lower limits are set to their		

Key access: Mode > Power Meter

Spectrum Monitor

Press **Mode > Spectrum Monitor** to access the submenu listed as below:

- **Spectrogram** Toggles the spectrogram monitoring between **Run** and **Pause**.
 - Run/Pause Key access: MODE > Spectrum Monitor
- Restart Meas Resets the spectrogram display. Key access: MODE > Spectrum Monitor

Update Interval Enables you to set the interval of time to update data to 1 or more seconds. Or, you may set it to automatically determine the Update Interval that provides the maximum data collection speed.

A data sample is taken every time interval for display on the spectrogram. Increasing the update time allows data capturing over a longer period of time in the spectrogram.

Key access: MODE > Spectrum Monitor

Spec View Enables you to view the details in the captured spectrogram. when the Spectrogram is running, Pressing **Spec View** pauses the running spectrogram.

Press Home/End to view the first /last spectrogram in cache.

Press **Playback** to playback the spectrogram process. The direction and the update interval is changeable as your need.

Key access: MODE > Spectrum Monitor

Palette Toggles the spectrogram color mode between full color and gray scale.

Key access: **MODE > Spectrum Monitor**

Disp Mode Allows you to set the spectrogram display mode as trace, spectrogram or both trace and spectrogram.

Key access: MODE > Spectrum Monitor

File Logging Accesses the submenu for spectrogram file operation.

Start/Stop Save

This softkey allow you to start or stop the automatic save function. Once the spectrogram measurement frames reached the file size set in the **File Size**, a file (*.SPE or *.CSV) will be automatically saved, and the spectrogram measurement will restart.

Key access: **MODE > Spectrum Monitor**

NOTE The save process takes a few seconds to read from cache. During this period, the measurement is paused.

Timed Setting

This submenu allows you to configure automatic time save function. You can set start date, time, stop date, time in this menu. Press **{Timed Save On}**, the analyzer will start the auto-saving function from the **Start Time**.

• File Type

Toggles the saved file type between trace and CSV.

• File Path

Allocate the path where the file is saved.

• File Size

Set the number of frames for the spectrogram trace file. The allowed input range is 200 to 1500 frames.

Reflection Measurement

The reflection measurement mode provides the reflection measurement, one port cable loss and distance to fault measurement function.

Auto Scale

Press this softkey to adjust the amplitude scale automatically to include the peak and valley level in graticule.

Key access: Amplitude > Auto Scale

Calibrate

This softkey activates the calibration process for the measurement.

Key access: Frequency > Calibrate

Cal Type

This softkey toggles the calibration type between full span calibration and selected span calibration.

Full span calibration runs an open-short-load calibration across the full frequency span.

A FullSpan calibration ignores the frequency changes during measurements.

Selected span calibration performs an open-short-load calibration across a user-defined frequency span. A SelectedSpan Cal requires a re-calibration of the analyzer, after changing the measurement frequency range. Normally, the selected span should be set as close to the actual swept frequency range.

Key access: Freq > Cal Type

Run/Hold

This softkey toggles the frequency sweep between run and pause status.

Key access: Sweep > Run/Hold

Data->Mem

This softkey is used to store the active data trace into memory. The trace in memory will be refreshed in the next sweep once you press this softkey. There are three trace refresh mode for your selection:

Data Only the activated trace is viewable. The trace memory is not viewable.

Memory Only the trace in memory is viewable.

Data&Memory The trace both activated and in memory is viewable.

Key access: Trace > Data->Mem

Disp Mode

This softkey allows you to set the Y axis of the graticule as return loss, VSWR or reflection coefficient value.

Key access: Meas > Disp Mode

IIM On/Off

This softkey toggles IIM between on and off. When there is a need to measure the antenna feed line in field, there are probably some interference signals coupled into the device, which will be detected as spurs in the measurement result. When IIM is set to on, the analyzer will compensate those spurs by IIM algorithm.

Key access: Meas > IIM

AM/FM Modulation Analysis

Use the arrow keys to highlight the mode you need and press **[ENTER]** as a terminator. When this mode is selected, the AM/FM modulation analysis menu will be displayed.

Carrier Freq Sets the modulated carrier frequency.

Key access: Mode > AM/FM Modulation Analysis

IFBW This specifies the IF bandwidth for the signal to be analyzed. The measurement accuracy will be impacted if this value isn't set precisely.

Key access: Mode > AM/FM Modulation Analysis

EqLPF This specifies the IF bandwidth for the signal to be analyzed. The measurement accuracy will be impacted if this value isn't set precisely.

Key access: Mode > AM/FM Modulation Analysis

- Filter Setup
 Accesses the Filter setup submenu for further configuration.

 Key access: Mode > AM/FM Modulation Analysis
 - Meas Filter Selects the measure filter as Root Nyquist, Nyquist, and Gaussian.
 - **Ref Filter** Selects the reference filter as Root Nyquist, Nyquist, and Gaussian.
 - Alpha/BbT Sets the root-off factor α for Root Nyquist and Nyquist filter or BbT for Gaussian filter.
 - FilterSets the symbol numbers for the selected filter. TheSymbolsallowed value range is from 2 to 25.

 View Accesses the submenu to select four display mode: Symbol - displays the binary symbol in full screen/window.
 Waveform - displays the signal waveform.
 AM Error - displays the AM error.
 Eye Diagram - Displays the Eye diagram.
 Key access: Mode > AM/FM Modulation Analysis

X Scale Accesses the submenu to configure the X scale parametes:

Scale/Div sets the number of symbols in one division.

Ref Value sets the starting value in term of times at the reference position.

Ref position sets the display reference position to either Left, Ctr (center), or Right. If the **Auto scale** key is set to on, these parameters are adjusted automatically according to the measurement result.

Key access: Mode > AM/FM Modulation Analysis

Y Scale Accesses the submenu to configure the X scale parametes:

Scale/Div sets the number of symbols in one division.

Ref Value sets the starting value in term of times at the reference position.

Ref position sets the display reference position to either Top, Ctr (center), or Bottom.

The **Ext Gain** is set to add the external gain to the test result. If the **Auto scale** key is set to on, these parameters are adjusted automatically according to the measurement result.

Key access: Mode > AM/FM Modulation Analysis

Meas Length Sets the number of symbols which will be used in calculating the measurement.

Key access: Mode > AM/FM Modulation Analysis > More

Average On Off	Specifies the display measurement result format. When the Average Number is set to off, the column title "Average" in numerical results view will be changed to "Current".
	Key access: Mode > AM/FM Modulation Analysis > More
Trigger	Enables you to configure the trigger. When using a trigger source other than Free Run, the analyzer will begin a sweep only with the selected trigger conditions are met. A trigger event is defined as the point at which your trigger source signal meets the specified trigger level.
	Free Run - New sweep starts as soon as possible after the current sweep ends.
	RF Trigger - Activates the trigger condition that starts the next sweep if the detected RF envelope voltage rises to a level set by the RF trigger level.
	Ext Rise/Fall - Activates the trigger condition that will start a sweep when the external voltage passes through 2 volts. The external trigger signal must be a 0 V to +5 V TTL signal. Sets the trigger polarity to positive/negative.
	Trig Delay - Allows you to set and turn on or off a delay, during which the analyzer will wait to begin a sweep after receiving an external trigger signal.
	Key access: Mode > AM/FM Modulation Analysis > More
Limits	Set a limit value to warn you if the measured value exceeds the value specified here. The test reuslt will be in purple if this reslut exceeds the corresponding limit value.
	Limit - Turns on/off the limit function
	CarrPow Upr - Sets the carrier power upper limit
	FreqDev Up/Low - Sets the frequency deviation upper/lower limit
	CarrFreOff Up - Sets the carrier frequency offset upper limit
	Key access: Mode > AM/FM Modulation Analysis > More

Sweep Togglese the sweep type between single and continuous in AM/FM mode. When this softkey is set to Single, press the next **Single** softkey to execute a new sweep as soon as the trigger condition is met.

Key access: Mode > AM/FM Modulation Analysis > More

Single When the analyzer is in continuous sweep mode, pressing this softkey will change the sweep setting to single sweep. It will then begin a sweep after the trigger conditions are met.

If the analyzer is already in single sweep, pressing this softkey will execute a new sweep as soon as the trigger condition is met.

If average is on pressing this softkey will halt averaging of the current value, and then continue averaging from the current count number when a single sweep function triggers.

Key access: Mode > AM/FM Modulation Analysis > More

CarrFreq Step Changes the step size for the center frequency function. Once a step size has been selected and the center frequency function is activated, the arrow keys change the center frequency by the step-size value. The step size function is useful for finding harmonics and sidebands beyond the current frequency span of the analyzer.

Key access: Mode > AM/FM Modulation Analysis > More > More

Auto CarrFreqThis function can remedy the carrier frequency deviation when the
deviation less than symbol rate 5.

Key access: Mode > AM/FM Modulation Analysis > More > More

ASK/FSK Modulation Analysis

Use the arrow keys to highlight the mode you need and press **[ENTER]** as a terminator. When this mode is selected, the ASK/FSK modulation analysis menu will be displayed.

- **Carrier Freq** Sets the modulated carrier frequency.
 - Key access: Mode > ASK/FSK Modulation Analysis
- **Symbol Rate** This specifies the fundamental symbol rate of the signal to be analyzed. The values should be positive. The non-positive value will be converted to 1Hz. The measurement accuracy will be impacted if this value isn't set precisely.

Key access: Mode > ASK/FSK Modulation Analysis

- **Filter Setup** Accesses the Filter setup submenu for further configuration.
 - Key access: Mode > ASK/FSK Modulation Analysis
 - Meas Filter Selects the measure filter as Root Nyquist, Nyquist, and Gaussian.
 - **Ref Filter** Selects the reference filter as Root Nyquist, Nyquist, and Gaussian.
 - Alpha/BbT Sets the root-off factor α for Root Nyquist and Nyquist filter or BbT for Gaussian filter.
 - FilterSets the symbol numbers for the selected filter. TheSymbolsallowed value range is from 2 to 25.
 - View Accesses the submenu to select four display mode: Symbol - displays the binary symbol in full screen/window.
 Waveform - displays the signal waveform.
 ASK Error - displays the ASK error.
 Eye Diagram - Displays the Eye diagram.

Key access: Mode > ASK/FSK Modulation Analysis

X Scale Accesses the submenu to configure the X scale parametes:

Scale/Div sets the number of symbols in one division.

Ref Value sets the starting value in term of times at the reference position.

Ref position sets the display reference position to either Left, Ctr (center), or Right. If the **Auto scale** key is set to on, these parameters are adjusted automatically according to the measurement result.

Key access: Mode > ASK/FSK Modulation Analysis

Y Scale Accesses the submenu to configure the X scale parametes:

Scale/Div sets the number of symbols in one division.

Ref Value sets the starting value in term of times at the reference position.

Ref position sets the display reference position to either Top, Ctr (center), or Bottom.

The **Ext Gain** is set to add the external gain to the test result. If the **Auto scale** key is set to on, these parameters are adjusted automatically according to the measurement result.

Key access: Mode > ASK/FSK Modulation Analysis

Meas Length Sets the number of symbols which will be used in calculating the measurement.

Key access: Mode > ASK/FSK Modulation Analysis > More

AverageSpecifies the display measurement result format. When theOn OffAverage Number is set to off, the column title "Average" in
numerical results view will be changed to "Current".

Key access: Mode > ASK/FSK Modulation Analysis > More

Trigger	Enables you to configure the trigger. When using a trigger source other than Free Run, the analyzer will begin a sweep only with the selected trigger conditions are met. A trigger event is defined as the point at which your trigger source signal meets the specified trigger level.
	Free Run - New sweep starts as soon as possible after the current sweep ends.
	RF Trigger - Activates the trigger condition that starts the next sweep if the detected RF envelope voltage rises to a level set by the RF trigger level.
	Ext Rise/Fall - Activates the trigger condition that will start a sweep when the external voltage passes through 2 volts. The external trigger signal must be a 0 V to +5 V TTL signal. Sets the trigger polarity to positive/negative.
	Trig Delay - Allows you to set and turn on or off a delay, during which the analyzer will wait to begin a sweep after receiving an external trigger signal.
	Key access: Mode > ASK/FSK Modulation Analysis > More
Limits	Set a limit value to warn you if the measured value exceeds the value specified here. The test result will be in purple if this result exceeds the corresponding limit value. Limit - Turns on/off the limit function CarrPow Upr - Sets the carrier power upper limit FreqDev Up/Low - Sets the frequency deviation upper/lower limit CarrFreOff Up - Sets the carrier frequency offset upper limit Key access: Mode > ASK/FSK Modulation Analysis > More

Sweep Togglese the sweep type between single and continuous in ASK/FSK mode. When this softkey is set to Single, press the next Single softkey to execute a new sweep as soon as the trigger condition is met.

Key access: Mode > ASK/FSK Modulation Analysis > More

Single When the analyzer is in continuous sweep mode, pressing this softkey will change the sweep setting to single sweep. It will then begin a sweep after the trigger conditions are met.

If the analyzer is already in single sweep, pressing this softkey will execute a new sweep as soon as the trigger condition is met.

If average is on pressing this softkey will halt averaging of the current value, and then continue averaging from the current count number when a single sweep function triggers.

Key access: Mode > ASK/FSK Modulation Analysis > More

CarrFreq Step Changes the step size for the center frequency function. Once a step size has been selected and the center frequency function is activated, the arrow keys change the center frequency by the step-size value. The step size function is useful for finding harmonics and sidebands beyond the current frequency span of the analyzer.

Key access: Mode > ASK/FSK Modulation Analysis > More > More

Auto CarrFreqThis function can remedy the carrier frequency deviation when the
deviation less than symbol rate 5.

Key access: Mode > ASK/FSK Modulation Analysis > More > More

Peak Search

Places a marker on the highest peak based on the settings of the **"Peak Criteria" on page 154**.

NOTE All peak search functions ignore the LO feed through signal. The process for determining if the Peak is the LO feed through takes into account Start Frequency, Span, Resolution Band width, Resolution Band width shape factor, and Frequency Accuracy. If there is no point of inflection within the LO feed through range, the point on the trace with maximum amplitude, that is higher in frequency than the LO feed through, will be selected.

- Peak Search Performs peak search as described above. Key access: Peak Search
- **Next Peak** Places the marker on the next highest peak. The signal peak must exceed the peak threshold value by the peak excursion value. If there is no peak, the marker will not move.

Key access: **Peak Search > Next Peak**

Next Left PK Moves the marker to the next peak to the left of the current marker position. The signal peak must exceed the peak threshold value by the peak excursion value. If there is no peak to the left, the marker will not move and the "**No Peak Found**" error message will appear on the display.

Key access: **Peak Search > Next Left Peak**

Next Right PK Moves the marker to the next peak to the right of the current marker position. The signal peak must exceed the peak threshold value by the peak excursion value. If there is no peak to the right, the marker will not move and the "**No Peak Found**" error message will appear on the display.

Key access: **Peak Search > Next Right Peak**

Pk-Pk Search Finds and displays the frequency (or time, if in zero span), and amplitude differences between the highest and lowest trace points.

Key access: **Peak Search > Pk-Pk Search**

To Center This is a hot key of marker to center. Key access: Peak Search > Pk-Pk Search

Continuous Pk When Continuous Pk is on, the marker will remain on the peak signal even if the frequency of that signal changes. The marker will remain on that signal as long as the amplitude of the signal does not change by more than 3 dB from one sweep to another.

If the signal is lost, the marker will attempt to find it again and maintain on the peak. If there are other signals on screen near the same amplitude, one of them may be found instead. Signals near 0 Hz cannot be maintained effectively.

This function is intended to maintain the marker on signals with a frequency that is changing, and an amplitude that is not changing.

Key access: **Peak Search > Continuous PK**

Peak Table Peak Table Displays a list of up to ten signal peaks that is updated at the end of each sweep. The peaks can be sorted in order by descending amplitude or by ascending frequency. Peaks above or below the display line can be excluded from the table. The peak table function works with trace 1 only.

Exprt Table to CSV Press this softkey to save the current peak table to a CSV file for your data analysis on PC.

Key access: **Peak Search > More**

Key Reference Peak Search

Peak Criteria	Accesses the submenu to set the criteria for peak search.		
	Key access: P	eak Search > More	
	Peak Excursion	Sets the minimum amplitude variation of signals that the marker identifies as a peak. If a value of 10 dB is selected, the marker moves only to peaks that rise and fall more than 10 dB above the peak threshold value. When the peak excursion is 6 dB or higher,	
NOTE	Two signal peal between them two peaks. A si above the noise	ks, which are so close together that the amplitude drop is less than the peak-excursion value, are not recognized as gnal peak is recognized only if it has a peak excursion drop e floor, on both sides of the signal.	
		the marker-peak does not recognize signals less than peak-excursion value above the noise floor. To correct this, when measuring signals near the noise floor, reduce the excursion value. To prevent the marker from identifying noise as signals, reduce the noise floor variance less than the peak-excursion value by reducing the video bandwidth or by using video averaging.	
		Key access: Peak Search > More	
	Peak Threshold	Sets the minimum amplitude that the marker can identify as a peak. For example, if set to -90 dBm, the marker moves only to peaks that rise and fall more than the peak excursion above -90 dBm. Only functional when in Excursion and Threshold marker mode. Key access: Peak Search > More	
	Peak Type	Toggles the peak type between maximum value and minimum value. Key access: Peak Search > More	

System

Pwr

	This softkey settings.	accesses	the submenu to set the system and utility	
Time/Date	accesses the and date.	e Time/Dat	e menu keys used to set and display the time	
	Key access:	System > 1	Time/Date	
Language	chooses the	11 langua	iges for softkeys display.	
	Key access:	System > 1	Time/Date	
wr on/Preset	Accesses the following softkeys for the preset settings.			
	Key access: System > Pwr On/Off			
	Power on DFT User Last	Determin analyzer the analy function. settings v panel pov	es the state of the analyzer when the is turned on. Power On set to Preset recalls zer settings previously with the Preset Power On set to Last recalls the analyzer when the analyzer is turned off by the front wer switch.	
	Preset Type	Selects U	lser or Factory preset settings.	
		User	Pressing Preset recalls the analyzer settings defined by Save User Preset .	
		DFT	Pressing Preset recalls the analyzer settings originally set at the factory.	
		Last	Pressing Preset recalls the analyzer settings to the last time power-off.	
	Save User	Saves the Preset reg Type to Us	e active settings of the analyzer into the User gister. To recall these settings, select Preset ser.	

System Info	Accesses the subr	nenu to check the system information as below.		
	Key access: System > More			
	Show System Displays the number and description of the options installed in your analyzer. It also displays the instrument model number, product number, serial number, the date of production, etc.			
	Installed Options	displays the installed option list.		
	Error History Accesses a list of the 100 most recent errors reported. The most recent error will appear at the bottom of the list. If the same error occurs continuously, that error message will not be added repeatedly to the list. Refer to "Instrument Messages" on page 173 for details.			
	Prev Page/ Next Page Clear Error Queue	Access the previous/next page of error messages. Clears all the errors in the errors queue.		
Service	Accesses the subr	nenu to set the service settings as below.		
	Key access: System > More > Service			
	Calibration Accesses the submenu to calibrate the time base of the analyzer, load default values for the alignment system.			
	Time Base by Ext	Calibrates the time base of the analyzer with external source.		
	Amp Alignment	Adjust the amplitude accuracy according the internal cal out signal.		
	CAL OUT On Off	Turns the internal amplitude reference signal on or off. When this signal is on, the RF input is disabled.		
	Upgrade Enables	the firmware upgrade process once the USB		

Upgrade Enables the firmware upgrade process once the USB disk with the firmware upgrade package plug connected.

Diagnostics Accesses the **Front Panel** softkey to verify the functionality of each front-panel key. The number next to each key name increments once each time the key is pressed. Rotating the knobs causes the number of pulses to be counted. Press **Return** will go back to the main menu.

Add Option Accesses the security system to enable licensing for individual options. A user may not turn off an option using this system. Once an option has been licensed for a given analyzer, it cannot be transferred to a different analyzer.

Port Setting Access the submenu to set the ports as below. Key access: System > More > Port Setting

 $\ensuremath{\text{lp Config}}$ Toggles the IO port between $\ensuremath{\text{USB}}$, $\ensuremath{\text{LAN}}$ and $\ensuremath{\text{GPIB}}$ (option) for remote control.

Probe Power Provides power for high-impedance AC probes or other accessories (+15 V, -12V, 150 mA maximum). Key access: **System > More > Port**

GPIB Address sets the GPIB address (option G01 required).

Key Reference Span

Span

Accesses the span function and the submenu softkeys for span functions. Pressing **Span** changes the frequency range symmetrically about the center frequency. The frequency-span readout describes the total displayed frequency range. To determine frequency span per horizontal graticule division, divide the frequency span by 10.

- Span Enter the span frequency range value. Key access: Span
- **Full Span** Changes the span to full span showing the full frequency range of the analyzer.

Key access: Span

Zero Span Changes the frequency span to zero. In this mode, the current center frequency is displayed in the time domain (the x-axis is displayed in units of time), like a conventional oscilloscope.

Key access: Span

Last Span Changes the span to the previous span setting. Key access: Span

Sweep

Accesses the Sweep softkeys for selection of the sweep mode and trigger mode of the analyzer. The softkey menu selections are defined as follows:

Sweep Time
Auto ManSelects the sweep time for the analyzer to tune across the
displayed frequency span (or, in zero span, the time the analyzer
take to sweep the full screen).Inputs may be made using the knob,
the arrow keys, or numeric keypad.

In non-zero spans

When the sweep time is auto-coupled, the analyzer selects the optimum (shortest) sweep time ranging from 10 ms to 1000 s. The auto selection is determined by three measurement settings:

- Frequency Span
- The selected Resolution Bandwidth
- The selected Video Bandwidth

Note that changing one of the three factors above will change the sweep time. The sweep time is in direct ratio to frequency span and is in reverse ratio to the selected resolution bandwidth and video bandwidth when auto-coupled.

CAUTION

With sweep time set to a value less than the minimum auto-coupled value, an annotation "Data out of range" appears in the active function block and the sweep time is automatically converted to the minimum auto-coupled value. Key Reference Sweep

In zero span

Auto-coupled does not function when in a zero span. The sweep time can only be set manually. The sweep time is selectable from 6 s to 200 s in zero span.

In FFT Mode

In FFT mode, the sweep time default is auto-coupled. The submenu, sweep time is invalid in FFT mode.

Key access: Sweep

SweepPressing Sweep Single puts the analyzer in single-sweep mode.Single ContPress Sweep Single to initiate a sweep when in single-sweep mode.Press Sweep Cont Performs one sweep after another as soon as it is
triggered. Pressing Preset (When Preset Type is set to Factory) sets
the sweep mode to continuous sweep.

Key access: Sweep

Single SweepWhen the analyzer is in continuous sweep mode and not in a
measurement mode (MEAS > Measure Off), pressing Sweep >
Single Sweep will change the sweep setting to single sweep. It will
then begin a sweep after the trigger conditions are met. If the
analyzer is already in single sweep, pressing Sweep > Single Sweep
will execute a new sweep as soon as the trigger condition is met.

If average is on (TRACE > More > Average Number On), pressing Sweep > Single Sweep will halt averaging of the current value, and then continue averaging from the current count number when a single sweep function triggers.

Key access: Sweep

Trigger Accesses the menu of keys that allow you to select the trigger mode of the analyzer. This softkey is only available in zero span.

Free Run

New sweep starts as soon as possible after the current sweep ends.

Video

Activates the trigger condition that starts the next sweep if the detected RF envelope voltage rises to a level set by the video trigger level. When **Video** is pressed, a line appears on the display. The analyzer triggers when the input signal exceeds the trigger level at the left edge of the display. Change the trigger level by using the arrow keys, the knob, or the numeric keypad.

NOTE

This function is not available when the Resolution Bandwidth is less than 1 kHz. Selecting a Resolution Bandwidth less than 1 kHz while in Video Trigger mode, changes the Trigger mode to Free Run.

External

Activates the trigger condition that will start a sweep when the external voltage (connected to **EXT TRG IN** on the rear panel) passes through approximately 2 volts. The external trigger signal must be a $0 \vee to +5 \vee TTL$ signal.

Key access: Trace > More

Gated Sweep Accesses the menu of keys to select the gated sweep parameters. This function is used to ensure fast and accurate measure TDM, TDD or RF busted signals.

Key access: Sweep > Gated Sweep

Gated Sweep

Turn on/off the gated sweep function.

Key Reference Sweep

Gated View

When Gate View is set to off, the display is in frequency domain. When Gate View is set to On, the display is in time domain (zero span), the gate length is shown in red lines for further adjustment.

View SweepTime

Adjust the sweep time scale to set the gate parameters precisely.

Gate Delay

Set the time to wait after the gate signal is received before the gate sweep is implemented. The gate delay is auto coupled to a minimum value with different RBW values.

Gate Length

Set the gate length for gated sweep. The gate length is auto coupled to a minimum value with different RBW values.

Gate Source

There are three sources for gated sweep.

When **External** is selected, a TTL signal is required.

For External and Periodic Timer, a sync source is

required for specified event synchronization.

RF burst is an internal trigger source if there is not any external source.

Sweep Setup accesses the sub-menu to set the sweep time rule and sweep mode as below.

Swp Time Rule

The analyzer provides two sweep time rules to meet the different sweep time requirements:

• Speed

Activates the default fast sweep time rule.

Accuracy

Activates the normal sweep time rule to ensure the measurement accuracy.

Speed sweep time rule provides a fast measurement function to decrease the sweep time. Fast sweep will decrease the measurement accuracy.

Sweep Type

This softkey toggles the sweep type between swept mode and FFT mode. This FFT mode is only available when RBW is set to 1 kHz, 3 kHz, or 10 kHz.

Key access: Sweep > Sweep Setup

Dwell Time Sets the dwell time for Quasi-Peak detector. When the dwell time is set to AUTO, the time couples with EMC filter.

This softkey is only available when EMC filter **(BW > Filter Type)** and Quasi-Peak detector **(Trace/Det > More > Detector)** are selected in non-zero span.

Key access: Sweep > Dwell Time

Limits

Limit

Accesse parame	es softkeys t eters of limit	hat allow you to control and define the lines.	
Кеу асс	cess: Shift >	Limit	
Limit 1 Limit 2	selects either of the available limits. The Limit 1 and Limit 2 keys access softkeys to set parameters for the selected limit.		
	Key access	: Shift > Limit	
	Type Upper lower	defines the limit to be edited as an upper or lower limit. An upper limit will indicate a fail if trace 1 exceeds this limit. A lower limit will indicate a fail if trace 1 falls below the limit.	
		Key access: Shift > Limit > Limit 1/2	
	Limit On Off	Toggles the limit line function to on or off. The limit points must exist before the limit function can be turned on. Either Limit or Margin , as well as Test , must be turned on for a limit test. Limit points must be defined before the Limit function can be turned on.	
		Key access: Shift > Limit > Limit 1/2	
	Test On Off	Toggles the testing of the limit lines between on and off. If trace 1 is at or within the bounds of the set limit or margin, "Limit_# Pass" or "Margin_# Pass" is displayed in the upper left corner of the measurement area limit line. Only positive/negative margins are allowed for lower/upper limits. If the trace is out of the limit or margin boundaries, "Limit_# Failed" or "Margin_# Failed" is displayed. Either Limit or Margin must be turned on for test.	
		Key access: Shift > Limit > Limit 1/2	

Key Reference Limit

MarginToggles the margin function to on or off. UseOn OffMargin to set a limit line offset for the selectedlimit line. Either Limit or Margin as well as Test,
must be turned on for a limit test to work.
Key access: Shift > Limit > Limit 1/2

Accesses the submenu to edit the limit point, and also accesses the limits table. Use arrow keys to move between the rows in the limits table. New limit segments will only be applied after close the editor. Pressing **Return**, or any key not associated with the editor, will close the editor.

Key access: Shift > Limit > Limit 1/2

Point

Edit

Creates or edit a limit point. Up to 20 points can be defined for each limit line. Enter the point number using the numeric keypad, then Press **[Enter]**, or use the knob or arrow keys to move to an existing point.

Key access: Shift > Limit > Limit 1/2 > Edit

Frequency

Edits the frequency value for a limit point. After editing, the limit table will place the frequency or time in correct order. For a new point, the **Amplitude** default is 0 dBm, and **Connected** default is **Yes**.

Key access: Shift > Limit > Limit 1/2 > Edit

Amplitude

Sets the amplitude value for the current point. Key access: **Shift > Limit > Limit 1/2 > Edit** Key Reference Limit

		Connected To Previous Pt Yes No Defines if the current point being edited is to be connected to the previous point. Pressing this key toggles the Connected value between Yes and No. Key access: Shift > Limit > Limit 1/2 > Edit
		Delete Point Deletes the current point in the limit line.
		Pressing this key will delete the point immediately.
	Build From Trace	Build a limit from current existing trace. One X/Y point is made from each measured data point. Once the limit have been built from the trace, changes that you make to the trace, such as frequency range, do NOT change the limits. Build From Trace action doesn't change any limit state, if limit is on, the display will be updated. However, limits properties will be edited just like standard limits. Key access: Shift > Limit > Limit 1/2
	Delete Limit	Deletes the current limit set. Pressing this key will delete the limit line entirely. Key access: Shift > Limit > Limit 1/2 > More
Delete All Limits	Purges data fr delete all the I Key access: SI	om the limit-line tables. Pressing this key will imit line data immediately. nift > Limit

Trace/Det

Accesses the trace keys to store and manipulate trace information. Each trace consists of a series of points in which amplitude data is stored. The analyzer updates the information for any active trace with each sweep.

- **Trace** Selects the trace for current use.
- 1234 Key access: Trace/Det > Trace 1234
- **Clear Write** Erases any data previously stored in the selected trace, then continuously displays any signals during each sweep of the analyzer. This function is activated for trace 1 at power-on and **Factory Preset**.

Key access: Trace/Det > Clear Write

Max Hold Retains the maximum level for each trace point of the selected trace. Updates the trace point value if a new maximum level is detected in successive sweeps.

Key access: Trace/Det > Max Hold

Min Hold Retains the minimum level for each trace point of the selected trace. Updates each minimum trace point if a new minimum level is detected in following sweeps.

Key access: Trace/Det > Min Hold

View Holds and displays the amplitude data of the selected trace. The trace register is not updated as the analyzer sweeps. press **View** to retrieve a stored trace previously deactivated by pressing **Blank**.

Key access: Trace/Det > View

Blank Stores the amplitude data for the selected trace, then removes the trace from the display. The selected trace register no longer updates as the analyzer sweeps. To activate this function for traces 2, 3 and 4 at power-on press **Preset** (when **Preset Type** is set to **Factory** and **Factory Def**).

Key access: Trace/Det > Blank

Detector (detector type)

Softkey presents a submenu to select a specific detector type, or allows the analyzer to select the appropriate detector for a particular measurement.

Regarding detectors, it is important to understand what is a trace "bucket". For every trace point displayed, there is a finite time during which the data for that point is collected. The analyzer looks at all of the data collected during that time and present a single point of trace data based on the detector mode. The interval during which the data for that trace point is being collected, is called the "bucket".

Thus a trace is more than a series of single points. It is actually a series of trace "buckets". The data may be sampled many times within each bucket.

- Average displays the power average in the bucket.
- **Sample** displays the instantaneous level of the signal at the center of the bucket represented by each display point.
- **QuasiPeak** displays a weighted, sample-detected amplitude using specific, charge, discharge, and meter time constants derived from the legacy behaviors of analog detectors and meters.
- **Positive Peak** displays the max. of the signal in the bucket.
- **Negative Peak** displays the min. of the signal in the bucket.

The detector in use is indicated on the left side of the display. A "#" will appear next to it if the detector has been manually selected.

Key access: Shift > Dsip > More

PositiveObtains the maximum video signal between the last
display point and the present display point and stores
this value in memory. It's used primarily when
measuring sinusoidal components. When Positive
Peak is selected, "Peak" appears in the upper-left
corner.

NegativeIs a peak detector, but selects the minimum videoPeaksignal value. This detection should not be used to
measure the accurate amplitude. "NPk" also appears
in the upper-left corner, When Negative Peak is
selected.

- Average measures the average value of the amplitude across each trace interval (bucket). When **Average** is selected, "**Avg**" appears on the left corner.
- Sample Sample detection is used primarily to display noise or noise-like signals. It should not be used to measure the accurate amplitude of non noise-like signals. In sample mode, the instantaneous signal value of the present display point is placed in memory. When Sample detection is selected, "Samp" appears in the upper-left corner of the display.
- Normal Selects the maximum and minimum video signal values alternately. When selecting **Normal** detection, "Norm" appears in the upper-left corner.
- QuasiPeak Quasi-peak detection displays a weighted, sample-detected amplitude using specific, charge, discharge, and meter time constants derived from the legacy behaviors of analog detectors and meters. It is used for EMI measurements to provide a specific and consistent response to EMI-like signals.

Note that CISPR standard operation is to perform the averaging associated with quasi peak detection on the voltage scale. You can manually set the **Average Type** to **Log-Power** or **Power**, but the results will no longer be CISPR compliant.

The QuasiPeak detector is only available in **Sweep** mode. If the current sweep mode is **FFT**, once the QuasiPeak detector is selected, the sweep mode will be forced into **Sweep**.

The minimum RBW for QuasiPeak detector is 1 kHz.

Average Number
On OffInitiates a digital averaging routine that averages the trace points
in a number of successive sweeps resulting in trace "smoothing".
The number of sweeps (average number) is changeable when
setting Average (Off). Increasing the average number will further
smooth the trace. pressing BW > Avg Type to select the type of
averaging.

	To restart averaging:
	Enter a new average number
	 Change any related parameter (e.g., Center Frequency)
	When in sweep single , the specified number of averages is taken, then the sweep stops and an average trace displayed.
	When in continuous sweep mode, the specified number of averages is taken, then the averaging continues with each new sweep averaged in with a weight of $\frac{1}{\text{AverageNumber}}$ and the old average reduced by multiplying it by $\frac{1}{\text{AverageNumber}} - \frac{1}{1}$.
	To turn averaging off, press Average Number (Off).
	Key access: Trace/Det > More > Average Number On/Off
Average Dura. On Off	Initiates a digital averaging routine that averages the trace points in an average duration resulting in trace "smoothing". Increasing the average duration will further smooth the trace.
	The average is restarted when any of the following occurs:
	A new average duration is entered.
	• Any related parameter (e.g., center frequency) is changed.
	 {Avg Restart} is pressed
	Press Average Dura. (Off) to turn off averaging.
	Key access: Trace/Det > More > Average Number On/Off
Trace Math	This softkey provides a submenu for the traces operation.
	Key access: Trace/Det > More > More > Trace Math
	Variable A, B, C Press those softkeys to select a trace (for variable A,B, and C) or a display line (for variable A and B) for the trace calculation.
	A-B-> C Turn this softkey on to calculate variable A minus variable B. The result will display as variable C when all the variables is set to on. This function and A+B->C can not be set to on simultaneously.

A+B-> C Turn this softkey on to calculate variable A plus variable B. The result will display as variable C when all the variables is set to on. This function and **A-B->C** can not be set to on simultaneously.

Math By This softkey toggles the caculation type between power and logarithmic power. When it is set to **power**, the variable A and B will be calculated in power and the result variable C will display in converted logarithmic power. When it is set to **log power**, the variable A and B will be calculated in lograithmic power and the result variable C will display in logarithmic power. Key Reference Trace/Det
5 Instrument Messages

Overview 174 Command Errors 175 Execution Conflict 177 Device-Specific Errors 179



Instrument Messages Overview

Overview

If an improper operation occurs during the instrument configuration, a message will appear on the status line indicating the incident and the how the spectrum analyzer corrected the setting automatically. press **System > System Info > Errors History** to read the specific descriptions of those messages.

Example

In this example, a failure explanation is generally included with each error to further define its meaning. The instrument messages in this guide are listed numerically.

<Number> <Code> <Message>

1. -330 Self-test failed

A self-test failure occurred.

<Explanation in manual>

Command Errors

The messages listed below are command errors, which are saved into local registers.

-100 Command error

An unrecognized command or data type was encountered. This message is used when the device cannot detect more specifics described for errors -101 to -109.

- -101 Invalid character A syntactic element contains an invalid character.
- -102 Syntax error An unrecognized command or data type was encountered.
- -103 Invalid separator The parser was expecting a separator and encountered an illegal character.
- -104 Data type error The parser recognized a data element that is not allowed.

-108 Parameter not allowed More parameters were received than expected for the header. For example, the *ESE common command only accepts one parameter, so receiving *ESE 0,1 is not allowed.

-109 Missing parameter Fewer parameters were received than required for the header. For example, the *ESE common command requires one parameter, so receiving *ESE is not allowed.

-110 Command header error An error was detected in the header. This message is used when the device cannot detect more specifics described for errors -111 to -119.

Instrument Messages Command Errors

- -112 Program mnemonic too long The header contains more than 12 characters.
- -113 Undefined header The header is correct in syntax, but it is undefined for this device.
- -128 Numeric data not allowed A legal numeric data element was received, but the device does not accept one in this position for the header.
- -130 Suffix error
 This error is generated when parsing a suffix. This message is used when the device cannot detect more specifics described for errors -131 to -139.
- -131 Invalid suffix The suffix does not follow the syntax described in *IEEE 488.2*, or the suffix is inappropriate for the device.
- -134 Suffix too long The suffix contained more than 12 characters.
- -138 Suffix not allowed A suffix was encountered after a numeric element which does not allow suffixes.
- -144 Character data too long The character data element contains more than 12 characters.
- -148 Character data not allowed A legal character data element was encountered where prohibited by the device.

Execution Conflict

The system messages listed below are execution conflicts, indicating settings conflict during your operation.

- -200 Execution Error This is the generic syntax error for devices that cannot detect more specific errors.
- -222 Data out of range A legal program data element was parsed but could not be executed because the interpreted value was outside the legal range defined by the device. The displayed results may be clipped.
- -223 Too much data not all points entered Indicates that a legal program data element of block, expression, or string type was received that contained more data than the device could handle due to memory or related device-specific requirements.
- -224 Illegal parameter value An attempt was made to select a user file that contains 0 bits. Select another user file that contains at least 1 bit.
- -241 Hardware missing Missing device hardware. For example, the RF board is not installed.
- -253 Corrupt media A source media (possibly EEPROM) for a data file is corrupt. This error is usually seen in conjunction with errors concerning a certain file.
- -300 Device-specific error This is the device-specific error for devices that cannot detect more specific errors.

Instrument Messages Execution Conflict

- 330 Self-test failed A self-test failure occurred. Report this error to Keysight Technologies.
- 340 calibration failed An expected file was not found while trying to load internal calibration.

Device-Specific Errors

- Set 50 MHz signal < 0 dBm, do alignment again
 The 50 MHz energy is too high at the RF port for alignments to run.
 Reduce input power to less than 0 dBm and run alignments again.
- 104 1st LO Unlock
 The first LO on has lost phase lock. Report this error to the nearest Keysight Technologies sales or service office.
- 2nd LO UnlockThe second LO has lost phase lock. Report this error to the nearest Keysight Technologies sales or service office.
- 201 Option not installed The desired operation cannot be performed because a required option is not installed.
- 204 TG Frequency Limit The tracking generator has reached the limit of its allowable frequency range.
- 211 RBW limited to 1 kHz when Span > 1 MHz In spans greater than 1 MHz, narrow (digital) resolution bandwidths, below 1 kHz, are not available.
- 213 Span limited to 1 MHz when RBW < 1 kHz In narrow (digital) resolution bandwidths, below 1 kHz, spans greater than 1 MHz are not available.
- 214 TG start freq is less than 9 kHz Tracking generator uncalibrated below 9 kHz.
- 215 TG start freq is less than 1/2 res bw Tracking generator uncalibrated at start frequencies below 1/2 the current resolution bandwidth.

- 224 Option not licensed The selected option requires a license. Refer to the installation procedures in the user guide provided for this particular option.
- 238 VBW filter or Average Detector cannot use both
- 501 RF over load Either increase input attenuation or decrease the input signal level.
- 502 IF over load Either increase input attenuation or decrease the input signal level.
- File already existsYou attempted to save to a file that already exists. Either delete or rename the existing file or select a new name, then try again.
- 605 Media is protected A save was attempted to a write-protected device.
- 610 File access is denied The file is protected or hidden and cannot be accessed.
- 612 File not found The analyzer could not find the specified file.
- 651 Connect TG OUT to RF IN Attempt to align the tracking generator without its output connected. Connect the **TG SOURCE** to **RF IN**.
- 652 Connect CAL OUT to RF IN you must connect the **CAL OUT** to **RF IN** with the appropriate cable.
- 751 Instrument state set to initial values While trying to load a trace or state, the state information was found to be in error. This may be because the state had been stored on a later revision of analyzer firmware. A default set of state variables was loaded instead. There is nothing wrong with the analyzer.

- 752 Unable to load state from file Attempt to load a state from a file failed.
- 753 Unable to save state to file Attempt to save a state to a file failed. See the associated error messages for the cause.
- 757 Unable to load user stateA user preset failed, so the factory preset values were used. Save a valid state into user preset and try again.
- 758 Unable to save user state Attempt to save a user preset state failed.
- 760 Unable to query state Query of state over the remote interface was unsuccessful.
- 762 Unable to load file A failure occurred while loading a file.
- 764 Unable to save fileAttempt to save a file failed; the file was not saved.
- 767 Fatal LDS error

Attempt to initialize the instrument state has failed. Cycle instrument power. If this fails to correct the problem, contact your nearest Keysight Technologies service center.

- 768 Unable to load user state Attempt to load a state failed, because the state was saved with a measurement personality that is not currently loaded. Load the appropriate personality and try again.
- 770 Incorrect filenameYou sent a remote command to save a screen file but did not specify a valid extension.

- No Peak Found
 No signal peak was found that meets the criteria under Peak
 Search > Peak Criteria.
- 781 Video Trigger cannot be active You sent a remote command to do one of the following:
 - Turn on video trigger while the Average Detector or a Marker Function is active.
 - Turn on the Average Detector or a Marker Function while Video Trigger is active.
- Video Trigger cannot be used with Mkr FuncDue to the Average Detector, the video Trigger cannot be used with Maker function.
- 783 Allowable span for current CF exceeded
- 784 Allowable CF for current span exceeded
- 805 Doing Alignment

6 Troubleshooting

This chapter includes information on how to check for a problem with your Keysight Technologies spectrum analyzer, and how to return it for service.

If you experience a problem or would like additional information about your analyzer, Keysight Technologies' worldwide organization is ready to provide the support you need.



Check the Basics

	Before calling Keysight Technologies, or returning an analyzer for service, perform the quick checks listed below. This check may eliminate the problem.		
	Is there power at the receptacle?		
	 Is the analyzer turned on? Listen for internal fan noise to determine if the analyzer cooling fan is running. Feel the rear side of the analyzer for air flow. 		
	 If other equipment, cables, and connectors are being used with your spectrum analyzer, make sure they are connected properly and operating correctly. 		
	• Review the measurement procedures being performed when the problem first appeared. Make sure all of the settings are correct.		
	 If the analyzer is not functioning as expected, return the analyzer to a known state by pressing Preset. 		
NOTE	Some analyzer settings are not affected by a Preset. If you wish to reset the analyzer configuration to the state it was in when it was originally sent from the factory, press System, Power On/Preset, Preset Type, Factory. Then press the green Preset key on the front panel		
	 Is the measurement being performed, and the results that are expected, within the specifications and capabilities of the analyzer? Refer to the <i>Technical Overview</i> for your analyzer. 		
	 Is the analyzer displaying an error message? If so, refer to "Instrument Messages" on page 173 for details. 		
	• To meet specifications, the analyzer must be aligned. For more information on how to align the analyzer, refer to "Time Base Calibration" on page 23 .		
WARNING	No operator serviceable parts inside. Refer servicing to qualified personnel. To prevent electrical shock, do not remove covers.		

Troubleshooting Check the Basics

NOTE If the analyzer is still under warranty or is covered by a maintenance contract, it will be repaired under the terms of the warranty or plan (the warranty is located at the front of this manual).

If the analyzer is no longer under warranty or is not covered by an Keysight Technologies maintenance plan, Keysight Technologies will notify you of the cost of the repair after examining the analyzer.

If a problem persists, please contact the Keysight Technologies office for further information and service.

Warranty and Service Options

Please read the warranty and become familiar with its terms.

If your analyzer is covered by a separate maintenance agreement, please be familiar with its terms.

Keysight Technologies offers several optional maintenance plans to service your analyzer after the warranty has expired. Call your Keysight Technologies office for full details.

The calibration cycle of N932xC spectrum analyzer is one year.

NOTE A button cell provides power to the real time clock of the spectrum analyzer. It is not rechargeable. If you find your unit encounters a clock defect, please contact your nearest Keysight Customer Contact Center (CCC) for service.

Contact Keysight Technologies

Keysight Technologies has offices around the world to provide you with complete support for your analyzer. To obtain servicing information or to order replacement parts, contact the Keysight Technologies customer contact center listed below. In any correspondence or telephone conversations, refer to your spectrum analyzer by its product number and full serial number..

Online assistance: http://www.keysight.com/find/assist

United States	Canada	China	
(tel) 800 829 4444 (fax) 800 829 4433	(tel) 877 894 4414 (fax) 800 746 4866	(tel) 800 810 0189 (fax) 800 820 2816	
Europe	Japan	Korea	
(tel) +31 20 547 2323 (fax) +31 20 547 2390	(tel) +81 426 56 7832 (fax) +81 426 56 7840	(tel) 080 769 0800 (fax) 080 769 0900	
Latin America	Taiwan	Australia	
(tel) +1 (305) 269 7500	(tel) 0800 047 866 (fax) 0800 286 331	(tel) 1 800 629 485 (fax) +61 (3) 9210 5947	
Other Asia Pacific Countries			

(tel) +65 6375 8100

(fax) +65 6755 0042 Email: tm_ap@keysight.com

7 Menu Maps

This chapter provides a visual representation of the front panel keys and their associated menu keys (in Spectrum Analyzer mode). Refer to **Chapter 4 " Key Reference"**, on page 103 for key function descriptions.

The name editor menu is shown separately, though it is accessed when entering data for many keys. The front-panel key menus appear in alphabetical order as follows.



Amplitude Menu



BW Menu



Sweep Menu



Display Menu



*This menumap is for **Channel Scanner** measurement.



*This menumap is for ASK/FSK modulation analysis.

File/Mode - Task Planner



1

*The softkey *Copy/Move* only exists in the submenu of *Copy To/Move To*.

2

*The softkey *View FileType* is fixed as TPF in Task Planner Mode.

Frequency Menu



*This softkey is only visible when option BB1 is installed.

Limit Menu



Marker Menu



Menu Maps Peak Search Menu

Peak Search Menu



Measure Menu (1 of 2)



Measure Menu (2 of 2)



Mode - Tracking Generator



Menu Maps Mode - Power Meter

Mode - Power Meter



Mode - AM/FM Modulation Analysis



* Ext Gain is only available in Y Scale submenu.

Mode - ASK/FSK Modulation Analysis



Mode - Reflection Measurement



a. Press Meas twice to toggle the submenu between Meas setup and Mode setup.

b. The Meas submenu is specific for DTF measurement.

c. The Cable Type and Window submenu is specific for DTF measurement.

Menu Maps Name Editor Menu

Name Editor Menu



System Menu



SPAN Menu



Trace/Det Menu



Menu Maps Trace/Det Menu
Numerics

3GPP W-CDMA 127 802.11a 128 802.11b 129

KEYSIGHT

TECHNOLOGIES

А

Abs Start 130 Abs Stop 130 adjacent channel power 125 Amplitude key 102 annotation, marker 33 Attenuation 102 attenuation, reducing 44 Average 167

В

BW/Avg key 106

С

Calibrate, using T-combo 72 calibration, freq change 140 Calibration, span changes 72 CE mark 10 Center Freq 113 CF Step 114 channel power 121 comparing signals off screen 36 on the screen 34 Continuous PK 151 CSA mark 10 c-tick mark 10

D

delta marker 117 Det/Display key 110 Detector 166 distortion, measuring 53 DTF Measurement 74

Е

Enter key 111 error message 17 ESC/CLR 112 ESD 21 external reference 24

F

Fail Mask 130 firmware revision, update 25 front panel overview 4 front panel, using 30

Н

harmonic distortion measuring 53

improving frequency resolution and accuracy 49 instruction manual 10 instrument messages 169 Int Preamp 102 ISM1-A 10

L

Limits 162

М

Marker key 116 Marker Table 119 Meas key 121 measuring ACP 125 channel power 121 distortion 53 low-level signal 44 multiple signals 34 occupied BW 123 SEM 126 source? frequency drift 51 TOI 56 menu maps 183 messages 17 MODE key 132

Ν

Next Peak 150

0

occupied BW 123 Offset/Limits 127 options enable 24 order list 12

Ρ

Peak Search key 150 power cord 14 power requirements 14 Preset/System key 153 Pwr on/Preset 153

R

rack mount 19 Ref level 102 Rel Start 130 Rel Stop 130 requirements ventilation 18 Res BW 106 resolving signals equal amplitude 38 hidden by large signals 41

S

Scale/Div 102 Search Criteria 152 Show System 154 SPAN key 156 spectrum emission mask 126 Start Freq 113 Stop Freq 114 symbols 10

Т

TOI measuring 56 tracking drifting signals 51

Index



U

Uncoupled, definition 47 using frequency counter 49

V

VBW/RBW 106 ventilation 18 Video BW 106 View/Trace key 165 viewing signal 32

W

WEEE 10

This information is subject to change without notice. © Keysight Technologies 2012-2021 Edition 4, August 2021



N9322-90002 www.keysight.com

