

Ver.3.10



VERSION

NL5 User's Manual version 3.10.35, 09/10/2023 The latest versions of NL5 documents can be found at <u>sidelinesoft.com/nl5</u>.

LIMITED LIABILITY

NL5, together will all accompanying materials, is provided on a "as is" basis, without warranty of any kind. The author makes no warranty, either expressed, implied, or stationary, including but not limited to any implied warranties of merchantability or fitness for any purpose. In no event will the author be liable to anyone for direct, incidental or consequential damages or losses arising from use or inability to use NL5.

COPYRIGHTS

© 2023, A.Smirnov. The program and User's Manual are copyrighted. No portion of this Manual can be translated or reproduced for commercial purpose without the express written permission from the copyright holder. On publication of results obtained from use of NL5 citation is appreciated.

[&]quot;Smith" is a registered trademark of Analog Instruments Company, New Providence, NJ. Microsoft, Windows, and Microsoft Visual C++ are registered trademarks of Microsoft Corporation. MATLAB is a registered trademark of The MathWorks, Inc. PYTHON is a registered trademark of the Python Software Foundation. National Instruments is a registered trademark of National Instruments Corporation. Built with Indy (www.indyproject.com). Verilog is a registered trademark of Cadence Design Systems. Xilinx and Vivado are registered trademarks of Xilinx.

Table of Contents

I. Introduction	6
Install and run NL5	7
NL5 License	7
NL5 file types	
NL5 Help	
NL5 preferences	
NL5 DLL	
Create and Simulate Your First Schematic	
II. User Interface	
Application	
Navigation bar	
Settings window	
Context menus	
Shortcuts	
Mouse	
Image Copy, Save, and Print	
Data format	
Numbers	
Names	
Operators	
Functions	
Expressions	
C language	
Script	
Script syntax	
Script commands	
III. Schematic	
Edit schematic	35
Cursor	
Wire	
Ground	
Connection	
Component	
Label	
Drawing	
Text	

Variables	
Zoom and scrolling	
Selection	
General commands and shortcuts	
Open and save schematic	
Open	
Save	
Components	
Working with special component types and models	
Subcircuit model	
PWL model	
List model (voltage and current source)	
List model (switch and logic generator)	
Table model	
2D Table model	
C-code component	
DLL component	
Roots model	6
Attachments	
NL5 components (*.nlc)	
Customized component	
Encrypted component	
Schematic variables	
Schematic settings	
Schematic sheets	
Schematic groups	
Check schematic	
Schematic tools	
V. Transient	
Algorithm	
Running transient	
Transient window	
Status bar	
Cursors	
Labels	
Legend	
Annotations	
Text	
Table	
Storage	
Transient settings	
Simulation	

Add traces	
Format traces	
Screen	
Cursors	
Table	
Storage	
More commands	107
Transient Tools	
XY diagram	
Eye diagram	
Amplitude histogram	
FFT	
Transient histogram	
Power	
DC sweep	
V. AC analysis	
Algorithm	
Running AC analysis	
AC window	
Status bar	
Cursors	
Legend	
Annotations	
Text	
Table	
Storage	
AC settings	
Simulation	
Add traces	
Format traces	
Screen	
Cursors	
Table	
Storage	
More commands	
AC Tools	
Smith chart	
Nyquist plot	
AC histogram	
VI. Tools	
Script	160
Console	

Sweep	
Optimization	
HTTP link	
NL5-MATLAB link example	
Scope	
Working with oscilloscope	
Working with waveform generator	
Working with segmented memory	

I. Introduction

Install and run NL5

The only file required for NL5 operation is executable nl5.exe. You can place nl5.exe into any directory. There could be several copies of nl5.exe in different directories on one computer.

It is recommended to run nl5.exe with administrator privileges, to have full access to the **Registry**. To set up administrator mode, right-click on the NL5 icon, select **Properties**, select **Compatibility** tab, check **Run this program as an administrator**.

The following switches and parameters can be used.

Switches:

-http or /http	: start HTTP link
-scope Or /scope	: open Scope tool window

Parameters:

>nl5.exe rc.nl5	: open schematic rc.nl5
>nl5.exe rc.nlt	: load transient data from rc.nlt
>nl5.exe rc.nlf	: load AC data from rc.nlf
>nl5.exe pref.nlp	: load preferences from pref.nlp
>nl5.exe script.txt	: open and run script from script.txt

NL5 License

Without a license, NL5 operates as a **Demo version**. Demo version has all full function features available, however the total number of components in the schematic is limited to **20**. As an exception, NL5 Demo version can simulate demo schematic with an unlimited number of components, if that schematic was created with a special License option. Ask for that option if you want to distribute big schematic files to someone who does not have a license.

Different types of NL5 License are available at NL5 website. The License file nl5.nll ¹ should be placed in the same directory as an executable file nl5.exe.

NL5 License also supports NL5 DLL.

Use NL5 lite for simulation with unlimited components without a license.

NL5 file types

Extension	Description	
nl5	Schematic	
nl5~	Schematic backup	
nlp	Preferences	
nlc	NL5 component	
nlt	Transient data (binary)	
nlf	AC data (binary)	
nll	License	

The following file extensions are used by NL5:

Information about NL5 file types and icons is stored in the registry. Please run NL5 as administrator to be able to modify that information.

NL5 Help

NL5 help file n15.chm is not required, but if used, it should be placed in the same directory as n15.exe. The file contains only reference information, such as description of operators, functions, commands, components, and models. For detailed information refer to the NL5 User's Manual and NL5 User's Reference.

For context Help, press **F1**, or click **Help** button *some*, which is available in some windows.

If you cannot see content of Help file, most likely the file is blocked. To unblock:

- Locate nl5.chm file in the NL5 directory.
- Right-click the file, then click Properties.
- Select General tab.
- Click Unblock.
- If **Unblock** button is not visible, delete nl5.chm file from the directory, copy it to NL5 directory again from nl5.zip download package, and repeat this procedure.

NL5 preferences

Preferences are stored in the file nl5.nlp, typically located in the same directory as nl5.exe. NL5 reads preferences from the file at start-up and saves into the file every time **Apply** or **OK** button in the **Preferences** window, and on exit.

Please note that if nl5.exe is located anywhere inside C:\Program Files directory, it may not be able to save preferences file nl5.nlp due to writing restrictions. In this case, the preferences file will be saved in the C:\Users\user_name\Documents\nl5 directory (or similar directory, depending on specific OS).

Preferences can also be saved in a custom preferences file (extension nlp), and then opened back from the file, so you can have different "profiles", and switch between them quickly.

To open **Preferences** window click **A** in the Main menu, or in some pop-up context menus.

Some useful **Preferences** settings:

Application/Library.

Library path (subcircuits, DLLs, and other files): specify default directory paths list for files used by components. Click Edit , then enter library paths, one path per line, or click to select from folders list.

Edit Libraries	×
😂 🖬 💠 🗙	
C:\Projects\nl5 C:\Documents\nl5	^
	V
<	>
	OK Cancel


Library path could be full path, or path relative to the directory where schematic file is located. When new schematic is created, library paths specified in Preferences will be copied into the schematic library list. To modify library paths list of a specific schematic, go to **Schematic settings**

👫 , **Library** tab.

Default directory for saved components: specify default directory path for components saved into *.nlc file. Enter manually or click **Select directory** is to select from folders list.

Document/Graphs/Legend.

Legend style. Select **Ver.2** or **Ver.3** to set old legend view as in NL5 Ver.2, or a new NL5 Ver.3 view:



After general legend view is selected, its specific features can be manually changed by selecting desired options.

NL5 DLL

NL5 DLL is a dynamic-linked library available for **Windows** (n15_d11.d11), **Linux** (n15_d11.so), and **macOS** (n15_d11.dy1ib). It performs transient and AC simulation of circuits created by NL5 Circuit Simulator, provides raw simulation data, allows modification of circuit parameters, adding data traces, and some other operations through DLL API functions. NL5 DLL can be used as an analog simulator which is started and controlled from other applications and tools (MATLAB, Python, custom C/C++ code), and as an analog co-simulation tool working with digital simulation tools, for example SystemVerilog simulators (through DPI interface).

Currently released **Version** and **Revision** of NL5 DLL is always the same as Version and Revision of NL5 Circuit Simulator (for example 3.10). This guarantees full compatibility in terms of algorithm, components, models, features, and performance. However, there is nothing wrong in using different Versions/Revisions of DLL and NL5.

Current **Build** of DLL (for example 3.10.52.20) can be different from NL5, due to possible fixes and modifications specific to NL5 and DLL.

Without a license, NL5 DLL operates as a **Demo version**. Demo version has all full function features available, however the total number of components in the schematic is limited to **20**.

For unlimited number of components, NL5 DLL should use NL5 License.

Create and Simulate Your First Schematic


By default, a new schematic window should be opened automatically at start up. If not, click **New** toolbar button in the main NL5 window.

Enter schematic.

Entering and editing can be done using keyboard keys, mouse, or both. Here are step-by-step instructions how to enter a simple schematic using keyboard.


A red cursor is located in the middle of the screen and is pointing to the right.

- Press **Space** to switch to drawing mode.
- Press Arrow Down several times to draw short wire downward.
- Press V key and then press Enter to place a voltage source.
- Press G key to place a ground. Now cursor is switched back to selection mode.
- Press Arrow Up several times to move cursor back to the starting point.
- Press Arrow Right to change direction; then press Space to switch to drawing mode.
- Press Arrow Right several times to draw a short horizontal wire.
- Press **R** key and then press **Enter** to place a resistor.
- Press Arrow Right several times again; then press Arrow Down several times.
- Press C key and then press Enter to place a capacitor.
- Press **G** key to place a ground. Schematic is ready.



Edit component parameters.

- Double click on the voltage source **V1** on the schematic. A **Components** window will show up.
- Click on **V1** in the components list. Click right to the model name (top-right), select **Pulse**.
- Click on the resistor **R1**, enter 1 in the parameter field **R**.
- Click on the capacitor C1, enter 1 in the parameter field C.



View transient settings.

Click **Transient settings** in the schematic window toolbar, select **Simulation** to go to **Settings** window, **Simulation** tab. You do not need to change anything here, but you can, if you wish.

Add transient traces.

ſIJ

T

10

1e-3

States

T nl1 - Settings - Transient

Start display when:
Bause simulation when:

 $|\uparrow| + | = \times | \Rightarrow |$

😅 📰 | 📴 🛅 | 🖻 🛍 🐄 | 🗕 🗙 | 🛧 🖊 👯

↔

Apply

🖾 🗄 ۹P 🎞 🗉

Start. s

Screen, s


Step, s

Select Add traces tab 🐤, select V in the left window, then double-click on V1 and C1 in the components list. Voltage traces will be added to the trace list.

Check all Select all


Check traces to be shown on the graph


 \times



Click **Start transient** ➡ to run simulation:

T Advanced settings...






View and edit AC settings.

Click **AC settings** in the schematic window toolbar, select **Simulation** to go to **Settings** window, **Simulation** tab. Click on the **AC source** drop-down list, select **V1**.

Add AC traces.

Select Add traces tab , select V in the left window, then double-click on C1 in the components list. AC voltage trace will be added to the traces list.



Run AC.

Click **Start AC** to run AC simulation:




II. User Interface


Application

NL5 is using standard Windows multiple-document interface (**MDI**) with important and useful addition: **floating windows**.

All schematic-related windows (Schematic, Transient, AC, Transient and AC tools) are first created in "MDI child" mode, and are located inside the "main" window:



After that, any window can be switched to a "floating" mode and moved outside the "main" window (for example, to a different monitor), maximized to full screen, etc.:




To turn "floating" mode on/off, use **View/Floating window** main menu command, **Floating window** context pop-up menu command (**Right-click** on the window), or **Floating window** button on the right end of window top toolbar:



- Floating Schematic window.
- Floating Transient window.
- Floating AC window.
 - Floating Transient and AC tools.

Navigation bar

Navigation bar shows currently opened documents (schematics), with highlighted active document and window:



- Click on the document name to activate document.
- Click on the window icon to activate document and window.
- Right-click to see pop-up menu window with related commands.
- Click \times to close schematic.

Settings window

T nl1 - Settings - Tra	nsient	×
	Image: Start, s Start, s Screen, s Step, s	Check all Select all ▼ V(V1)
T Advanced setting	1 s Apply	Check traces to be shown on the graph

Settings window shows settings for Transient, AC, or Tool window. Settings window always shows information for active document (schematic). The name of active schematic is shown in the header of Settings window.

When **Transient**, **AC**, or **Tool** window is activated, **Setting window** will automatically show settings for that window. Also, you can click **Select settings** button (top left) and select any window from the list of currently available windows for active schematic:

1	-
-1	Transient
æ	XY diagram
\sim	AC
0	Smith chart

If some parameters in **Settings window** are modified, their background color will change to light-yellow:

0	Start, s
5m	Screen, s
10e-6	Step, s


Press Enter or click Apply to accept changes.

Settings window can always be opened.

Context menus

Almost everywhere, mouse right-click will open context pop-up menu window. The content of the context menu depends on many factors, such as current window, selection, position of mouse pointer, etc. If you are not sure how to perform specific operation, try right-click at the point/area of interest: desired command might be shown in the context menu.

For example, right click on the DLL component shows all commands that can be applied to that component:



Please note that there could be minor changes in context menu content and arrangement in different NL5 builds.

Shortcuts

- F1 Help (context help on a specific window, selected component, C function, etc.).
- F2 show Schematic window.
- **F3** show Components window.
- F4 show Variables window.
- F5 show Transient window.
- F6 start transient.
- $\mathbf{F7}$ continue transient.
- F8 show AC window.
- **F9** start AC analysis.
- F10 show Settings window.

Mouse

Most mouse and mouse wheel operations are similar in Schematic, Transient, AC, and Tool windows.

Some options of mouse wheel operation can be changed in **Preferences/Document/Schematic/Mouse**, and **Preferences/Document/Graphs/Mouse**.

Image Copy, Save, and Print

Right-click on Schematic, Transient, AC, or Tool window, select Image in the context menu:

lmage 🔹 🕨	₿ <mark>`</mark>	Copy to clipboard
	BMP	Save as BMP
	JPG	Save as JPG
	PNG	Save as PNG
	9	Print
	Image 🔸	BMP JPG PNG

Copy to clipboard or **Save** image into the file in any of 3 available formats (**PNG** format is suggested). **Print** image, or save as PDF, if available.

Preview window will show up:

🔛 Print - Preview		_	
Options Black and white Frame	Printer Microsoft Print to PDF	Setup	Print Close

Select **Options**:

- Black and white,
- **Frame** (Schematic window only).

For printing, select **Printer** from the drop-down list, or click **Setup...** for printer setup.

Click Copy/Save/Print button to proceed.

Image Copy/Save operations are also available for other windows, such as **PWL** window, **Roots** window, and more.

Data format

Data format used in NL5 mostly complies with common engineering and scientific practice.

Numbers

Boolean number can be entered as false or true (case-insensitive):

```
bool i = true;
bool retvalue = FALSE;
```

When converted to other types, true is considered as 1, false as 0. When other types are converted to bool, non-zero value is considered as true, zero value as false.

Integer (int, int64) number can be entered in decimal, binary, octal, or hexadecimal formats.

```
Binary: use 'Ob' or 'OB' prefix, then use digits 0 and 1: 0b11111111, 0B10101010, 0b10
```

Octal: start number with prefix 0 (zero), then use digits 0...7: 0377, 0123456

Hexadecimal: use '0x' or '0X' prefix. Then use 0...9, and capital or low-case A, B, C, D, E, F: 0xFF, 0X10aa, 0x10000

If a value of a number exceeds 32-bit range, it will be automatically converted to int64 type. Use i64 suffix to explicitly define 64-bit integer:

0i64, 0xffffffi64

Floating point (float, double) number can use exponential multipliers **E** or **e**, or **case-sensitive** letter multipliers:

Letter	Multiplier
Т	10 ¹²
G	109
М	10 ⁶
k, K	10 ³
m	10 ⁻³ 10 ⁻⁶
u	10-6
n	10 ⁻⁹ 10 ⁻¹²
p	10 ⁻¹²
f	10 ⁻¹⁵

For example:

1.3e+3, 47E-9, 100k, 0.33u

Letter multiplier can be used instead of a decimal point. Zero before decimal point or letter multiplier can be omitted:

1k3, .47, n47

Infinite value is denoted by:

inf

Complex number consists of real and imaginary parts of floating point type. Imaginary part of a complex number has **lower case** letter 'j' at the end of a number. Letter 'j' cannot be used alone, only as a suffix:

```
50+45j
1+1e-3j = 1+.001j
30j
1+j : wrong! Correct format: 1+1j
```

The following predefined constants (case-insensitive) can be used:

```
PI = Pi = pi = 3.14159265359
RAD = Rad = rad = 180/pi = 57.2957795131
LOW = Low = low : low logical level
HIGH = High = high : high logical level
```

Constant RAD can be used to convert degrees to radians and radians to degrees:

degrees = radians * RAD
radians = degrees / RAD

where degrees is value in degrees, and radians is value in radians.

All numerical component parameters, and most of other parameters in NL5 are floating point (double). Those parameters can be entered in any format, however after that they are automatically converted and stored in the floating point format.

When floating point number is displayed, an engineering notation, with exponential multiplier and power of ten to be multiple of three, is used:

Entered	Displayed
1k3	1.3e+3
47e-8	470e-9
5600000	5.6e+6

Names

Component. When a new component is created, it is assigned a default name: 'letter' plus number:

R1 V2

Then the component can be renamed. The name is case-insensitive and may contain any (almost) characters and symbols. However, to be used in formulas, functions, C-code, etc. it should satisfy C-language standard for the variable name: start with letter or '_', and then contain only letters, digits, and '_'.

If the component has been renamed, its name will be automatically modified in all appearances of the component name in trace names, formulas, and functions.

To access component's parameter in the formula, function, or script expression, use component name followed by dot '.' and parameter name:

R1.R V2.slope C123.IC

If parameter name is not specified, a first parameter of the component will be used:

R1 = R1.RC2 = C2.C

If current component model does not have parameters, a component model name will be used:

A1 = Amperemeter

To access component, which is part of the subcircuit, use subcircuit component name followed by dot '.' and component name in the subcircuit. A nesting level is unlimited: components inside subcircuit, which in turn is part of subcircuit, can be accesses by similar notation:

X1.X2.V3.period

where x1 and x2 are subcircuits.

To access global variable of the C model of Code component x_1 (in a script or command-line) use the following notation:

```
X1.variable_name
```

To access component's model name (in a script or command-line) use component name followed by dot '.' and "model":

V1.model = pulse

If current component model does not have parameters, ".model" can be omitted:

S1 = Off

Schematic variable. Schematic variable (a variable defined in the **Variables window**) name has the same format as a component, except it does not have parameters. For example:

Freq X1.var

Trace. The basic name of transient or AC trace consists of the letter specifying type of the trace (\forall, \exists, P, S) , followed by component's name in parentheses:

V(R1) I(C2) P(L3)

The trace can be renamed to an arbitrary text:

Copy of V(R1) new trace V pulse

To be used in formulas and expressions, trace name should satisfy C-language standard for the variable name: start with letter or '_', and then contain only letters, digits, and '_'.

Trace and cursors data. Trace and cursors data shown in the transient or AC table (value at cursor, min, max, mean, etc.) and trace value at specified time can be used in the script expressions (for example, logdata command). Please note that to access trace data from Console, Script, and HTTP link, the trace must exist, although it does not need to be shown on the graph or in the table. Left and right are values specified as table "Interval" in the **Settings/Table** window: **Cursors, Screen, All data**, or **Selection**.

To access data, use the following notation:

•	Cursors	(screen)
---	---------	----------

left	 left interval value.
right	 right interval value.
delta	=right-left

• Transient

V(R1).(1.2)	- value at t=1.2
V(R1).left	– value at "left".
V(R1).right Or V(R1) – value at "right".
V(R1).delta	-V(R1).right-V(R1).left.
V(R1).min	– min.
V(R1).max	– max.
V(R1).pp	– peak-to-peak (max – min).
V(R1).mean	– mean (average).
V(R1).rms	– rms.
V(R1).sd	- standard deviation (rms of the signal with subtracted mean value).
V(R1).freq	– frequency.
V(R1).period	– period.
V(R1).integral	– integral.

• AC magnitude

V(R1).(1.2)	– value at f=1.2
V(R1).left	– value at "left".
V(R1).right	or $V(R1)$ – value at "right".
V(R1).delta	- V(R1).right - V(R1).left.
V(R1).min	– min.
V(R1).max	$-\max$.
V(R1).pp	– peak-to-peak (max – min).
V(R1).slope	- slope of the gain, dB/dec.

• AC phase

```
V(R1).phase.(1.2) - phase value at f=1.2
V(R1).phase.left - phase left.
V(R1).phase.right - phase right.
V(R1).phase.delta - phase delta.
V(R1).phase.min - phase min.
V(R1).phase.max - phase max.
V(R1).phase.pp - phase peak-to-peak (max - min).
```

If storage data exists, trace data are taken from selected current Run or storage.

To access trace data, trace name should satisfy C-language standard for the variable name: start with letter or '_', and then contain only letters, digits, and '_'. If the original trace name does not satisfy this requirement, please specify a custom trace name at **Transient/Settings/Format traces** or **AC/Settings/Format traces** page, and then use it in expressions.

Operators

NL5 supports the following arithmetic and logical operators:

	++		+	-	*	/	olo
	!	~	<<	>>	&	^	
	<	<=	>	>=	==	! =	
	& &		?:				
	+=	-=	*=	/=	%=		
	=3	^=	=	<<=	>>=		
and type-cas	ting operate	ors:					
	(bool)	(int)	(int64)	(float)	(double)	(cc	omplex)

See NL5 User's Reference for details.

Functions

NL5 offers many standard and NL5-specific functions. The functions can be used in the C code (script, Code component), traces of **Function** type, and in **Function** model of some components.

For the convenience of users, there may be several names used for the same function (for example log10 and lg), so that the user can use the name he/she is more comfortable with. The following functions are available:

sin cos	sqrt sqr	mag, abs phase	par random, rand	sum mean
tan, tq	sq	re	qauss	max
asin	-	im	limit, lim	min
asin	pow	±111		111 - 11
acos	pwr	sign	islow	bool
atan	exp	round	ishigh	int
atan2	ln, log	floor	db	int64
	lg, log10	ceil		float
	lb, log2			double
				complex

Please note that argument of functions **sin**, **cos**, **tan**, **tg** is in radians, not degrees. Similarly, functions **asin**, **acos**, **atan**, **phase** return radians, not degrees. This is different from NL5 Ver.2.

See NL5 User's Reference for details.

Expressions

Expression may consist of:

- Numbers.
- Predefined constants.
- Names of components, parameters and variables.
- Local script or C-code variables.
- Operators.
- Functions.
- Parentheses with unlimited nesting level.

For example:

```
2*2
2<<3
sin(2*PI*f) // "f" is schematic variable.
max(R1,R2,R3)
1/((R1+R2)*C1)
```

Expression can be used instead of number in most entry fields in the dialog boxes, and for some component parameters. When **Enter** key is pressed, or **OK** or **Apply** button (if exists) is clicked, the expression is immediately evaluated and replaced with the numerical value.

Please note that division of two integer values will produce rounded integer result according to C-language rules **only** in expressions used in C-code component and script. In all other places, integer values will be considered as double values, and a result will be of double type. This is similar to how calculations are performed in the calculators, Excel spreadsheets, etc. For example:

1/100 = 0.01 (will be 0 in C-code) 5/2 = 2.5 (will be 2 in C-code)

C language

Simplified C language interpreter is implemented in the NL5. It is used in the **script** and in the **C-code** component.

The following data types are supported:

bool - boolean (true/false).
int - 32-bit signed integer.
int64 - 64-bit signed integer.
float - same as double.
double - 8-byte floating point.
complex - consists of double real and imaginary parts.

Only one-dimensional arrays are supported.

The following C keywords, statements, and operators are available:

bool	if…else	continue
int	for	break
int64	while	return
float	do…while	
double	switch	
complex	case	
	default	

The following C language features are currently **not** implemented in NL5:

- Preprocessor (#define, #include)
- Structures and unions.
- Pointers and references.
- goto statement.

Please refer to publicly available resources for general C language syntax description and reference.

Script

Script is a program which allows automating simulation process. By using script, you can open/close schematic files, modify component parameters, run simulation, analyze the data, save/export simulation results, etc.

Script can be executed from NL5 command line, or at **Script** tab of **Tools** window. Script commands can also be executed from command line in the **Console** tab of **Tools** window, and through **HTTP link** from external applications. This allows using NL5 as an "add-on" simulation engine with popular engineering tools such as MATLAB®, Python, and others.

Script syntax

Script is written on C language and is executed by C language interpreter built in NL5. All C operators and functions can be used in the script. In addition, NL5-specific script commands can be used to run simulation, analyze data, and save simulation results. See **NL5 User's Reference** for details.

Component parameters and schematic variables can be used in expressions and can be modified similar to C variables:

```
R1 = tau / C1;
freq = 1. / V1.period; // "freq" is schematic variable
```

Trace and cursors data can be used in expressions. The data correspond to the values configured in the Transient or AC Data table. In order to use trace data, the trace should be added into the Transient or AC data, but does not need to be displayed on the graph or in the data table. For example:

```
x = V(out).max - V(out).min;
if( V(C1).(3.45) > threshold ) break;
charge = I(C1).mean * delta;
```

Script commands

Script commands are used to open schematic, control simulation process (run and continue simulation), and save simulation data in different formats. The following general script commands are available:

ac	exit	return	sleep
clear	export	rununtil	stop
close	import	save	store
cmd	logdata	savedata	storetext
cont	open	saveic	traces
cursors	pause	show	tracename
display	ready	silent	tran

Script commands related to Scope tool:

scope.cmd	scope.off	scope.select
scope.get	scope.on	scope.single
scope.getn	scope.read	scope.status
scope.image	scope.refresh	scope.stop
scope.log	scope.run	scope.update

Please note that unlike standard C function calls, script commands parameters do not need to be enclosed into parentheses. However, for consistency of the code, parentheses can be used as well. For example:

```
open(rc.nl5);
open rc.nl5;
tran(0, 1, 1m);
close();
clear;
```

See NL5 User's Reference for details.

III. Schematic

Edit schematic

₽	nl1	- Sc	hem	atic (r	mod	dified)																-			×
	7	망	Ъ	8	V	<u>.</u>	Պ	1	+ 1	•	4 14	• •)	ξ	∾	T	- =	> ₩		B %		×	ŝ	$\bigcirc $	£ Þ	h riþ
4	+	Ą	abc ®	É	3	<u>•</u> @-	-11	⊢ :	1t	14	-17-		-14-	-13	₫	43	×	**	-9-	<u>-9</u> -	-R- 	-D		- \$	∢
	All	Α	С	D	F	1	L	0	R	S	Т	۷	W	Х	Y	Z									
																								^	₩ 2
•													R1			out									
•													\sim	•	C										() €
													1												đ
										(ŧ	yı Pu	(A(Ilse)			•	C1 1								- - - -
•																									
•																									
•				•									•				•	•						~	
_	neet1	Γ	_		_			_	_		-	Cli	ck to	start	sele	ction									

Cursor



- **Double-click** set cursor at that point and center it on the screen.
- Left, Up, Right, Down change cursor direction, move cursor.
- Click on the cursor close to the cursor corner to change cursor direction.
- Home center cursor on the screen.

Wire



- Press **Space** or click **Wire** to switch to **Wire** mode.
- **Click** and drag to draw wire.
- Left, Up, Right, Down change cursor direction, draw wire.
- Press and hold **Ctrl** to draw diagonal wire.
- Press **Space** or **ESC** to switch back to **Selection** mode.

Ground



- Press **G** or click $\stackrel{\perp}{\checkmark}$ on the **Components bar**.

Connection



- Press '.' (dot) or click + on the **Components bar**.

Three wires coming to one point are connected automatically: a connection point will be automatically added during schematic check. Two crossing wires are not connected by default and should be connected manually. All unnecessary connection points will be automatically removed during schematic check. **Warning**: diagonal wire cannot be connected to the wires it is crossing.

Component



- Select tab with component letter on the **Components bar**, click on the component. **OR**
- Press component letter key (for example 'R') one or more time to select required component.
- Move component by keyboard/mouse, rotate, mirror, flip, select view if needed.
- **Right-click** on the component to see context menu, or use toolbar buttons or shortcuts to do the following:
 - or **Ctrl-L** rotate component left.
 - or **Ctrl-R** rotate component right.
 - or **Ctrl-M** mirror component.
 - flip component.
 - t or +/- key show next component view (if applicable).
- Press Enter to place component or press Del or ESC to cancel.


When component is placed, click on the component to select it, then use the following ways to access component editing commands:

- toolbar buttons,
- keyboard shortcuts,
- Main menu/Edit, Main menu/Edit/Selection,
- **Right-click** on the component to see pop-up context menu.


The following component editing commands are available:

- set component at 45 degrees (available for some R, L, C, S, and D components).
- or **Ctrl-T** rotate attribute of selected component.
- $\uparrow \downarrow$ or +/- key show next component view (if applicable).
- **Ctrl-L** rotate component left.
- or **Ctrl-R** rotate component right.
- or **Ctrl-M** mirror component.
- Gr Ctrl-F flip component.
- to or +/- key show next component view (if applicable).
- **Component** $\stackrel{\text{\tiny{bh}}}{\mapsto}$: more component related commands.
- Add trace 📅 : add trace for the component.
- **Double-click** on the component to edit component parameters in the **Components window**. Then, if you finish editing parameters by pressing **Enter** or **Esc**, you will switch back to the schematic.

When component is placed above existing wire, a piece of the wire underneath the component is automatically removed, so that no editing of the wire is required:



Similarly, when component is moved/copied above existing wire, a piece of the wire underneath the component will be automatically removed:




Label



- Press Enter or click $\stackrel{abc}{\otimes}$ on the Components bar.
- For new label, enter label Name and Description (optional), click OK.
- For existing label, enter label Name or select from the list of existing labels, click OK.
- **Double-click** to edit label parameters in the **Components window**.
- **Right-click** on the label to see relevant commands. Some useful commands:
 - **Component** + : more label related commands.
 - Add trace 📅 : add trace for the label.

Drawing



- Click Line . , Rectangle , or Oval o to switch to drawing mode.
- **Click** and drag to draw.
- Press and hold **Ctrl** to draw square, circle, or line in the direction multiple of 45 degrees.
- **Double-click** or **Right-click/Format** to format drawing.

Text

This is text

- **Right-click/Insert text** to add text to the schematic.
- **Double-click** to edit and format.

Variables



- **Right-click/Insert variables** to show schematic variables and their values on the schematic. The list is automatically updated when variables or their values change.

Zoom and scrolling

- Click to switch to **Scrolling** mode, then click and drag to scroll the screen. **OR**
- Press and hold **Shift**, then click and drag to scroll the screen.
- Shift-Left, Shift-Up, Shift-Right, Shift-Down scroll the screen.
- **Ctrl-mouse wheel** scroll horizontally.
- Shift- mouse wheel scroll vertically.
- • or **PgUp -** zoom-in.
- *Q* or **PgDo** zoom out.
- **D** or **Ctrl-Home** fit all schematic to the screen.
- **Shift-Home** fit selection to the screen.
- **Mouse-wheel** zoom in/out.

Selection

- **Click** on the schematic element to select.
- Point on empty space, **click** and drag to select a block (rectangle).
- Press and hold **Ctrl** while selecting add to existing selection.
- **Ctrl-A** select all schematic.
- **Right-click/Select net -** selects all wires connected to the selection either directly, or through labels (including other sheets).
- Click on empty space or press Esc to unselect (press Esc twice to unselect a block).
- Left, Up, Right, Down move selected block.
- **Click** and drag to move element or selection.
- Click and drag to move attribute of selected component.
- Shift + Click and drag to move element or selection with rubber bands.
- Ctrl + Click and drag to copy element or selection.
- **Ctrl** + **Shift** + **Click** and drag to copy element or selection with **rubber bands**.
- **Right-click/Format** to format selection.
- Right-click/Disable or Ctrl-D to disable selection.
- **Right-click/Enable** or **Ctrl-E** to enable selection.

Disabled schematic elements are shown in "disabled" color and are not used for simulation. Disabling elements allows temporary exclude elements from simulation without deleting.

- **b** or **Ctrl-C** copy selection.
- $\overset{\bigstar}{\mathbf{b}}$ or **Ctrl-X** cut selection.

- or Ctrl-V paste selection.
 or Del delete selection. _
- _
- or **Ctrl-L** rotate selection left. _
- \frown or **Ctrl-R** rotate selection right. _
- or **Ctrl-M** mirror selection. _
- or **Ctrl-F** flip selection.

General commands and shortcuts

- Click to show/hide **Components bar**, resize the bar by mouse if needed. Press **Tab** to change attributes display for all components. _
- _
- **Right-click** to open context menu. Some useful commands: _
 - **Component** → access component/label related commands. **Add trace** → add trace for the component/label. _

 - **Image** copy schematic image to clipboard or save into the file. _
- or Ctrl-Z Undo.
- or Ctrl-Y Redo.

Open and save schematic

Open

When **Open** Schematic of a special type, some actions may be required.

Encrypted schematic. When opening encrypted schematic, a password should be entered. Please be aware that for security purposes it is impossible to open (decrypt) such a schematic without password.

Ver.2 schematic. When schematic with old Ver.2 format s opened, it is automatically converted to a new Ver.3 format, and then the window with conversion notes shows up. When saved, this converted schematic will be saved in a new Ver.3 format and cannot be opened by NL5 Ver.2 anymore.

Save

Save 🖬 and Save As are standard saving commands.

Save As Encrypted. Enter password and save encrypted schematic. Please be aware that for security purposes it is impossible to open (decrypt) such a schematic without password.

To save schematic with transient/AC data or script text, select saving options in the Schematic settings

\$, Save options tab.

Components

All available components are shown in the Components bar:

Click 🕮 to show/hide **Component bar**. Resize the bar hight by mouse if needed.

Each **component** has a letter associated with it. When a new component is placed, its default **name** consists of a letter and number. The name can be changed to arbitrary text, however, to be used in formulas, it should satisfy C-language standard for the variable name (start with letter or '_', then consist of letters, digits, or '_').

Label is a special type of component: there can be many labels with the same name in the schematic. All labels with the same name are electrically connected. Labels in the subcircuit are local to the subcircuit and are not connected with labels of the same name in the main schematic or other subcircuits.


Labels can be used:

- To connect different points of the schematic without wire.
- To connect parts of the schematic located on different sheets.
- As a simulation probe (V trace).
- As a voltage source.

Symbol. Most of component have just one symbol associated with it, which cannot be changed. Some components may have several **views**, when the symbol is modified depending on different pin locations (for example, location of positive/negative input pins), and different functionality (for example, inversion of logical signals). For logical gates, changing **view** may also be used to change gate logical function (AND, OR, XOR).

Select component and click \uparrow to change a view, or press '+'/'-' keys to go through all applicable combinations of view \uparrow , mirror \downarrow , and flip \blacklozenge .

Also, some components may have different symbols for different component **model** or component parameters. For example, symbol of the **Function** component indicates functionality of a selected model, and symbol of the **Switch** component indicates switch position in non-active state:



Model. Component **model** defines specific component functionality. For example, voltage source models include **Pulse**, **Sin**, **Step**, **File**, and more. Select component model in the drop-down list above parameters.

Parameters. Component parameters may be of different type: floating point, text, etc. Floating point parameter can be entered as an expression, for example:


R1.R*2.5

Such an expression will be immediately calculated and replaced by a resulting value.

Formula. Floating point parameter can be entered as a formula if started with '=' symbol:

=R1.R*2.5

Enter formula and press **Enter**, the formula will be calculated immediately. Then it will be recalculated automatically when required. The parameter entered as formula will have subtraction button on the right. Click the button to see and edit formula expression:



If formula expression and cannot be evaluated, #VAL text will be displayed instead of a number. Erase the formula to leave its last value as a constant.

Some parameters of floating point type may be **blank**, which means the value is not defined. For example, blank **IC** (initial condition) parameter of capacitor means that its initial voltage at t=0 is not defined and will be determined during DC operating point calculation.

Function. Some component parameters represent a **function**. Function is an expression which is recalculated at every transient or AC calculation step. Function can use the following variables:

t – current transient time, s. f – current AC frequency, Hz. w – angular AC frequency, $w = 2\pi f$. s or p – Laplace parameter, $s = p = j^* 2\pi f$. x, y – input signals for Function model. V(name) – voltage on the component *name*. V trace should be available for the component. l(name) – current on the component *name*. I trace should be available for the component. P(name) – power on the component *name*. P trace should be available for the component.

For example:

```
sin(t*1000)*(1+cos(t*10))
(t%2>1)?1:-1
sq(V(r1))/r1
1/(1+s*R1*C1)
```

Blank parameter. Some parameters of floating point type may be **blank** (empty), which means the value is not defined. For example, blank **IC** (initial condition) parameter of capacitor means that its initial voltage at t=0 is not defined and will be determined during DC operating point calculation.

Logical levels and threshold for all components are defined in the Schematic settings **Components** tab.

Attributes. There are 2 attributes of the component that can be displayed on the schematic: Name and Value.

Name is automatically assigned to the component when it is placed and can be changed later. Also, an arbitrary text, **Description**, can also be added and displayed along with the **Name**. To edit component

Name and Description, click Rename in on the Components window toolbar.

Value content depends on the component type. By default, it is the first parameter of the model, model name, or empty. It can be customized to display any of component parameters in different format, formula expression, etc.

Press Tab to toggle attributes display mode for all components in the schematic:

- Name only
- Name and Value
- Value only
- No attributes

To move attributes, select component first, then click and drag the attribute.

To format attributes of specific component, **right-click** on the component, select **Format**, then select **Attributes** tab.

Component model and parameters can be selected and edited in the **Components windows**:

▶ rc - Components ×						
ib 🔁	Хĭ	\mathbb{R}	Х	r 🖸)	🛱 🕂 🛱 📽 🔟 🔳 👔
Name	Value			V1		Pulse 🔻
C1	1			V1	V	10
R1	1			VO		0
V1 (AC)	Pulse			<u> </u>	Y	-
out				Period	S	400e-3
				Width	s	200e-3
				Slope		Linear 👻
				Rise	s	0
				Fall	s	0
				Delay	s	0
						•

Double-click on the component or press **F3** to open or switch to the **Components window**. If **double-click** on the component in the schematic window was used, edit parameter and press **Enter** to switch back to schematic window.

Operations available for selected component are available on the toolbar.


Click **Find component** to find select component on the schematic. The component symbol will be selected and centered on the screen. For **label**, click again to see the next label with this name at all schematic sheets.

Working with special component types and models

Subcircuit model

Subcircuit model (**SubCir**) allows creating simple and readable schematic by substituting some part of the schematic with one component (symbol). When simulation starts, the component with **SubCir** model is replaced by actual schematic loaded from subcircuit file.


SubCir model is available almost for all components, so that some simple symbol can in fact represent quite complex circuit. For example, **switch** component with **SubCir** model may represent a complex circuit with additional resistors and parasitics:




Several X components: **Block-2**, **Block-3**, **Block-4**, **Block-6**, and **Block-8** are offered to be used for subcircuit with fixed symbol and number of pins:

Block-2	Block-3	Block-4	Block-6	Block-8
(1) (2)	(1) (2)	(1) (3)	(1) (4)	(1) (5)
	· (3) ·	(2) (4)	(2) (5)	(2) (6)
			(3) (6)	(3) (7)
				(4) (8)

Component **X**, **Custom block** is a customized component. When placed on the schematic, it does not have any pins. **Right-click** on the component, select **Component** $\stackrel{\text{(b)}}{\longrightarrow}$, then **Edit component** $\stackrel{\text{(c)}}{\Longrightarrow}$ to open **Edit component** window:



NL5 circuit is a special component with **SubCir** model. It is a customized component as well, but in addition, names of labels connected to component pins are also defined in **Edit component** window. Them, pin names are shown on the component symbol:



SubCir model has the same parameters for all component types (except **NL5 circuit**, which does not have **Pin1...PinN** parameters):

Model	Parameter	Units	Description
SubCir	File		File name of subcircuit schematic.
Caben	Pin1		Name of subcircuit label connected to pin 1
	PinN		Name of subcircuit label connected to pin N
	Cmd		Subcircuit start-up command string
	IC		Subcircuit Initial conditions string

File is a file name of subcircuit schematic file. Enter file name manually or click it to select the file. File extension .nl5 can be omitted. If **File** does not have a full path, NL5 will search for the file in the following order:

- In the directory where schematic file is located.
- In the directories specified in the Library list (see Schematic settings chapter).

- In the directories specified in the Library list relative to the directory of schematic file.

Parameters **Pin1...PinN** define subcircuit labels connected to the pins. If label name is defined, it is displayed on the component image, otherwise a pin number in parentheses is displayed. Any of **PinN** parameters can be empty, which means that the pin is not connected to the circuit. To disable labels/pin

numbers display, **right-click** on the component, select **Format**, go to **Attributes** tab, unselect **Show subcircuit labels**.

Cmd is a string with comma-separated expressions in "name=value" format, which is executed when subcircuit is loaded. This allows using the same subcircuit file with modified values of different components. For example:

R1=1k,R2=12k,C1=5n

where R1, R2, and C1 are subcircuit components.

IC is a string similar to Cmd. It defines initial conditions of subcircuit components, for example:

C1.IC=10,02.IC=0

where c1 and o2 are subcircuit components. Unlike **Cmd**, **IC** parameter can be automatically modified by the following commands:

- Save initial conditions : fills in IC string with current IC's of all components in the subcircuit.
- Schematic tools X, Initial Condition tab, check box Clear subcircuits IC: clears IC string.

Subcircuit is always being loaded from the file when simulation starts, even if subcircuit is currently opened in the same NL5 instance. If subcircuit was modified, it should be saved into the file before next simulation start in order to changes take effect. If transient was paused, subcircuit modified, and then simulation continued, subcircuit will not be automatically loaded. Instead, if should be "reloaded"

manually: right-click on the component, select Component M, then Reload subcircuit 🚔 .

To access and modify subcircuit component parameters from command line, script, HTTP-link, and NL5 DLL functions, use X1.R2 notation, where X1 is component with **SubCir** model, and R2 is component inside the subcircuit. Please note that subcircuit component may be accessed only when simulation is started and then paused, so that subcircuit file is loaded into NL5.

Subcircuit can be **attached** to the component. Attached subcircuit becomes a part of the component, it will be saved into schematic file with the component, so that subcircuit file is not needed for simulation anymore. Attached subcircuit can be edited and saved back to the attachment, so that it will affect only component it is attached to. As a result, several components can use the same subcircuit, with modifications specific to that component. Also, subcircuit components may be accessed any time, even when simulation is not running.

PWL model

PWL (PieceWise Linear) model describes non-linear characteristic of the component with piecewise linear approximation.

Please note that **pwl** parameter of the **PWL** model typically specifies PWC (PieceWise Constant) function, which represents sensitivity (derivative) of PWL function. For instance, **pwl** parameter of a resistor specifies R(V), which is PWC function, while resistor I(V) characteristic is PWL function. The parameter is still called **pwl** (not **pwc**) for historical reasons.

The following table shows PWC (**pwl** parameter) and corresponding PWL functions for NL5 components:

Component	PWC	PWL
Resistor, diode, zener	R(V)	I(V)
Resistor	R(I)	V(I)
Capacitor	C(V)	Q(V)
Inductor	L(I)	H(I)
Voltage controlled voltage source, OpAmp	K(V)	V(V)
Current controlled voltage source	K(I)	V(I)
Voltage controlled current source	K(V)	I(V)
Current controlled current source	K(I)	I(I)

For voltage/current controlled linear components (R, C, L, and amplifier) **pwl** parameter is also PWC function, describing change of component main parameter (R, C, L, K) with control signal:

Component	PWC
Voltage controlled resistor	R(Vin)
Current controlled resistor	R(Iin)
Voltage controlled capacitor	C(Vin)
Current controlled capacitor	C(Iin)
Voltage controlled inductor	L(Vin)
Current controlled inductor	L(Iin)
Voltage controlled amplifier	K(Vin)
Current controlled amplifier	K(Iin)

PWL model of a resistor is described here as an example.

pwl parameter is a comma-separated string, describing PWC function:

R0,V1,R1,V2,R2,...,VN,RN

where:

R0 is resistance while voltage across the resistor is less than V1.

R1 is resistance while voltage across the resistor is between V1 and V2.


•••

RN is resistance while voltage across the resistor is greater than VN.

Values $v_{1...v_N}$ should be given in ascending order. Resulting PWL characteristic is calculated automatically, and always goes through the origin (0,0). Please note that only numbers can be used in **pwl** parameter: formulas are not allowed.


PWC function can be symmetrical or non-symmetrical. **Symmetrical** function is defined only in the interval from zero to plus infinity; the negative part of PWC function is symmetrical to positive one:

pwl = 1, 1, 2, 3, 5




Non-symmetrical function is defined from minus to plus infinity. One of the argument points must be **zero**: it serves as an indicator of non-symmetrical characteristic:

pwl = .5, -1, 1, 0, 1, 1, 2, 3, 5



To edit **pwl** parameter, select the parameter and click it to open **PWL** window:



Right-click on the graphs area to see context menu with relevant commands. The following tabs are available:

Table . Edit PWL data in the table.

 \rightarrow in the first column indicates selected row.

Select cell and edit the number: **From** value is updated automatically.


- $\underline{\mathbf{A}}$ symmetrical PWC. The first **From** value will be **zero**.
- **L** non-symmetrical PWC. The first **From** value will be **-inf**.
- split selected row.
- remove selected row.
- × clear all data.
- ✓ or **Enter** refresh graphs.

Add/remove *****. Add or remove points (rows) in the specified range.

Approximate f_x . Approximate arbitrary function.

$I(V) \sim f(x) = x/sqrt(1)$	+x*x]		
Approximate using existing points Automatic update	Approximate in the range	0 1 10 ~	From To Intervals

- Select PWL parameter or characteristic from drop-down list. For instance, select R(V) or I(V) for resistor.
- Enter $\mathbf{f}(\mathbf{x})$ as a function of parameter \mathbf{x} .
- Click \checkmark or press **Enter** to refresh graphs. Both R(V) and I(V) functions will be calculated and shown on the graph.
- To approximate function f(x) using existing points (rows) in the table, fill in To column of the table, click Approximate using existing points. Select Automatic update to perform approximation automatically on any changes in the data table.
- To approximate function with automatic points selection to provide minimal approximation error, specify **From**, **To**, and **Interval** of approximation, click ➡ **Approximate in the range**:



List model (voltage and current source)


List model describes piecewise linear voltage or current source.

List parameter is a comma-separated string with time/value pairs:

T1,V1,T2,V2,...,TN,VN

Signal value between specified points is linearly interpolated. Signal value before T1 is V1, signal value after TN is VN. Values T1...TN should be given in ascending order. Although the signal is defined on the interval T1...TN, it can be repeated continuously, or delayed by setting component parameters **Delay** and **Cycle**. Please note that only numbers can be used in **List** parameter: formulas are not allowed.

Edit **List** parameter manually, or click **l** to open **List** window:



Enter data in the table as comma-separated time/value pairs. The data will be automatically sorted in ascending order when refreshed.

List model (switch and logic generator)

List model describes switching sequence of Switch component, and logical signal of Logic Generator component.

List parameter is a comma-separated string with time/value pairs:


T1, S1, T2, S2, ..., TN, SN

where Ti, Si pair defines state of the signal at specified time:

- Positive value corresponds to **On** state of the switch, or **High** state of the logic generator.
- Zero or negative value corresponds to **Off** state of the switch, or **Low** state of the logic generator.

Signal state before T1 is S1, signal state after TN is SN. Values T1...TN should be given in ascending order. Although the signal is defined on the interval T1...TN, it can be repeated continuously, or delayed by setting component parameters **Delay** and **Cycle**. Please note that only numbers can be used in **List** parameter: formulas are not allowed.

Edit **List** parameter manually, or click **l** to open **List** window:



Enter data in the table as comma-separated time/value pairs. The data will be automatically sorted in ascending order when refreshed.

Table model


Table model describes look-up table of the Function component.

Table parameter is a comma-separated string with input/output pairs:

X1,Y1,X2,Y2,...,XN,YN

where xi, yi pair defines input value x and output value y. Output value between specified points is linearly interpolated. Output value below x1 is linearly extrapolated using x1...x2 interval data, output value above xN is linearly extrapolated using x(N-1)...xN interval data. Values x1...xN should be given in ascending order. Please note that only numbers can be used in **Table** parameter: formulas are not allowed.

To edit **Table** parameter, select the parameter and click it to open **Table** window:



Enter data in the table as comma-separated input/output pairs. The data will be automatically sorted in ascending order when refreshed.

User's Manual

2D Table model

Table model describes 2D (two-dimensional) look-up table of the Function-2 component.

Table parameter of the model defines output value z as a function of x and y inputs of the component in the following format:


Z11, Z12, ..., Z1N, Z21, Z22, ..., Z2N, ..., ZM1, ZM2, ..., ZMN

where:

- Zij defines output of the function for input values Xi and Yj.
- \mathbf{N} is total number of \mathbf{x} points, defined by \mathbf{X} parameter of the component.
- \mathbf{M} is total number of \mathbf{Y} points, defined by \mathbf{Y} parameter of the component.

Output value between specified **x** and **y** points is linearly interpolated on both coordinates. Output value below x1 is linearly extrapolated using x1...x2 interval data, output value above xN is linearly extrapolated using x(N-1)...xN interval data. The same rule is applied to **y** coordinate. Please note that only numbers can be used in **Table**, **X**, and **Y** parameters: formulas are not allowed.

First, enter **X** and **Y** parameters, then enter **Table** values (select the parameter and click \square). Columns correspond to **X** parameter, rows – to **Y** parameter:




• show z(x) traces: each trace represents one row of the table. Total number of traces is **m**, highlighted trace corresponds to the selected cell of the table.

- show Z(Y) traces: each trace represents one column of the table. Total number of traces is **n**, highlighted trace corresponds to the selected cell of the table.


C-code component

In **C-code** component, the component function code can be written in C language. The code is interpreted by NL5 during transient simulation. Although C code interpretation is relatively slow, using **C-code** component allows fast iterations of the code and easy access to C-code variables for debugging. When the code is finalized, it can be compiled and built as DLL for faster simulation (see *Working with DLL* chapter).

C-code component is a customized component. **Right-click** on the component, select **Component** then **Edit component** is to open **Edit component** window and specify symbol size, inputs, outputs, and clock (optional):



Execution. A principle of C code execution is shown on the following diagram:



Each input/output pin with a name has a variable of the same name in the C code associated with the pin. A voltage on the input pin of the component (for example, **in**) is measured by a "virtual" voltmeter, and is assigned to the variable double in. While C code is executed, a new value of output variable double out is evaluated. A voltage equal to out value is set to a "virtual" grounded voltage source, connected to the output pin of the same name **out**.

Inputs and outputs can also be assigned to array elements. For example, inputs x[0], x[1], and x[2] correspond to the array double x[3].

-x1	y1	-x[0]	y[0]
-x2	y2	-x[1]	y[1]
-x3	уз —	-x[2]	y[2]

Input/output variables corresponding to inputs and outputs (arrays) are **global** variables and should be declared as variables of double type in the beginning of the code, outside of **init** or **main** functions. (See **global variables** chapter below for details). If not explicitly declared, all required input/output variables will be automatically created during initialization phase of the analysis at t=0.

Code structure. A typical code structure is the following:

```
// Global variables
...
// Initialization function
init()
{
    ...
}
// Main function
main()
{
    ...
}
```

If complex initialization of global variables is not required, initialization function can be omitted. Then the code will look like this:

```
// Global variables
...
// Main function
main()
{
    ...
}
```

If global variables (other than inputs and outputs) are not used, both initialization and main functions can be omitted, and the C-code will look like that:

// The **code**

Global variables. Global variables are **public** variables of the code. They can be accessed outside the C code: from the script (for example, for data logging), from the command line, displayed as a trace on the transient graph, used in the expressions for V/I sources, etc. Also, global variables are **static**: they persist and keep their values during entire transient simulation, between calls of C-code functions.

Global variables can be used for storing code data that are calculated once during initialization, and then used in the main function on each simulation step. Global variables can also be used for storing values that are calculated on one simulation step, and then are used on the next simulation step.

Global variables should be declared in the beginning of the code outside of init and main functions. Variables can also be initialized during declaration. However, if some code is required for initialization, it should be done in the init function.

Although input/output variables are always global, they can be explicitly declared as global variables as well. If not explicitly declared, all required input/output variables will be created automatically during initialization phase of the analysis at t=0.

To access global variables outside the C-code use the following notation:

```
component name.variable name
```

For array elements, use the following notation:

component_name.array_name[index]

For example, to display global variable as a trace on the transient graph, add a trace of **function** type, and enter variable name, or any expression containing the variable:

```
X1.out1
Xcode.array[3]
X1.X2.temp (X1 - subcircuit, X2 - C-code component)
```

Initialization function is executed once at the beginning of simulation at t=0. The name of the initialization function should be init. Initialization code is used to initialize global variables if some complex code is required for initialization. Initialization function is optional and can be omitted. Variables declared in the init function are **local** and persist only during execution of that function.

Main function calculates output variables using current values of input variables during transient simulation. If **clock** pin does not exist, the function is executed on every calculation step. If **clock** pin exists, the function is executed only on rising or falling edge of logical clock signal. The name of the main function should be main.

Variables declared in the main function are **local** and persist only during execution of that function. Use global variables for storing values that are calculated on one simulation step, and then are used on the next simulation step.

Along with global and local variables, the following **read-only** variables and functions can be used in the main function:

Component parameters (such as R1, C2, V.period, etc.), *t* - current time **V**(*name*) - voltage on the component *name* **I**(*name*) - current through the component *name* **P**(*name*) - power on the component *name* **S**(*name*) - state of the component *name* where *name* is the name of any component in the schematic, and V, I, P, or S value is available for that component.

Code of main function can be modified during transient simulation: pause the transient, make changes, and continue transient. The changes will take effect immediately.

Initial conditions (IC parameter). Initial conditions is a string with comma-separated expressions in "name=value" format assigning initial values to output variables and global variables of the code. For example:

y1=1.2, y2=0, y3=2.345, integral=-4.19, counter=100


Here y1, y2, and y3 are output variables; integral and counter are global variables.

IC string will be automatically modified by the following commands:

- **Save initial conditions** $\stackrel{\clubsuit}{\Longrightarrow}$: fills in **IC** string with current variable values.
- Schematic tools R, Initial Condition tab, check box Clear C-code and DLL IC: clears IC string.

If not empty, IC will be executed right after initialization (init function), and before the first transient simulation step at t=0.

Editing C-code. To edit the Code, select the parameter and click it to open Code window:




- clear code and set code template with empty init() and main() functions.
- check code. A message box with errors or warnings found will be shown.
- ¹²³ show line numbers (no editing allowed in this mode).
- **¹** Help (**F1**). Opens Help topic on statement, operator, or function, where cursor is located.


DLL component

In **DLL** component, the component function code can be written in C/C++ language, compiled by C compiler, and built as Windows DLL (Dynamic-Linked Library). DLL functions will be called by NL5 during transient simulation. DLL code will be executed much faster than C code in **C-code** component. However, changing the code requires recompiling the code and rebuilding the DLL.

DLL component is a customized component. **Right-click** on the component, select **Component** [▶], then **Edit component** [↓] to open **Edit component** window and specify symbol size, inputs, outputs, component variables, and clock (optional):



Execution. A principle of DLL code execution is shown on the following diagram:



A voltage on the input pin of the component **in** is measured by a "virtual" voltmeter and is assigned to the corresponding element of the array data of double type. The pointer to the array is passed as a parameter to the DLL function main. The function is executed; a new value of output **out** is evaluated and assigned to the corresponding element of the array data. A voltage equal to that value is set to a "virtual" grounded voltage source, connected to the corresponding output pin **out**.

Array double data[] is used to pass input/output values to/from DLL function. Array size is <*number* of inputs> + <*number* of outputs>. When calling DLL function, first <*number* of inputs> elements of the array are set to input values in the same order as input pins are shown on the component symbol (left


side, top-to-bottom). Output values calculated in the DLL are placed in the next *<number of outputs>* elements of the array in the same order as output pins are shown on the component symbol (right side, top-to-bottom). For example, if the component has two inputs and two outputs, the following code will assign minimum input value to the first output, and maximum input value to the second output:

```
data[2] = min(data[0], data[1]);
data[3] = max(data[0], data[1]);
```

Component variables. Any variables created in the DLL code are not accessible by NL5. DLL **component variables** are used for storing values that are accessible both from DLL and NL5.

Component variables are instantiated in NL5 and can be accessed and modified both by NL5 and DLL. Component variables can be used, for example, for debugging purposes: they can be displayed on the graph as a trace without passing them through output pins of the component. Component variables can be changed by NL5 script or command line when simulation is paused. Also, values of component variables will be saved as initial conditions in the **IC** parameter of the component.

Input, output, and component variable names are defined in the In, Out, and Var tabs. You can also assign initial values (IC) to outputs and component variables in the form name=value:



If component variables are used, the size of the data[] array should be *<number of inputs>* + *<number of outputs>* + *<number of component variables>*. When calling DLL functions, corresponding elements of the array (following output values) are filled in with current values of component variables. DLL can modify component variables by assigning new values to corresponding elements of the array.

For example, if DLL component with 2 inputs and 2 outputs has a component variable counter, it can be modified by NL5 using following notation:

```
component name.counter = 0;
```

DLL, in turn, can modify value of counter as:

data[4] = counter;

Variable counter can be displayed on the graph as a trace of **Function** type using the following notation:

component name.counter

When simulation is already started and paused, open **Edit component** window for DLL component and click **DLL variables** button. DLL component variables and their current values will be shown (in floating point format). Those values can be edited and will be sent to the DLL when pressed **OK**.

Initialization function (Init parameter). The function should be declared as follows:

```
extern "C" __declspec (dllexport) int NAME(double t, double* data);
```

where:

```
NAME - function name, for instance init
t - current simulation time (always = 0)
data - pointer to the array with input/output data
```

The function returns zero if no errors occur, or user-defined non-zero integer error code. If error occurs, the error code will be displayed in the NL5 error message window.

Initialization function is executed once at the beginning of simulation at t=0. The function can be used to assign initial (default) values to outputs and component variables (if defined) by setting corresponding elements of the array data[], declare and initialize static DLL variables and arrays, allocate additional memory which will be used by DLL, open data logging files, etc.

This function is optional and can be omitted. Leave Init parameter blank if function is not used.

Main function (Main parameter). The function should be declared as follows:

```
extern "C" declspec (dllexport) int NAME(double t, double* data);
```

where:

```
NAME - function name, for instance main
t - current simulation time
data - pointer to the array with input/output data
```

The function returns zero if no errors occur, or user-defined non-zero integer error code. If error occurs, the error code will be displayed in the NL5 error message window.

The function calculates output variables using current values of input variables during transient simulation. If **clock** pin does not exist, the function is executed on every calculation step. If **clock** pin exists, the function is executed only on rising/falling edge of logical clock signal.

For example, function main below calculates sum of 8 inputs:

```
extern "C" __declspec (dllexport) int main(double t, double* x)
{
     double y=0;
     for(int i=0; i<8; ++i) y += x[i];
     x[8] = y;
     return 0;
}</pre>
```

This function is optional and can be omitted. Leave Main parameter blank if function is not used.

Pause function (Pause parameter). The function should be declared as follows:

extern "C" __declspec (dllexport) void NAME();

where:

NAME - function name, for instance on pause

The function is called when transient simulation is paused. Use this function to perform operations such as saving data into the file, reallocate unused memory, etc.

This function is optional and can be omitted. Leave Pause parameter blank if function is not used.

Exit function (Exit parameter). The function should be declared as follows:

extern "C" declspec (dllexport) void NAME();

where:

NAME - function name, for instance on exit

The function is called when DLL is being closed and DLL component destroyed. Use this function to free the memory allocated by other DLL functions, close files used for data logging, etc.

This function is optional and can be omitted. Leave **Exit** parameter blank if function is not used.

Using one DLL by several components. Several DLL components may use the same DLL file. Be aware that in this case only one copy of DLL is loaded into the memory, so that the same static variables will be shared by all components. In this case, **Init**, **Pause**, and **Exit** functions may be called only by one component. Also, different components can use different functions from the same DLL.

If you need several components to be using the same DLL with separate static variables, use several copies of the DLL file with different names. Another solution would be **attaching** DLL to the component. If DLL is attached, NL5 will create a unique temporary DLL file for each component during simulation, so that each component will be using its own DLL copy.

Initial conditions (IC parameter). Initial conditions is a string with comma-separated expressions in "name=value" format assigning initial values to outputs and component variables of the DLL. For example:

min=-1.23, max=4.56, counter=100

where min and max are outputs, and counter is component variable.

IC string will be automatically modified by the following commands:

- Save initial conditions 🗳 : fills in the string with current variable values.
- Schematic tools X, Initial Condition tab, check box Clear C-code and DLL IC: clears this string.

If not empty, **IC** will be executed right before calling DLL initialization function, so that DLL initialization function could use parameters defined in the **IC** string.

Roots model

Roots model describes zeroes and poles of transfer function of s-function component:


 $f(s) = \mathbf{K} * (s-z_1)*(s-z_2).../(s-p_1)/(s-p_2)...$

and impedance of Impedance component.

$$z(s) = \mathbf{Z} * (s-z_1)*(s-z_2).../(s-p_1)/(s-p_2)...$$

where zn are zeroes, pn are poles.

Zeros and poles are entered in the **Roots** window:



To enter new zero/pole, select the last (empty) table cell, **Re** column, enter the value, and press **Enter**, or click \checkmark to update the table. Then enter **Im** value if needed. If non-zero **Im** value is entered, a conjugate zero/pole is added automatically.

To edit existing zero/pole, select the cell, enter new value, and press **Enter**, or click \checkmark to update the table. Click \blacksquare to remove selected zero/pole, marked by \Rightarrow in the first column, or click \checkmark to clear the table.

Attachments

Any files/data used by NL5 components (**File**, **SubCir**, **DLL**, etc.) can be **attached** to the NL5 schematic file. Them the schematic file will contain all the data needed for simulation, which makes it easy to maintain, encrypt, and distribute.

To attach the data to the component, click **Attach** 0 on the **Component window** toolbar, or **rightclick** on the component, select **Component**, then **Attach** 0. To remove attachment click **Remove attachment** 0.

Attached data/schematic can be reviewed and edited by clicking **Open attachment/subcircuit**

If attached subcircuit of **SubCir** model is opened and edited, it can be saved back to the attachment only by **Save / Save attachment** command, so that original subcircuit file will not be changed. If the same subcircuit is attached to several components, it can be modified for each component separately.

Please note that attaching **DLL** may result in large size of the schematic file, since binary data of the dll file are converted into text format.

Current attachments of all components of the schematic can be reviewed and managed in the **Schematic tools** window, **Attachments** tab. Current attachments of all components of the schematic can be reviewed and managed in the **Schematic tools** window, **Attachments** tab.

NL5 components (*.nlc)

NL5 component can be saved into a **component file**: schematic file with nlc extension. Then the component can be loaded from the file and placed onto schematic as a standard component. For components with external data (**SubCir** and **File** models, **DLL**), attach the data to the component and save it in the component file: then the **component file** can be easily distributed without additional files. The component can also be encrypted: **right-click** on the component, select **Component** \clubsuit , then **Encrypt**).

To save a component into **component file**, **right-click** on the component, select **Component** P, then **Save component** \blacksquare .

To place component onto schematic, click Load component in the Components bar:



Customized component

Some components are **customized**, so that their symbol and/or number of pins can be edited by user. To edit component symbol, open **Edit component** window:

- Right-click on the component, select Component [▶], then Edit component [↓] (if available).
 OR
- Click Edit component 🏥 on the Components window toolbar.

The following component properties can be edited for all customized components:

- Symbol width.
- Symbol height.
- Number of pins (inputs and/or outputs).
- Pins location.

The following properties can be edited for specific component types:

- Pin names.
- Subcircuit label names.
- Clock signal, inversion of clock signal.
- Inversion of the output.
- Logical function.
- Number of windings.
- Beginning and end of windings.
- DLL component variables.


Encrypted component

Any component in the schematic can be **encrypted**: **right-click** on the component, select **Component b**, then **Encrypt**. Model and parameters of encrypted component are non-visible and non-editable, so that it can be distributed to other users with guarantee that its content will remain unknown.

Encrypted component can be decrypted back until schematic file is closed: **right-click** on the component, select **Component** \rightarrow , then **Decrypt** \bigcirc . Once schematic with encrypted component is saved and closed, the component cannot be decrypted: this is done to maximize security of encryption.

Schematic variables

Schematic variable is a floating point variable which belongs to the schematic. The variable and its value can be defined in the **Variables window**:




Click **Rename** button to rename the variable or specify its format:

Var3			×
Var3			Name
	hexadecimal	\sim	Format
	32	\sim	Bit
			OK
			Cancel

Format (double, integer, binary, octal, hexadecimal) specifies how the variable is displayed. Binary, octal and hexadecimal also have **Bit** settings. The variable value can be entered in any format, and then it will be displayed in specified format.

Click **Copy** button to copy variable to the clipboard, then click **Paste** to paste it to the same or another schematic. To copy all variables, click drop-down arrow next to the **Copy** button, then select **Copy all**:



Please note that variables should be copied/pasted separately from schematic components.

Variables can be used in formulas, functions, script, C-code, etc. For example:

R Ohm =Var1*2

Schematic settings

Details on some **Schematic settings T** tabs:

Library. Specify library paths list for component files (DLL, SubCir, File model, etc.). Click Edit , then enter library paths manually, one path per line, or click v to select from folders list:

Edit Libraries		×
😂 🖬 💠 🗙		
C:\Projects\nl5 C:\Documents\nl5\MyPro	ijec t	^
<		~
	OK	Cancel

When new schematic is created, a default list is copied from **Preferences**, **Library** tab. Library path could be full path, or path relative to the directory where schematic file is located.

If specified file name of the component does not have a full path, NL5 will search for the file in the following order:

- In the directory where schematic file is located.
- In the directories specified in the Library list (see Schematic settings chapter).
- In the directories specified in the Library list relative to the directory of schematic file.


Components. Specify logical levels and threshold for all components in the schematic.

Ver.2. If schematic was converted from NL5 Ver.2 format, this tab will show conversion notes: for example, what component types/models were renamed, replaced, removed, etc.

Schematic sheets

Schematic may contain several **Sheets** ^D. Electrical connection between schematic sheets can be done through labels and functions.

Existing sheets are shown in the **Sheet tab** of **Schematic window**. **Right-click** on the tab to access sheets-related commands in the pop-up context menu, or click **Sheets** to manage sheets in the **Sheets** window:



Schematic groups

Group is a set of components that always have the same model and parameter values. When model or parameter of any component in the group changes, all other components are changed automatically. An exception is IC-type (Initial Condition) parameter (or several IC parameters), which can be different for components in the group.

Only components of the same type can be assigned to the same group. If component is assigned to the group, the group name is shown in the **Group** column of **Components window**.

To assign selected component to a new or existing group, click **Group** in the **Components** window:

Group R3		×
Enter new group nar existing group from d		
Group1		~
💁 Groups	OK	Cancel

Click Groups... to manage existing groups, add new group, and assign components to the group in the **Groups** window:

💁 nl2 - Groups			×
💠 動 🗕 🗙			
Group1 Group2	Name R1 R2 R3 R4 R5	Value 1e+3 1e+3 1e+3 1e+3 1e+3	Group Group1 Group1 Group1
	☐ R5 ☑ R6 ☑ R7 ☐ R8	1e+3 1e+3 1e+3	Group2 Group2
Same IC for all components in selected group			

If "Same IC for all components in selected group" is checked, Initial Condition parameter(s) for all components in that group will always be the same, otherwise they can be different.

Deleting the group does not affect components assigned to that group.

Check schematic

Check schematic \checkmark command performs extensive check of the schematic for potential problems, and reports results in the window:

✓ nl1 - Check schematic		×
? D1,R1	< Click here to check again > Overlapping components	
? C1	Not connected	
?	Possibly floating schematic (no ground)	

Also, the check function removes unnecessary connection points and adds connection points where needed (three wires).

Click on the row to select (highlight) a schematic element(s) for which the problem was detected.

Go to **Preferences** , **Warnings** tab to select/unselect reported issues. **Right-click** to access check-related commands in the pop-up context menu.

Schematic check is automatically performed at **Transient** and **AC** simulation start. The problems reported by the function do not prevent from running simulation, and typically do not affect simulation results. However, they could indicate not accurate schematic design, and should be fixed if possible.

Schematic tools

Schematic tools 🏾 offer some useful operations on schematic.

Attachments. The table shows components with File, SubCir, and DLL models, the file name, and whether the file is currently attached (checked) or not attached (unchecked). Change checkbox states as needed to attach files or remove attachments. If When removing attachment, save to file option is selected, you will be asked for a file name.

Renumber. Renumber components on the schematic. Select **Order** and **Names** option, see example of renumbering in the **Example** window. **Numerical** name is the name that starts with a letter, and the rest of the name is a number, otherwise the name is considered as **Text**.

Initial Conditions. Set Initial Conditions (IC) of selected component types to specified value.

Clean Up. Clean up schematic, select what operations to perform.

Formulas. Replace all formulas with values.

Parameters. Set selected parameters of all components to specified value. Select parameters, enter new parameter value, or select from drop-down list.

Set period. Set Period parameter of all Sin and Pulse voltage and current sources, and Pulse switches. Width, Rise, Fall, and Delay values will be adjusted proportional to period.

Transform.

Frequency. Transform frequency response of the schematic by changing R, C, and L values. Enter f1 and f2 values, or place cursors at f1 and f2 frequencies on the AC graph (active cursor at f2). Select one of the following options:

- **R** = const. C and L will change as follows: C=C*f1/f2, L=L*f1/f2
- **C** = const. R and L will change as follows: R=R*f1/f2, $L=L*(f1/f2)^2$
- **L** = const. R and C will change as follows: R=R*f2/f1, $C=C*(f1/f2)^2$

Impedance. Transform schematic impedance from r1 to r2 by changing R, C, and L values. Enter r1 and r2 values, then click **Execute** to proceed. R, C, and L values will change as follows:

```
R=R*r2/r1
C=C*r1/r2
L=L*r2/r1
```

IV. Transient

Algorithm


NL5 performs simulation with ideal and piecewise linear (PWL) components. For instance, an ideal diode is either short circuit (zero resistance), or open circuit (infinite resistance), so that its PWL representation consists of just two linear segments. As long as all of the components are staying within their current segment, the circuit is described by the system of linear differential equations. The system is modified only at the moments when at least one component changes its linear segment.

Start. When simulation starts at t=0, a **Direct Current (DC) operating point** is calculated first. Some of the components may have specified Initial Condition (IC): these ICs will be used during DC operating point calculation. If circuit has more than one steady state, it can be set to a desired state by defining proper ICs. After DC operating point is found, simulation continues as a sequence of **linear segment** simulations, with **switching** between them.

Linear segment. In the linear segment, the circuit is described by the system of linear differential equations, which is solved by Trapezoidal integration method. The method provides sufficient accuracy with good robustness and calculation speed. During linear segment simulation, the algorithm is performing "switching point detection": checking conditions on all components that may change their state or linear segment.


Switching. When switching point is detected, the current linear range ends, **switching** algorithm performs instantaneous switching, and a new linear segment starts. Switching algorithm can be optimized for specific circuit by selecting from several options at **Transient settings/Advanced settings**.

Instantaneous switching of ideal components may produce infinite voltage or current pulses. For example, when capacitor is connected to voltage source through ideal switch, an infinitely short current pulse with infinite amplitude may occur. The area (integral over time) of such pulse is limited and is equal to the total charge coming to or out of the capacitor during switching. Similar situation may occur when current through the inductor is discontinued, which results in an infinite voltage pulse across the inductor. Integral of the voltage over time corresponds to a magnetic flux in the inductor. Such a pulse is known as Dirac pulse, or delta-function. In NL5, the current or voltage delta-function is shown as a triangle pulse with the duration of each slope equal to minimal calculation step used at that moment, and the area satisfies charge or magnetic flux conservation law.



Simulation step. Unlike many analog simulators, NL5 does not perform automatic step control. Selecting simulation step is user's responsibility. This gives user full control on simulation, although requires certain experience and understanding of the process. The rule of thumb is keeping simulation step below smallest time constant in the circuit, otherwise the integration method may get unstable, and produce "numerical oscillations" when signal is "jumping" up and down at each simulation step. Very often, such oscillation caused by non-optimal step would not affect overall functionality of the circuit and can be ignored. To get rid of that type of oscillation, reduce simulation step to reasonably small value, or use Suppress oscillations option (Transient settings/Advanced

settings/Transient/Simulation step). Here is an example of transient improvement with this option:



Although simulation step is specified by user, NL5 still can automatically reduce the step to satisfy the following conditions:

- Period of sine source contains at least 16 steps.
- Pulse or switch On/Off state contains at least 4 steps. _
- Non-zero rising or falling edge contains at least 4 steps.
- Interval between two points of the source component, interpolating the signal between two points, _ contains at least 4 steps.
- Delay time of transmission line and "delay" component contains at least 2 steps.

Also, simulation step can be reduced to detect switching point and perform accurate switching.

Automatic step reduction can be disabled by selecting **Constant step** option (**Transient** settings/Advanced settings/Transient/Simulation step).

Traces. During simulation, NL5 only stores data for specified **traces**. Pause or stop simulation to add/remove traces, then continue or start simulation. A special type of trace is Math (post-processing). That trace is calculated from other traces only when simulation is paused or stopped.

Memory. Simulation data is stored in the operating memory. The memory is allocated as needed by relatively small blocks. If available operating memory is not enough for all the data, some of the blocks currently storing the very beginning of the trace will be reassigned to a new data, and thus some traces may be "truncated" at the beginning. At the first time this happens, the warning message will be displayed in the status bar of Transient window.

By default, NL5 saves all calculated data for all traces. To reduce memory consumption, a simple data compression method can be used: if several data points in a row have the same amplitude, only first and last point of such sequence are being stored. To use this method, select **Data compression** option (Transient settings/Advanced settings/Transient).

Running transient

- Go to **Settings window** (then select desired Transient settings tab).

- Start transient (available on the Schematic and Transient window toolbars). When simulation is running, schematic cannot be edited, and component parameters/model cannot be changed. Stop or Pause simulation to do any changes.



→ - Pause transient (or press Space).



- **Continue** transient (or press **Space**).

- **Stop** transient. Clear extra memory allocated for simulation. Simulation cannot be continued.

Transient modes:

Single: simulation paused at the right edge of the screen. Please note that simulation step is not adjusted to stop exactly at the screen edge, so the last calculated point could have time greater than

screen edge. Press **Space** or click **Continue** ito continue simulation.

Scope: when the right edge of the screen reached, the screen shifts so that its right edge becomes the left, and simulation continued.

Scroll: when the right edge of the screen reached, the screen is scrolled to the left by some small amount (about 1%), and simulation continued.

E Zoom: when the right edge of the screen reached, screen size increased by some small amount (about 1%) keeping left edge the same, and simulation continued.

Continuous: when the right edge of the screen reached, simulation continued further without changing the screen. Use this mode to view simulation results at specific time, while simulation is running.


- Save IC. Stop simulation, move component states to component initial condition (IC). Also, a **Delay** parameter of all sources will change accordingly to provide specific starting phase of the signal. All saved states will be deleted.

Please note that not all components/models provide initial conditions for all possible states. For instance, some models of controlled sources and switches (One-shot, Pulse, Sin, Clock, etc.) will always start being in inactive state.

- Sweep parameter. Open Tools window, Sweep tab. See Tools chapter for details.

- Show transient log.

Transient window



Add transient traces using any of the following methods:

- Go to Settings window 🛣 , Add traces 👎 tab, see detailed instruction below.
- **Right-click** on the component in the schematic window, select **Add trace** $\overset{m}{\sim}$, then select trace type.
- Select component in the **Components window**, click **Add trace X I R** button.
- Select variable in the Variables window, click Add trace Add trace

Go to Settings window 🛣 , Format traces 🕮 tab to select trace type, color, scales, etc.

Go to **Settings window** \mathbb{T} , **Screen** \boxminus tab to configure **Transient window** sections, scales, and other properties.

There could be 3 types of sections displaying transient data: Preview, Digital, and Analog.

Preview section shows **all data** of one selected trace and can be used to select desired horizontal range for analog and digital sections. The trace is always auto-scaled horizontally and vertically.

- Move **preview cursors** by mouse (just one cursor or both simultaneously) or click on the section to select screen horizontal range.
- Use **mouse-wheel** to change screen horizontal range.
- **Right-click** on the section to select another preview trace or hide the section.
- Use **split bar** below the section to change its height.


Digital section contains all traces of Digital and Bus type.

- Use **split bar** below the section to adjust section height manually.
- Double-click the split bar to set the height so that all traces in the section are visible.
- Go to **Preferences** , Graphs, Digital/Bus tab to configure size and format of digital/bus traces.

Analog sections contain traces of **Analog** type. Every analog trace can be assigned either to **Digital** or one of **Analog** section. Having just one analog section could be sufficient for most applications. Multiple sections (up to 4) may be used to combine several traces with similar properties (function, scale, etc.): for example, one section for high voltage traces, and another section for low current traces.

Some useful operations on Analog sections:

- Maximize analog section temporarily maximized selected analog section to the full window size.
- Separate traces mode (press Tab) show each trace in its own smaller area separated by horizontal lines:



Separate traces Off

Separate traces On

- Show selected background = use highlighted background of the selected traces. This feature is applicable for digital/bus traces, and analog traces in Separate traces mode.
- Use **split bars** between analog sections to adjust section height.
- Vertical scaling operations and vertical scrollbar apply to currently active **Analog** section.

Vertical scale. Each trace in the analog section is shown with its individual Scale and Mid values,

specified at **Settings window**, **Format traces** tab. Vertical scale and gridlines are shown for selected trace (or several selected traces if their **Scale** and **Mid** values are the same). If several traces with different **Scale** and **Mid** values are selected, vertical scale is not shown.

Depending on selected **vertical mode**, all vertical zoom/scroll/reset operations (when buttons, keys, mouse, mouse wheel) will apply to:



- All traces of the active analog section.

- Selected traces of the active analog section.

• Screen. In this mode, zoom and offset apply to the whole screen image, while scales and offsets of traces remain unchanged. This mode is similar to NL5 Ver.2 functionality. Please note that when switching back to either of the first two modes, screen zoom and offset are reset to default, and the image of the graph may change.

Click **Reset vertical scale** to set **Scale** and **Mid** to default values.

Mouse. There are 3 modes of mouse operation in analog sections:

Cursors \bowtie mode. Some mouse operations apply to transient cursors \P :

- **Double-click** the screen to show cursors and/or reset cursors lock mode.
- Click on the screen to move closest cursor to that point.
- Place mouse pointer over the cursor, then click and drag to move the cursor.
- Press Left/Right arrow key with Ctrl, Shift, or Ctrl-Shift keys to move active cursor with different step resolution.

Zoom mode (press and hold **Ctrl** key to switch to **zoom** mode temporarily). Click and drag to select horizontal, vertical, or rectangle area to be zoomed-in:



Move mouse pointer horizontally to select horizontal area.





Move mouse pointer vertically to select vertical area.

Move mouse pointer diagonally to select rectangle area.

Scrolling mode (press and hold **Shift** key to switch to **scrolling** mode temporarily). Click and drag to scroll the screen.

Mouse wheel:

Mouse wheel – horizontal zoom (relative to mouse pointer position). Shift-mouse wheel – horizontal scroll. Ctrl-mouse wheel – vertical zoom (relative to mouse pointer position). Ctrl-Shift-mouse wheel – vertical scroll.

Keys and shortcuts:

F5 – show transient window .
F6 - start transient .
F7 - stop transient .
Space – pause/continue transient.
Tab - separate traces in active analog section .
Up, Down – vertical scroll.
PgUp, PgDn – vertical zoom ↓, ↓.

Home – vertical fit the screen

Left, Right – horizontal scroll. End – center beginning of traces (set to the middle of the screen). Ctrl-End – center end of traces. Shift-End – center middle of the traces. Ctrl-PgUp, Ctrl-PgDn – horizontal zoom ↔, ↔. Ctrl-Home – horizontal fit the screen ↔.

Shift-PgUp, Shift-PgDn – vertical and horizontal zoom. Shift-Home – fit the screen ➡.

Ctrl-Right, Ctrl-Left, Shift-Right, Shift-Left, Ctrl-Shift-Right, Ctrl-Shift-Left - move selected cursor with different resolution.

Status bar

Right-click status bar to configure:

/Run3/Run4/ t= 200	24 MD	distant and a second
	- V	Progress
	\checkmark	Memory
		Simulation time
	\checkmark	Cursors
		Interval
		Frequency

- **Progress** current transient time, simulation status (running, paused).
- **Memory** amount of memory allocated for calculation and data.
- **Simulation time** –simulation (processor) time.
- **Cursors** show cursors position (left and right).
- Interval interval between cursors.
- **Frequency** = 1 / Interval.

Cursors

Cursors for **Transient table** and **Transient tools**.

- Go to **Cursors** tab of **Settings window** to configure cursors options and perform some operations on cursors.
- Click **Show cursors** to show/hide cursors. Please note that table and transient tools may use specified **Cursors** interval type even when cursors are hidden.
- Click **Cursors to screen** to set horizontal scale to cursors position.

Labels


Labels are trace names shown in the area on the right side of the graph. Highlighted background of the label indicates selected traces.

- Click **Show labels** to show/hide labels.
- **Click** on the label to select one trace.
- **Ctrl-click** to add trace to selection or unselect the trace.
- **Shift-click** to select a range of traces.
- **Right-click** on the label to see labels-related context menu.

Legend


Legend shows list of traces currently displayed on the graph. Legend is also available in all **Transient tools**.

- Click **Show legend** to show/hide legend.
- Click on the border of the legend and drag to move the legend window.
- **Click** on the trace in the legend to select one trace.
- **Ctrl-click** to add trace to selection or unselect the trace.
- **Shift-click** to select a range of traces.
- **Right-click** to see context menu with more selection options.
- Go to **Preferences** A, Legend tab to select legend style (colors, font). The style can be defined manually or selected from two predefined options (NL5 Ver.2 and NL5 Ver.3), and then adjusted manually if needed:



Annotations

Annotation s is a text with a pointer, which always points to the same data point of a trace, even when graph is zoomed or scrolled:



- To add annotation, set cursor to the time point where annotation is needed, **right-click** the graph,

select Annotate 🚴, then select Selected traces 🍣 or All traces 🕏 .


- Go to **Preferences** Annotation tab to configure annotation colors, font, and some other common properties.
- **Double-click** on the annotation, or **right-click** the annotation and select **Edit annotation** to edit (customize) specific annotation:

🛃 Edit ann	otation ×
☑ Name ☑ Time ☑ Value	■ 妻 電 』 込 □ Apply to all annotations
Enter text here	^
<	~
	Close

- **Click** and drag annotation text to move the text while keeping pointer at the same data point.
- **Click** and drag the end of the pointer to move annotation pointer to a different data point. The pointer will follow the mouse pointer, staying at the nearest point of the trace (trace data between data points are linearly interpolated).
- Annotations defined on the transient graph can also be displayed on the **XY diagram**, **Eye diagram**, and **Amplitude histogram** Transient tools.

Text

Right-click on the graph, select **Insert text**



If graph is zoomed or scrolled, the text stays at the same place, anchored to the left-top corner of the graph window.

- **Double-click** on the text, or **right-click** on the text and select **Edit text** to edit or configure the text.
- Click and drag the text window to move it. If pointer is locked, only text will move.
- **Click** and drag the end of the pointer to move the pointer only.


Table

Table shows cursors position, trace values, and some characteristics of the traces calculated in specified interval (**Cursors, Screen, All data, Selection**).

- Go to of **Settings window** $\overline{\mathbf{x}}$, **Table** \boxplus tab to configure the table.
- Click **Show table** to show/hide the table.
- Click **Floating table** to show the table in a floating window. Click \blacksquare and \blacksquare any time to switch between window modes.
- **Right-click** the table to see context menu with table-related commands.
- **Right-click** / **Copy** to copy content of the table cell to the clipboard.

Storage

Storage can be used to keep simulation data for further analysis and comparison. When simulation is performed, transient data are shown on the graph, and a tab named **Run** corresponding to current transient data is shown in the **Storage tab**:




When new simulation is started, current simulation data are deleted. To keep it for further analysis and comparison, it can be saved into **storage**.

Right-click the graph or **Storage tab**, and select **Move Run to storage** $\stackrel{\clubsuit}{}$, then enter storage name:

Storage	
Move run to storage Enter storage name:	
Run1	
	OK Cancel

Simulation data will be moved to the storage, and a tab corresponding to the stored data will appear in the **Storage tab**. Also, storage is used for **Sweep parameter** operation.

Stored data can be displayed in different ways, for example:



- Go to Storage \blacksquare tab of Settings window \square to configure storage.
- **Right-click** the graph or **Storage tab** for storage-related commands.

Transient settings

Simulation

🝸 nl2 - Settings - Tra	nsient	×
Image: Secting - Image: Im	Image: Start, s Start, s Step, s	
T Advanced setting	s Apply	Check traces to be shown on the graph

Start, Screen. Screen settings at simulation start (simulation itself always starts at t=0). Click to apply current screen settings to **Start** and **Screen** parameters.

Start display when. Select this option and enter condition to start display when condition is met (at time greater than **Start**). For example:

V(C1)>10.0

Pause simulation when. Select this option and enter condition to pause simulation when condition is met. For example:

P(R1)>1.0

If simulation paused at specified condition and then continued, it will be performed until condition is not met, and then paused when condition is met again.

Advanced settings ¹ - more algorithm, transient, and data settings.

Advanced settings	×
Transient AC	
Simulation step	Convergence
Optimal switching \sim	5 Time-out, s
Step multipliers:	Ignore No solution error
125e-3 Switching point detection	Data
250e-3 Switching	Data compression
Suppress oscillations	☑ Save data before Start
1e-12 Zero (machine precisio	n) OK Cancel

Simulation step. Select simulation step control mode:

- **Constant step** step will never be reduced by NL5 and will always be as defined by the user. This option provides fastest simulation, however switching and convergence may not be reliable.
- **Fast switching** fast simulation with acceptable switching convergence for most circuits.
- **Optimal switching** good convergence and performance for most circuits.
- Accurate switching best convergence, however simulation time might be longer.
- **Custom** use your own **Step multipliers**:

Switching point detection - current step may be reduced by this coefficient to detect switching point more accurately.

Switching – after switching occurred, the current step will be reduced by this coefficient for at least two simulation steps to provide more accurate results. Also, this will define the displayed amplitude of possible "infinite" voltage or current pulses for simulation with ideal components. This value is recommended to be at least two times greater than **Switching point detection** value.

Suppress oscillations. Reduce oscillations caused by high simulation step. Using this option may increase simulation time.

Convergence.

Time-out specifies maximum time allowed for calculating one simulation step. If calculation takes longer, simulation is stopped with error message. If time-out occurred due to unresolved switching iterations, the error message will indicate a component that started switching process. Time-out may also occur due to infinite while/do/for loops of C-code. Set **Time-out = 0** to disable time-out detection.

Ignore No solution error. Sometimes switching process cannot be resolved, and error message is being displayed, for example:

Transient er	ror			
	Check and modify s OR	alculating switching trigger chematic to resolve switch plution error' in Advanced	ning	^
				~
T A	dvanced settings		ОК	

Such a problem is most likely to happen during switching process in a complex circuit with ideal components, where infinite loop gain, infinite voltage/current, or other extreme (non-realistic) conditions may occur. To resolve the problem:

- First, check the schematic to fix possible general schematic issues.
- Identify critical ideal components which may cause the problem and replace them with more "realistic" models (use finite gain and bandwidth, non-zero and non-infinite resistance, etc.).
- Add small resistors in series, large resistors in parallel, and/or small capacitors in parallel to critical points.

If none of those actions help, select **Ignore 'No solution' error** option. With this option enabled, if switching cannot be resolved, NL5 will accept some, probably invalid, solution, and continue transient simulation. Although one or more data points may not be entirely correct, there is a high chance that the solution will converge to the correct one very soon.

Data.

Data compression. If several data points in a row have the same amplitude, only first and last point of such sequence will be stored.

Save data before Start. Although simulation always starts at t=0, the data before **Start** may be not stores, to reduce memory consumption.

Zero (machine precision) – relative difference between two floating point numbers which can be reliably recognized. Increasing **Zero** may help to improve convergence at switching points, however, for most of circuits changing **Zero** is not recommended.



T nl1 - Settings - Transient	×
0 - 🖻 🗟 🖶 🖍 🖿 🖛 📲 🗕	- X 🛧 🕹 🛱
👕 🔸 🖾 😑 👎 🌐 🗉	Check all Select all
Select trace type V I P State Variable Function Math	✓ V(Y1) ✓ V(C1) ✓ I(C1)
Apply	Check traces to be shown on the graph

V, I, P, State, Variable:

Select one or more components in the list, then click • Add new trace, or double-click on the component in the list.

To add trace in the **Schematic window**, **right-click** on the component, select **Add trace** $\stackrel{\text{magenta}}{\longrightarrow}$, then select trace type. **Digital** type is adding **V** trace with trace type set to **Digital**.

To add traces in the **Components window**, select component and click \mathbf{X} , \mathbf{I} , or \mathbf{R} . To add **Variable** trace in the **Variables window**, select variable and click \mathbf{X} .

State trace may be used to clearly indicate a state of the component instead of looking at current and/or voltage on the component. For example, for diodes and switches, it is 0 if device is in **Off** state (non-conducting), and 1 if device is **On** state (conducting). For **PWL** models, it indicates PWL characteristic piece number which is currently being used.

Function:

Click Add new trace, then enter function. The function may consist of arithmetic operators and functions, component parameters, global variables of C-code components, names of existing traces, current transient time t, and V, I, and P on the component (even if V, I, P trace for the component is not defined) :

```
sin(t*1000)*(1+cos(t*10))
V(in)/I(A1)
X2.param (value of param variable of C-code component X2)
X2.arr[5] (value of arr[5] of C-code component X2)
```

Use function to display V/I/P on the components inside subcircuits, for example:

V(X1.R1) - voltage at R1 in the subcircuit X1.

The function is calculated only during simulation: if function is changed, it will not be immediately recalculated.

Math:

Click **Add new trace**, then specify **Math** trace :

Add trace						×
Operation	n					
Function	ı			\sim	OK	
Function					Cancel	
				~		
	-					
Interval	Cursors	~				
300)e-3		Left			
600)e-3		Right			

Select **Operation**, then enter parameters required for that operation (if any). Specify **Interval** where **Math** trace will be calculated.

The **Math** trace is **post-processing** type of trace: it is recalculated automatically when simulation paused or stopped, and if trace type, parameters, or interval changed (unless **Recalc Math traces manually** option is not selected at **Format traces** tab).

The **Math** trace also applies to source **storage** data, and is displayed as a **Math** trace storage. While normal trace storage is never changing, **Math** trace storage is automatically recalculated in case of operation or parameters changed, or trace range changed.

Please note that for some operations, a time interval of resulting **Math** trace could be smaller than that of a source trace. For example, one moving average data point is using a source data in the time interval of an averaging window size. As a result, moving average trace will start a half of an averaging window size later and stop a half of an averaging window size before a source trace.


Details and examples of some Math types:

Function. Enter a function expression in the **Function** window. The function may consist of arithmetic operators and functions, component parameters, global variables of **C-code** components, any other traces, current transient time t. For example:


```
sin(t*1000.)*(1+cos(t*10.))
V(R1)/R1.R
old_trace + new_trace
```

To access a specific storage data, use a trace name.storage name notation:


```
trace.Run1 - trace.Run2
```



Min, Max, Mean, RMS, SD. Calculate specified value of selected trace.




LPF, HPF. Apply low-pass or high-pass filter to selected trace.




Moving Average, Moving RMS, Moving SD. Calculate specified moving average type.

Add trace	×					
Operation						
Moving Average \sim	OK					
Trace	Cancel					
V(V1) ~						
Window, s 0.1		1.04				
0.1		1.24				
		0]
					V(V1)	
Interval : Screen 🗸		1.24				
0 Left		0		-/ \+	_ _	
5 Right					Moving Averag	e of V(V1)
		0	·····¦1	2	3	4

Integral. Calculate integral over time. Integral value starts from zero.




Regression. Calculate polynomial regression of selected order (0...5).




Add trace	×				
Operation Counter V	K	of V(SOS)	0)1)2)3)4	(5)6	<u>(7)8)9</u>
Trace V(SOS) ~	ncel				V(SOS) Counter of V(SOS Counter of V(SOS
Threshold, V 2.5					
Edge Up ~	10				
Interval : Cursors V	5				
107 Left					
138 Right	_0	100	110	120	130

Counter. Count transitions of specified type (Up/Down).

F-V converter, T-V converter. Frequency-to-Voltage and Time-to-Voltage conversion. Trace voltage is equal to a frequency or a period of the trace signal, calculated using time between transition with specified threshold and direction.



Format traces



Check traces to be shown on the transient graph.

Select one or more traces (using Ctrl and Shift keys) to perform operations on selected traces.

Click **Select All** to select all traces or click for more selection options. Traces can also be selected in the **Legend** and **Labels** area of the Transient window. The top toolbar provides various operations on selected traces and trace data.

If more than one trace of a different type is selected, only parameters applicable to **all** selected traces will be shown. If parameter has different values for different traces, its field will be blank. If color is different, it will be displayed like this:

Trace configuration fields may be different for different trace types.

Trace/Function/Math. This field indicates trace type and is available for editing for **Function** trace only. For **Function** and **Math** trace, click **b** to edit the trace.

Name. Enter trace name which will be shown instead of **Trace**. To be used in formulas, it should satisfy C-language standard for the variable name: start with letter or '_', and then contain only letters, digits, and '_'. Otherwise, you will be given a warning:

abc!!!	Name
The name cannot be u	used as a variable

Type defines how the trace will be displayed:

- Analog trace will be displayed in analog format in Analog section.
- **Digital** and **Bus** trace will be displayed in digital or bus format in **Digital section**.


Analog.

Scale, Mid – scale values for analog trace. Click to select from previously used values. Click to auto-scale, or to reset vertical scale of selected traces.


Line – show lines.

Data points – show simulation data points. If **Data compression** option is selected, some simulation data points of a constant signal will not be stored and displayed.

Select Advanced formatting to allow advanced formatting capabilities:



Markers may be located at calculated data points, similar to standard formatting **Data points** option, or at the same distance along the trace line, regardless of actual data points and trace shape:



Digital.


Threshold – is used to convert analog signal to logical low/high level. It can be different from transient **Logical Threshold**. Click to see and select current Logical Threshold or click to select current Logical Threshold.

Style – select style of displaying high level state:

~	Style
	1

Bus.

Format –format of the number displayed. For **Text** format, click is to associate displayed text with the value in the value, text format:



If the value is not found in the list, no text will be displayed.

Fixed point - number of fractional bits of a bus number, when displayed in a fixed point format. A number prefix format can be selected in the **Preferences**, **Digital/Bus** tab.

Bus content – select if individual bits of the bus are displayed as separate traces, and how high logic state is shown:

None	~	Bus content
None		
	_	
	_	
	_	
	_	

Time shift, s – trace will be displayed shifted horizontally. Click 1 button to change time shift of selected traces by mouse in transient window. Click this button again to turn this mode off or select another transient cursor mode in the transient window toolbar.

Color - click colored rectangle to select trace color.

Width - enter or select from drop-down list trace width in pixels.

Recalc Math traces manually – if selected, traces of Math type will be recalculated only when

clicking f_x button. Use this option if recalculating traces of Math type takes a long time, and if continuous automatic updating those traces is not required.



ml2 - Transient settings - Screen	×
Image: Indifficie Secting 3 Selecting 3 Image: Indifficie Secting 3 Selection Image: Indifficie Section Annotations Vertical gridlines Selection Fixed vert. gridlines Labels Vertical gridlines Labels Horizontal gridlines Legend Show hor. grid for separated traces Clip separated traces Image: Indifficient Section Preview Digital Analog Horizontal Image: Indifficient Section Start, s Image: Indifficient Section	
Apply	Check traces to be shown in Analog section


Select what is shown on the transient screen (numbers, gridlines, annotations, labels, etc.).

Configure transient graph sections:


- Select **Preview** in the list, then check one trace to be shown in the **Preview** section. Uncheck the trace to hide **Preview** section.
- Select **Digital** in the list, then check traces to be shown in the **Digital** section in **Digital** or **Bus** format. When checked, the trace will be automatically removed from the section where it was currently displayed. When unchecked, the trace will not be shown on the graph.
- Add analog section 👇 add new Analog section (up to 4).
- Select **Analog N** in the list, then check traces to be shown in that section in **Analog** format. When checked, the trace will be automatically removed from the section where it was currently displayed. When unchecked, the trace will not be shown on the graph.
- Maximize analog section 🖸 maximize selected analog section.
- Separate traces = separate traces in the selected analog section.

Special options for Separate traces mode:

- Show hor. Grid for separated traces. If selected, a standard horizontal grid lines are shown for each trace, otherwise only **Top**, **Mid**, and **Bottom** values (if vertical size allows):




- **Clip separated traces**. If selected, a trace will be "clipped" within its area and won't overlap with other traces, otherwise traces from different areas may overlap:



Selected.


Not selected.

Cursors



Lock position – cursors are not moving.

Lock interval – both cursors are moving together keeping same interval between them.



Lock to screen – keep cursors at screen edges.


Left, Right, Interval – enter position of the cursors or interval between cursors.

Move active cursor $\Rightarrow | \neq | = \text{click to move active cursor right/left to min/max data point of selected trace.}$

Table


Transient - Settings - Transient	×
	- X ↑ ↓ ∯ Check all Select all ▼
🕈 🕈 🖾 目 11 🆽 🗉	
✓ Show table Show floating table Show time on the header ✓ Show table cursors on the graph	☑ V(V1) ☑ V(C1) ☑ I(C1)
$ = + + \omega$	
🗹 Select all	
✓ left ✓ right ✓ delta ✓ min	
☑ max ☑ pp ☑ mean	
0 Table cursor, s	
Interval : Cursors V	
300e-3 Left	
600e-3 Right	
Apply	Check traces to be shown in the table

Show table – show/hide the table. **Show floating table** – show/hide table in floating window.



Show time on the header:


	left	right	delta	min	max
Cursors	9.15323	10.7863	1.63306		
V(C1)	1.02711	3.99423	2.96712	593.352e-3	3.9942
V(C3)	2.50229	2.53668	34.3879e-3	1.46046	2.5366
V(C4)	2.80702	2.23147	-575.551e-3	1.57179	2.8070




On

Check trace parameters to be shown in the table.

Custom **Table cursors** can be added to the table. To add a table cursor, enter time in the **Table cursor** field, or set active cursor in the **Transient window** to a desired time, and click **Add table cursor** button:




A new item is added to the list. Now, the **t1** column in the table will show trace values at specified time. Select **Show table cursors on the graph** to show table cursors on the graph:



Select Interval where table data are calculated.

Check traces to be shown in the transient table.






Store last Run – when transient starts, move current transient run to the storage under the name Last. You can always see the difference between a new and previous run.

Use time shift (Scope) - select how segmented memory data are being displayed. See Working with segmented memory chapter of the Scope tool description.

Display storage – specify how to show storage data on the graph:



Selected only

Selected and dimmed

All

Check storage data in list to show it on the graph and table.

Check traces to show storage data for those traces.

More commands

Open data $\stackrel{\frown}{=}$ - open traces and data from a file of **nlt** type. You can select one or multiple files to open. Prefix "Copy of..." will be added to a trace name.

Save data - select traces and save traces with data in a file of **nlt** type, in special NL5 transient data binary format. Traces without data will not be saved.

Import from file - import traces and data from text or binary files created by NL5 or other software tools or instruments. You can select one or multiple files to open. The following file formats (file name extension) are supported:

- **txt**, **csv** text format (comma-separated).
- **wfm** Tektronix waveform format.
- **isf** Tektronix internal format.
- **bin** Keysight Technologies (Agilent) binary format.
- **trc** LeCroy binary format.
- **raw** LTSpice data format.
- **qraw QSPICE** data format.

Text format (txt, csv).

When file is selected, its content is shown in the window for verification and editing:

time(s)	V(V1)	V(C1)	I(C1)	I(B1)		^
0	0	0	0	0		
100e-3	5.87785	293.949e-3	5.5839	5.5839		
200e-3	9.51057	1.02615	8.48442	8.48442		
300e-3	9.51057	1.86454	7.64603	7.64603		
400e-3	5.87785	2.44148	3.43637	3.43637		
500e-3	98.2549e-12	2.4937	-2.4937	-2.4937		
600e-3	-5.87785	1.96245	-7.8403	-7.8403		
700e-3	-9.51057	1.01553	-10.5261	-10.5261		
800e-3	-9.51057	-17.1537e-3	-9.49341	-9.49341		
900e-3	-5.87785	-769.895e-3	-5.10796	-5.10796		
1	-196.51e-12	-981.192e-3	981.192e-3	981.192e-3		
1.1	5.87785	-593.875e-3	6.47173	6.47173		
1.2	9.51057	222.812e-3	9.28775	9.28775		
1.3	9.51057	1.13765	8.37292	8.37292		
1.4	5.87785	1.78376	4.09409	4.09409		~
	re 5 columns and 1 columns and rows to i			e table.		
2 V First column			1	 Header row 	OK	
All	 Number of columns 		1	 Time column 		
2	✓ First row				Cance	

First column - select first column of the data to be imported.

Number of columns - select number of data columns to be imported. To import all available data (after the first column), select **All** from drop-down list (or set this parameter to -1).

First row - select first row of the data to be imported.

Number of rows – select number of data rows to be imported. To import all available data (after the first row), select **All** from drop-down list (or set this parameter to -1).

Header row - select the row whit trace names. If such a row does not exist in the data file, select **Add header** from drop-down list (or set this parameter to 0), and trace names will be added automatically.

Time column - select the column with time. If such a column does not exist in the data file, select **Add time** from drop-down list (or set this parameter to 0), and time will be added automatically with time step specified in **Time step** parameter.

Both comma and Tab delimiters of the text data are accepted.

LTSpice format (raw), QSPICE format (qrow).

List of traces (variables) available in the file will be shown in the **Select traces to import** window. Check traces and click **OK**:

Select traces	to import	
□ V(n001) □ V(n002)		
□ V(n003) ☑ I(C1)		
🗆 I(S1)		
Cheek all	Uncheck all	
CHECK di		

Check traces and Click OK to confirm import.


Scope data formats (wfm, isf, bin, trc).

Please be aware that not all format versions and format-specific options are implemented and tested. If you receive error or warning message, please contact us to provide details about the failure: it would help us fixing the problem and adding new features and options. If you want more formats to be implemented in the NL5, feel free to contact us as well.

Import from clipboard - paste traces in text format from the clipboard. The same selection window as for **Import from file** command will be shown with data obtained from clipboard.

Both comma and Tab delimiters of the text are accepted.

For example, you can select a range with trace data in MS Excel, **Copy** data to clipboard, then **Import from clipboard** to NL5 transient window:



View/Export data • view trace data in the table and save in a file or copy to clipboard in text format. Specify export parameters:

📄 Vie	w/Export	data		— 🗆 X
0	0	0	^	Check all
50e-3	0	0		
100e-3	0	0		V(C1)
150e-3	0	0		✓ V(V1)
200e-3	0	0		
250e-3	488e-3	10		
300e-3	952e-3	10		
350e-3	1.39292	10		
400e-3	1.81269	10		
450e-3	2.21199	10		
500e-3	2.59182	10		Interval : All data 🛛 🗸
550e-3	2.95312	10		
600e-3	3.2968	10		0 Left
650e-3	3.62372	10		5 Bight
700e-3	3.93469	10		
750e-3	3.7428	0		50e-3 Step
800e-3	3.56026	0		Joe J
850e-3	3.38662	0		Significant digits
900e-3	3.22145	0		6 V Time
950e-3	3.06434	0		o v Illie
1	2.91489	0		6 🗸 Data
1.05	2.77273	0		
1.1	2.6375	0		Tab 🗸 Delimiter
1.15	2.50887	0		
1.2	2.38651	44.4089e-15		Copy Export Close
1.25	2.75783	10	\mathbf{v}	Copy Export Close

Check traces to be exported.


Interval – data interval to be exported.

Step – the data are exported with fixed specified time step. Transient data between calculated data points are linearly interpolated.

Significant digits - select significant digits for time and data.

Delimiter – select comma or Tab.
Click Copy to copy data to clipboard.
Click Export to save into the file. Select file name and extension (csv, txt).

To transfer data from NL5 to MS Excel, set **Tab** delimiter, **Copy** data to clipboard, then **Paste** data to Excel spreadsheet:



Copy selected traces - copy selected traces with data to the clipboard.

Paste traces - paste traces with data from the clipboard.


Duplicate selected traces - duplicate (**Copy/Paste**) selected traces with data.

Find component - show the component used for V/I/P trace on the schematic.


Transient Tools

XY diagram

Select **Transient/Transient tools** or click **Transient tools** on the **Transient window** toolbar, select **XY diagram** Olick **Tool settings** to configure XY diagram.



Select trace to be used as **X** axis. Trace name is shown in the windows header. Select **Interval** of transient data to be shown in the XY diagram. **Check** traces in the list to be shown on the graph.



XY diagram shows traces with **Scale** and **Mid** values specified in Transient settings. In addition, XY diagram graph can be zoomed/scrolled by toolbar buttons, mouse (similar to Transient window), or by

setting parameters **Multiplier** and **Offset** in the settings **Screen** tab of Settings window. **Double-click** to center screen.

Right-click on the graph to show context menu.

Show markers - show markers corresponding to active cursor in Transient window.

Show annotations - show annotations defined in Transient window.

Eye diagram

Select **Transient/Transient tools** in or click **Transient tools** on the **Transient window** toolbar, select **Eve diagram**.

Click **Tool settings** ^T to configure Eye diagram.


Trc - Settings - Eye diagram	×
Image: Second secon	 X ↑ ↓ ↓ ↓ Check all Select all ▼ V(V1) V(V1)
Apply	Check traces to be shown on the graph

Select Width of Eye diagram.

Click **1** to use interval between Transient cursors.

Select **Interval** of transient data to be shown in the Eye diagram.

Check traces in the list to be shown on the graph.



Eye diagram shows traces with **Scale** and **Mid** values specified in Transient settings. In addition, Eye diagram graph is zoomed/scrolled by toolbar buttons, mouse (similar to Transient window), or by setting

parameters Multiplier and Offset in the settings Screen 1 tab.

Double-click to center screen.

Right-click on the graph to show context menu.

Show markers - show markers corresponding to active cursor in Transient window.

Show annotations - show annotations defined in Transient window.

Amplitude histogram

Select **Transient/Transient tools** is or click **Transient tools** on the **Transient window** toolbar, select **Amplitude histogram**.

Click **Tool settings** ^T to configure Amplitude histogram.

Trc - Settings - Amplitude histogram	×
	X ↑ ↓ ‡ Check all Select all
Interval: All data	
Apply	Check traces to be shown on the graph

Select **From** and **To** of Amplitude range. Select number of **Bins** within Amplitude range.

Linear interpolation (between transient data points). NL5 calculates transient response at discrete time points and then displays traces connecting those points by straight lines. If **Linear interpolation** option is selected, such linearly interpolated signal will be used as a source for amplitude histogram. For slow changing signal linear interpolation provides quite accurate approximation of a real signal, so that amplitude histogram will give quite accurate and reliable results.

However, if the signal is supposed to have only discrete amplitude levels with fast transition between those levels comparing to simulation step, such an interpolation may produce wrong results: the histogram may show signal amplitudes between discrete states which do not exist in real signal. Use **Linear interpolation** option to obtain accurate histogram for specific signals.

Autoselect range and Scales 🔁 - set Amplitude range to minimum and maximum of the signal and perform **Fit the screen** of the histogram.

Select **Interval** of transient data to be shown in the Eye diagram. **Check** traces in the list to be shown on the graph.

· rc - Transient		- 0	🗙 🛛 🚠 rc -	- Amplitude histogram	- 🗆	\times
<u> </u>	∃ ➔│ 🖹 🗳 🏕 👷 🔠	91 🕄 🗉 🔳 🗷 🕅 🗖	~ [à 🔁 🜌 🛼 📃		
1 500e-3	V(V1)	(1)	 ▲ ▲ ↓ ↓			 <!--</td-->
0 - <u>1</u> 00e-3			↔ ↓ <		}	
3 { Run/	4 t= 10 16	5 MB Click 3.60721 7.1001				< 2 5 E

Zoom, scroll, mouse, and mouse-wheel operations are the same as in Transient window.

Double-click to center screen.

Right-click on the graph to show context menu.

Show markers - show markers corresponding to active cursor in Transient window.

Show annotations - show annotations defined in Transient window.

View/Export into text file or copy to clipboard:

View/Ex	port
bin_start	V(V1)
-10	0
-9.33333	0
-8.66667	1.16832e-3
-8	1.16832e-3
-7.33333	11.6832e-3
-6.66667	28.0396e-3
-6	75.9405e-3
-5.33333	172.911e-3
-4.66667	389.049e-3
-4	778.098e-3
-3.33333	1.27346
-2.66667	2.13568
-2	2.79227
-1.33333	3.56219
-666.667e-3	3.93985
0	3.95299
666.667e-3	3.39396
1.33333	2.73882
2	2.04222
2.66667	1.29333
3.33333	761.742e-3
4	357.504e-3

Check traces to be exported.


Significant digits - select significant digits for data.

Delimiter – select **comma** or **Tab**.

Click **Copy** to copy data to clipboard.

Click **Export** to save into the file. Select file name and extension (csv, txt).

To transfer data from NL5 to MS Excel, set **Tab** delimiter, **Copy** data to clipboard, then **Paste** data to Excel spreadsheet:



FFT

Select **Transient/Transient tools** in or click **Transient tools** on the **Transient window** toolbar, select **FFT**

Click **Tool settings** ^T to configure FFT.

Trc - Settings - FFT	×
	■ X ↑ ♣ ☆ ✓ Check all <u>Select all</u> ▼
256 FFT points None Zero padding None Window None Divide by Image: Show FFT traces in AC window Image: Show FFT points in Transient Traces Image: Line Bars Histogram Points Interval : All data Image: Left Image: Structure	✓ V(1) ✓ V(C1) ✓ I(C1)
Apply	Check traces to be shown on the graph


Points – number of FFT points.


Zero padding - add zeroes to transient samples. Zero padding is a standard technique to improve spectral resolution.

If total number of FFT points, including zero padding, is too high (>=65536), a warning sign \bigcirc will show up. When move mouse over the sign, a hint message will be shown:


F	FT			
	32768	/	Points 🚺	•
	X2 N	/	Zero padding	FFT calculation may be slow:
	None N	/	Window	too many data points

Window – select window type. Windowing is a standard technique to reduce leakage effects and improve spectral resolution.





Traces - several trace options can be selected at a time:




Select Interval of transient data to be used for FFT calculation.

Divide by – FFT for all traces will be divided by FFT of specified trace (except that specified trace).

Show FFT traces in AC window \bigcirc - show FFT traces in AC window as well as in FFT window. The name of the traces will be "FFT of *trace name*". Working with AC traces in AC window allows using cursors and Data table.

Show FFT points in Transient - show points of transient trace which are used to calculate FFT for that trace. This feature may help to detect possible aliasing or other problems. Here is an example of aliasing when signal frequency is higher than Nyquist frequency:







Check traces in the list to be shown on the graph.

Zoom, scroll, mouse, and mouse wheel operations are the same as in **AC Window**. **Double-click** to center screen.

Right-click on the graph to show context menu.

Phase display:

- **Phase Off** : phase not shown.
- **Phase On** \bowtie : phase is shown in the same window as magnitude.
- **Phase separate** : phase is shown in separate window (bottom section).

Phase is shown in -180...+180 degrees range. However, for FFT trace divided by another trace, the phase is adjusted to show continuous phase in wide range.

FFT data point at **zero frequency** is not shown.

View/Export i - view FFT data in the table and export into text file (comma-separated):

View/E	xport			— 🗆 X
f(Hz)	V(V1)	Phase	~	Check all
0	-66.5799	90		
27.1673e-3	-37.9543	-15.4116		V(V1)
54.3347e-3	-28.0009	-100.309		
81.502e-3	-23.6775	170.507		
108.669e-3	-22.0493	79.9618		
135.837e-3	-21.7603	-11.7038		
163.004e-3	-21.8491	-104.562		
190.171e-3	-21.8007	162.253		
217.339e-3	-21.6244	69.9557		
244.506e-3	-21.4709	-21.7518		
271.673e-3	-21.328	-114.254		
298.841e-3	-21.1253	152.43		Show phase
326.008e-3	-20.9107	59.9024		
353.175e-3	-20.737	-31.5957		Significant digits
380.343e-3	-20.5067	-123.918		6 V Frequency
407.51e-3	-20.1542	142.489		
434.677e-3	-19.8333	49.7868		6 🗸 Data
461.845e-3	-19.637	-41.3855		
489.012e-3	-19.3268	-133.529		Tab 🗸 Delimiter
516.179e-3	-18.7588	132.466		
543.347e-3	-18.2721	39.5654		Copy Export Close
570.514e-3	-18.0815	-51.1323	~	Copy Capbran Close

Check traces to be exported.

Significant digits - select significant digits for frequency and data.


Delimiter – select **comma** or **Tab** (use Tab to export data to MS Excel). Click **Copy** to copy data to clipboard.

Click **Export** to save into the file. Select file name and extension (csv, txt).

Transient histogram

Select **Transient/Transient tools** in or click **Transient tools** on the **Transient window** toolbar, select **Transient histogram**.


Click **Tool settings T** to configure Transient histogram.




 \mathbf{Y} - histogram will display data calculated in the interval specified for Transient table (Transient table does not need to be shown).

X:

- **Traces**: show data as function of traces:





- **Storage**: show data as function of storage:

Check traces in the list to be shown on the graph.

Zoom, scroll, mouse, and mouse-wheel operations are the same as in Transient window. **Right-click** on the graph to show context menu.

On the Screen tab • of Settings window, select Trace type: Line or Histogram.

Power


Select **Transient/Transient tools** in or click **Transient tools** on the **Transient window** toolbar, select **Power P**.

Select Power Factor tab to calculate voltage and current RMS, power, and Power Factor.

- V trace: select voltage trace from the drop-down list.
- I trace: select current trace from the drop-down list.

Power factor **PF** is calculated as: $PF = \frac{Power}{VRMS \times IRMS}$

All parameters are calculated between cursors. For better accuracy, provide integer number of signal cycles between cursors.




Select THD tab to calculate Total Harmonic Distortion.

- **Trace**: select trace from the drop-down list.
- Harmonics: enter or select from drop-down list number of harmonics to calculate.

THD is calculated as: $THD = \frac{\sqrt{V_2^2 + V_3^2 + V_4^2 + \dots}}{V_1}$, where V_n is amplitude of nth harmonic.

THD is calculated between cursors. Please make sure that selected interval consists of exactly **1 period** of the signal fundamental (1st harmonic).




If calculation step is too big, higher harmonics may not satisfy Nyquist criteria: harmonic frequency exceeds half of discretization frequency. Such harmonics will be marked with an asterisk (*) symbol in the harmonics list.

DC sweep

Select **Transient/Transient tools** in or click **Transient tools** on the **Transient window** toolbar, select **DC sweep**.

DC sweep tool performs calculation of DC operating point while changing specified component parameter or variable in specified range and plots transient traces as a function of that parameter. The name of the parameter is shown in the header of the DC sweep window.




Click **Tool settings** $ilde{T}$ to configure DC sweep.

- **Parameter**: name of the parameter to be changed. Enter parameter name manually or select from drop-down list. The list shows parameters of the component which is currently selected in the schematic.
- **From, To**: range of parameter change.
- **Points**: number of points.

Check traces in the list to be shown on the graph.

Click **Start DC sweep** [➡] to perform DC sweep.



Double-click to center screen.

Right-click on the graph to show context menu.

Zoom, scroll, mouse, and mouse-wheel operations are the same as in Transient window.

View/Export i - view DC sweep data in the table and export into text file or copy to clipboard:

View/E	xport			— 🗆 X
V1.V	V(V1)	V(R1)	^	Check all
0	0	0		
20.202e-3	20.202e-3	0		✓ V(V1)
40.404e-3	40.404e-3	0		V(R1)
60.6061e-3	60.6061e-3	0		
80.8081e-3	80.8081e-3	0		
101.01e-3	101.01e-3	0		
121.212e-3	121.212e-3	0		
141.414e-3	141.414e-3	0		
161.616e-3	161.616e-3	0		
181.818e-3	181.818e-3	0		
202.02e-3	202.02e-3	0		
222.222e-3	222.222e-3	0		
242.424e-3	242.424e-3	0		
262.626e-3	262.626e-3	0		Significant digits
282.828e-3	282.828e-3	0		
303.03e-3	303.03e-3	0		
323.232e-3	323.232e-3	0		6 🗸 Data
343.434e-3	343.434e-3	0		
363.636e-3	363.636e-3	0		Tab 🗸 Delimiter
383.838e-3	383.838e-3	0		
404.04e-3	404.04e-3	0		Copy Export Close
424.242e-3	424.242e-3	0	\mathbf{v}	Copy Enport

Check traces to be exported.

Significant digits - select significant digits for data.

Delimiter – select comma or Tab (use Tab to export data to MS Excel).

Click **Copy** to copy data to clipboard.

Click **Export** to save into the file. Select file name and extension (csv, txt).

V. AC analysis

Algorithm

There are two methods of AC analysis in NL5: Linearize schematic and Sweep AC source.


Linearize schematic is a standard low-signal AC analysis. First, all non-linear components are replaced with linear equivalents at their operating point. Second, a signal of specified frequency with unit amplitude and zero phase is applied to the input node, and signals at other nodes are found by solving a system of linear equations. The process is repeated for specified number of frequencies.

In order to linearize schematic, state of all components should be known. It can be done manually by setting Initial Conditions (IC) for non-linear components, diodes, and controlled switches, or by automatic calculation of DC operating point (**Calculate DC operating point** check box in the **AC Settings**). DC operating point is calculated exactly as in transient analysis.

Sweep AC source method allows calculating AC response for any type of circuit, including switching circuits. A real sine-wave signal of specified amplitude and frequency is applied to the input node; the transient analysis is automatically performed; finally, the harmonic of specified frequency is extracted form signals of interest by Discrete Fourier Transform (DFT). AC response is calculated by comparison of the harmonic amplitude and phase of the specified signal to the input signal. This process is repeated for specified frequency range.

Transient simulation is automatically started and controlled by the method. Currently selected transient simulation step will be used. Please note that all existing transient data will be deleted when AC simulation starts.

AC source \bigcirc . Any voltage source, current source, or label can be used as AC source. Component selected as AC source will be marked with "(AC)" text on the schematic and in the **Components window**:



The AC source component may have any model (except **SubCir, Label, and IC**): the model will be ignored for **Linearized schematic** method and temporarily set to **Sin** for **Sweep AC source** method. DC voltage/current of the component will be set to its DC value at t=0, and AC voltage/current required for AC analysis will be added to that DC level.

Traces. NL5 only stores data for specified traces.

Running AC analysis

T - Go to **Settings window** (then select desired AC settings tab).

- Start AC (available on the Schematic and AC window toolbars). When simulation is running, schematic cannot be edited, and component parameters/model cannot be changed.

₩ - Stop AC.

- Sweep parameter. Open Tools window, Sweep tab. See Tools chapter for details.

- Show AC log.

AC window



Storage tab

Status bar

Add AC traces using any of the following methods:

- Go to Settings window 🌋 , Add traces 🎐 tab, see detailed instruction below.
- **Right-click** on the component in the schematic window, select **Add trace** $\stackrel{\text{magenta}}{\longrightarrow}$, then select trace type.
- Select component in the **Components window**, click **Add trace** X J button.

Go to Settings window \square , Format traces \square tab to select trace color, scales, etc.

Go to Settings window 🔀 , Screen 🔁 tab to configure AC window scales and other properties.

Scales. All traces are shown with the same scales, which can be linear or logarithmic.

Phase display method selection:

- **Phase off** \square do not show phase, magnitude only.
- **Phase On** \square show magnitude and phase in the same window.
- **Phase separate** $\stackrel{\text{les}}{\rightleftharpoons}$ show magnitude and phase in separate sections of the window.

Mouse. There are 3 modes of mouse operation:

Cursors P mode. Some mouse operations apply to AC cursors P:

- **Double-click** the screen to show cursors and/or reset cursors lock modes.
- Click on the screen to move closest cursor to that point.
- Place mouse pointer over the cursor, then click and drag to move the cursor.
- Press Left/Right arrow key with Ctrl, Shift, or Ctrl-Shift keys to move active cursor with different step resolution.

Zoom mode (press and hold **Ctrl** key to switch to **zoom** mode temporarily). Click and drag to select horizontal, vertical, or rectangle area to be zoomed-in:







Move mouse pointer diagonally to select rectangle area.

Move mouse pointer horizontally to select horizontal area.

Move mouse pointer vertically to select vertical area.

Scrolling mode (press and hold **Shift** key to switch to **scrolling** mode temporarily). Click and drag to scroll the screen.

Mouse wheel:

Mouse wheel – horizontal zoom (relative to mouse pointer position). Shift-mouse wheel – horizontal scroll. Ctrl-mouse wheel – vertical zoom (relative to mouse pointer position). Ctrl-Shift-mouse wheel – vertical scroll.

Keys and shortcuts:

F8 – show AC window \frown F9 - start AC \rightarrow Tab – toggle Phase display mode \frown \bullet \frown \bullet \bullet <tr

Shift-PgUp, Shift-PgDn – vertical and horizontal zoom. Shift-Home – fit the screen ♥.

Ctrl-Right, Ctrl-Left, Shift-Right, Shift-Left, Ctrl-Shift-Right, Ctrl-Shift-Left - move selected cursor with different resolution.

Status bar

Right-click status bar to configure:

Click to move cursor	44.6244e-3	146.79- 0	100 150- 0
_,		~	Progress
		~	Cursors
		~	Interval

- **Progress** current frequency of AC simulation.
- **Cursors** show cursors position (left and right).
- **Interval** interval between cursors.

Cursors

Cursors specify interval that can be used for **AC table** and **AC tools**.

- Go to **Cursors** tab of **Settings window** to configure cursors options and perform some operations on cursors.
- Click **Show cursors** to show/hide cursors. Please note that table and AC tools may use specified **Cursors** interval type even when cursors are hidden.
- Click **Cursors to screen** to set horizontal scale to cursors position.

Legend

Legend shows list of traces currently displayed on the graph. Legend is also available in all **AC tools**.

- Click **Show legend** to show/hide legend.
- **Click** on the border of the legend and drag to move the legend window.
- **Click** on the trace in the legend to select one trace.
- **Ctrl-click** to select more than one trace or unselect the trace.
- **Right-click** to see context menu with more selection options.
- Go to **Preferences** A, Legend tab to select legend style (colors, font). The style can be defined manually or selected from two predefined options (NL5 Ver.2 and NL5 Ver.3), and then adjusted manually if needed.

Annotations

Annotation sis a text with a pointer, which always points to the same data point of a trace, even when graph is zoomed or scrolled:




- To add annotation, set cursor to the frequency point where annotation is needed, **right-click** the graph, select **Annotate**, then select **Selected traces** or **All traces**.
- Go to **Preferences** A, **Annotation** tab to configure annotation colors, font, and some other common properties.
- **Double-click** on the annotation, or **right-click** the annotation and select **Edit annotation** to edit (customize) specific annotation:

🛃 Edit annot	ation X
✓ Name Frequency Value	E = = ∴ b. Apply to all annotations
Enter text here	^
<	>
	Close

- **Click** and drag annotation text to move the text while keeping pointer at the same data point.
- **Click** and drag the end of the pointer to move annotation pointer to a different data point. The pointer will follow the mouse pointer, staying at the nearest point of the trace (trace data between data points are linearly interpolated).
- Annotations defined on the AC graph can also be displayed on the **Smith chart** and **Nyquist plot** AC tools.

Text

Right-click on the graph, select **Insert text**



If graph is zoomed or scrolled, the text stays at the same place, anchored to the left-top corner of the graph window.

- **Double-click** on the text, or **right-click** on the text and select **Edit text** to edit or configure the text.
- Click and drag the text window to move it. If pointer is locked, only text will move.
- **Click** and drag the end of the pointer to move the pointer only.


Table

 Table
 Image: Shows cursors position, trace values, and some characteristics of the traces calculated in specified interval (Cursors, Screen, All data, Selection).

- Go to Settings window \square , Table \blacksquare tab to configure the table.
- Click **Show table** to show/hide the table.
- Click **Floating table** \square to show the table in a floating window. Click \square and \square any time to switch between window modes.
- **Right-click** the table to see context menu with table-related commands.
- **Right-click** / **Copy** to copy content of the table cell to the clipboard.

Storage

Storage can be used to keep the data for further analysis and comparison. When simulation is performed, AC data are shown on the graph, and a tab named **Run** corresponding to current transient data is shown in the **Storage tab**:




When new simulation is started, current simulation data are deleted. To keep it for further analysis and comparison, it can be saved into **storage**.

Right-click the graph or **Storage tab**, and select **Move Run to storage** $\stackrel{\clubsuit}{\rightarrow}$, then enter storage name:

Storage		
Move run to storage Enter storage name:		
Run1		
	OK	Cancel


Simulation data will be moved to the storage, and a tab corresponding to the stored data will appear in the **Storage tab**. Also, storage is used for **Sweep parameter** $\overset{\textcircled{}}{\Rightarrow}$ operation.


Stored data can be displayed in different ways, for example:



- Go to Storage 트 tab of Settings window 🌋 to configure storage.
- **Right-click** the graph or **Storage tab** for storage-related commands.

AC settings





AC source – enter the name of AC source component or select the name from drop-down list.

AC source can also be selected using any of the following methods:

- Right-click on the component in the schematic window, select Add trace $\stackrel{\text{res}}{\sim}$, then select Set AC source $\stackrel{\text{res}}{\circ}$.
- Select component in the **Components window**, click **Set AC source O** button.

The component selected as AC source will be marked with (AC) text on the schematic and in the **Components window**.

Frequency - select how frequency simulation points are specified.

- Interval. Specify frequency interval, number of simulation points, and scale (Lin/Log).
- List. Specify custom frequencies. Enter frequencies one per line in any order. Click Sort and

Refresh \checkmark to verify and sort entered numbers. Click **Edit frequency list** to create and edit frequency list in the **Frequency list** window:

Image: Constraint of the state of the	Frequency list		×
	1e+3 2e+3 4e+3 8e+3 15e+3 32e+3 54e+3 128e+3	Interval 1e+3 128e+3 2 ~ Log ~	To, Hz Points Scale

Method – select AC method.

Linearized schematic:

- Calculate DC operating point – use this option for non-linear schematic if needed.

Sweep AC source:

Method : Sweep AC source 🛛 🗸				
0.1	AC amplitude (f)			
10	Error, %			
☐ Find periodic operating point ☑ Sweep frequency from high to low ☐ Show transient				

- **AC amplitude** (**f**). Amplitude of AC source, **V** for voltage source and label, **A** for current source. Amplitude can be a constant or function of frequency **f**. For example:

0.1 1m*f 1000/f

Frequency-dependent amplitude may be useful to improve signal-to-noise ratio for switching circuits with frequency-dependent gain.

- Error, %. Expected error of AC analysis.
 - **Error** = **0** provides the most accurate simulation results. Transient simulation at each frequency will be performed for 128 periods of that frequency, which may result in a long simulation time.
 - **0** < **Error** < **100** provides reasonable accuracy for most schematics. Transient simulation at each frequency will be performed for 2...128 periods of that frequency; specific number of periods is automatically selected based on requested accuracy.
 - **Error** = 100 provides fastest simulation. Transient simulation at each frequency will be performed for 2 periods of that frequency, which may result in poor accuracy.
- **Find periodic operating point.** Run transient with zero amplitude of AC source prior to AC analysis until periodic steady state is reached. It is highly recommended either to have this option selected or to run transient manually until periodic steady state is reached, and then save transient

Initial Conditions

- **Sweep frequency from high to low.** Perform AC simulation starting from higher frequencies. This option allows to start seeing simulation results faster.

- **Show transient.** Show Transient window during simulation and keep transient data obtained during AC simulation. Transient data might be useful for finding optimal AC analysis settings and for troubleshooting.

Advanced settings ⁷ - more AC settings.


Advanced sett	ings	×
Transient AC		
Z0 for Gam	ma and VSWR traces	
z parameter z =	for 'z-function' component	

- **Z0 for Gamma and VSWR -** characteristic impedance for Gamma and VSWR traces.
- **Z parameter** define custom formula for Laplace-space approximation of z-transform parameter *z* or select formula from drop-down list. For example:

```
exp(s*1e-6)
exp(s*T)
(2+s*T)/(2-s*T)
```

This parameter is used only by **z-function** components.

Add traces



V, **I**:

Select one or more components in the list, then click **Add new trace** or **double-click** on the component in the list.

To add trace in the **Schematic window**, **right-click** on the component, select **Add trace** $\stackrel{\text{magenta}}{\longrightarrow}$, then select trace type.


To add traces in the **Components window**, select component and click \checkmark or \checkmark .

Z, Gamma, VSWR:

Click Add new trace or double-click on the trace type name in the list. Show impedance (Z), reflection coefficient (Gamma), or voltage standing-wave ratio (VSWR) relative to AC source.

Open loop:

Click Add new trace or double-click on the trace type name in the list. Open loop trace shows open loop transfer function of the circuit operating in close loop mode. To use Open loop trace, insert AC source at proper place inside the closed loop, for example:



Function:

Click Add new trace, then enter function. The function may consist of arithmetic operators and functions, component parameters, global variables of C-code components, names of existing traces, V and I on the component, and the following variables:

f – current AC frequency. w – angular AC frequency, w = $2\pi f$. s or p – Laplace parameter, s = p = j* $2\pi f$.

For example:

```
V(C1)/I(C1)
1/(1+s)
V(R1)*f
```

Please note that in **Linearized schematic** method, V/I on the component can be used even if V/I trace for that component is not defined. In **Sweep AC source** method V/I trace should be defined.

Use function to display V/I/P on the components inside subcircuits, for example:

V(X1.R1) - voltage at R1 in the subcircuit X1.

The function is calculated only during simulation: if function is changed, it will not be immediately recalculated.

Math:

Click **Add new trace**, then specify **Math** trace :

Ad	d trace					×
	Operation					
	Function				\sim	OK
	E					
	Function				~	Cancel
					-	
-	Interval :	Cursors	~			
	845.5	575e-3		Left		
	189.7	734e+3		Right		

Select **Operation**, then enter parameters required for that operation (if any). Specify **Interval** where **Math** trace will be calculated.

The **Math** trace is **post-processing** type of trace: it is recalculated automatically when simulation completed, and if trace type, parameters, or interval changed.

The **Math** trace also applies to source **storage** data and is displayed as a **Math** trace storage. While normal trace storage is never changing, **Math** trace storage is automatically recalculated in case of operation or parameters changed, or trace range changed.

Details and examples of some Math types:

Function. Enter a function expression in the **Function** window. The function may consist of arithmetic operators and functions, component parameters, global variables of **C-code** components, any other traces, and the following variables:


f - current AC frequency. w - angular AC frequency, w = $2\pi f$. s or p - Laplace parameter, s = p = $j*2\pi f$.

For example:

```
V(C1)/ R1.R
1/(1+s)
V(R1)*f
```

To access a specific storage data, use a trace name.storage name notation:

```
trace.Run1-trace.Run2
```



Min, Max. Calculate specified value of selected trace.

lit trace: Max of V(C1)	×	🔁 rc - AC — 🗆	\times
Operation			
Max ~	OK	20 dB	N
Trace	Cancel		5 5
V(C1) ~		0 dB	•
			++ +
			1
		-20 dB	1
			\$
Interval : Cursors V		<i>0</i>	₫
68.3026e-3 Left			C
384.582e-3 Right		10e-3 100e-3 1 v	I
		Run/ 68.3026e-3 384.582e	e-3

Format traces

Trc - Settings - AC	×
V(C1) Trace Wag/Phase Display Color 1 Vidth 1 Phase width Line Data points	
Advanced formatting Apply	Check traces to be shown on the graph

Check traces to be shown on the AC graph.


Select one or more traces (using **Ctrl** and **Shift** keys) to perform operations on selected traces. Click **Select All** to select all traces. Traces can also be selected in the **Legend** area of the AC window. The top toolbar provides various operations on selected traces and trace data.

If more than one trace of different type selected, only parameters applicable to **all** selected traces will be shown. If parameter has different values for different traces, its field will be blank. If color is different, it

will be displayed like this: Color . If a new value is entered in an empty field, that value will be assigned to all selected traces.

Trace/Function/Math. This field indicates trace type and is available for editing for **Function** trace only. For **Function** and **Math** trace, click **b** to edit the trace.

Name. Enter trace name which will be shown instead of **Trace**. To be used in formulas, it should satisfy C-language standard for the variable name: start with letter or '_', and then contain only letters, digits, and '_'. Otherwise, you will be given a warning:




Display defines how the trace will be displayed:

- **Mag/Phase** magnitude and phase.
- **Re** real part.
- **Im** imaginary part.

Color - click colored rectangle to select trace color.Width - enter or select from drop-down list trace width in pixels.Line – show lines.Data points – show simulation data points.

Select Advanced formatting to allow advanced formatting capabilities:






👕 rc - Settings - AC	×
Normal Principal Structure Image:	
Horizontal gridlines Horizontal Log 1e-3 Left, Hz 1e+3 Right, Hz	V(C4)
Vertical Log dB 40 Top -80 Bottom	
Phase: Separate V 180 V -180 Bottom	
Apply	Check traces to be shown on th graph

Select what is shown on the AC screen, set scales of the graph.


Phase - select phase display mode:

- **Off -** do not show phase.
- **On s**how magnitude and phase in the same area of the graph.
- Separate show magnitude and phase in separate areas of the graph.




Press Tab in the AC Window to toggle Phase display mode.





Lock position – fix cursors position, do not move.

Lock interval – always move both cursors keeping same interval between them.



Lock to screen – keep cursors at screen edges.

Left, Right, Interval – enter position of the cursors or interval between cursors. Move active cursor:

 $| \ddagger | \ddagger | \ddagger | \ddagger | = move active cursor right/left to min/max data point of selected trace.$


 $\frac{1}{2}$ – move active cursor right/left to unity gain point of selected trace.

Table ⊞

Tnl1 - Settings - AC	×
🔁 🕶 🖙 🔛 🔂 🔂 🔂 🖷 😁	- X 🛧 🖊 👯
🕈 🔶 🕅 🔁 👎 🖽 📃	Check all <u>Select all</u>
Show table Show floating table Show frequency on the header Show table cursors on the graph	 ✓ (V1) ✓ (C1) ✓ (C1)
+ = + + ∞	
☑ Select all	
✓ left ✓ right ✓ delta ✓ min ✓ max ✓ pp ✓ stope ✓	
0 Table cursor, Hz	
Interval : Cursors 🗸	
100 Left	
10e+3 Right	
Apply	Check traces to be shown in the table

Show table – show/hide the table.

Show floating table – show/hide table in floating window.



Show frequency on the header:

🜐 rc - AC	table					\times
	left	right	delta	min	max	
Cursors	7.58052e-3	308.121e-3	300.541e-3			
V(C1)	297.75e-3	-26.7505	-27.0482	-26.7505	8.99742	
V(C2)	239.139e-3	-36.1431	-36.3823	-36.1431	7.56486	
V(C3)	229.297e-3	-42.9083	-43.1376	-42.9083	7.28022	



Cursors	7.58052e-3	308.121e-3	300.541e-3	min	max
V(C1)	297.75e-3	-26.7505	-27.0482	-26.7505	8.99742
V(C2)	239.139e-3	-36.1431	-36.3823	-36.1431	7.56486
V(C3)	229.297e-3	-42.9083	-43.1376	-42.9083	7.28022



Check trace parameters to be shown in the table.


slope – magnitude slope between cursors, in dB/decade. If cursors are located at the same frequency, slope is calculated as magnitude derivative at this frequency, otherwise slope is calculated as (Mag right – Mag left) / (\mathbf{f} right – \mathbf{f} left).

Custom Table cursors can be added to the table.

To add a table cursor, enter frequency in the **Table cursor** field, or set active cursor in the **AC** window to a desired frequency, and click **Add table cursor** button:

🕂 🗕 🛧 🖊	ŝ	
🗹 Select all		
⊠ min ⊠ max		^
⊻ pp ✓ slope ✓ f1=16		
M <u> 11=16</u>		۷
16	Table cursor, Ha	z


A new item is added to the list. Now, the **f1** column in the table will show trace values at specified frequency. Select **Show table cursors on the graph** to show selected table cursors on the graph;



Select Interval where table data are calculated.


Check traces to be shown in the AC table.





Store last Run – when AC starts, move current AC run to the storage under the name **Last**. You can always see the difference between a new and previous run.

Display storage – specify how to show storage data on the graph:



Check storage data in list to show it on the graph and table.

Check traces to show storage data for those traces.

More commands.

Open data $\stackrel{\frown}{=}$ - open traces and data from a file of **nlf** type. You can select one or multiple files to open. Prefix "Copy of..." will be added to a trace name.

Save data - select traces and save traces with data in a file of nlf type, in special NL5 AC data binary format. Traces without data will not be saved.

Import from file - import traces and data from text or binary files created by NL5 or other software tools/applications. You can select one or multiple files to open. The following file formats (file name extension) are supported:

- **txt, csv** text format (comma-separated).
- **raw** LTSpice data format.
- **qraw QSPICE** data format.

Text format (txt, csv).

Empty lines and comment lines started with ';' symbol are skipped.

The first line (after skipped) can be a header line, having any text in the first column, followed by comma, space, or Tab separated names of the traces. If name of the trace consists of symbols other than numbers and letters, it should be enclosed in quotes.

All other lines are considered as trace data. The first column of the data consists of frequency (in Hz), other columns are trace data.

Trace data may have one column per trace, or two columns per trace. The first column is magnitude (absolute value, or dB), and it has trace name in the header line. The second column, if exists, is phase (in degrees), and it has "phase" text in the header line. If second trace column does not exist, the phase is set to zero. The data can be comma, space, or Tab separated. For example:

```
f(Hz),V(C1),phase,V(R1)
1,-1,-15,0
3,-2,-30,3
10,-8,-40,4
30,-20,-50,5
```

When file is selected, its content is shown in the window for verification:

📑 Import o	lata		— C	X	
f(Hz)	V(C1)	phase	V(B1)		
1	-1	-15	0		
3	-2	-30	3		
10	-8	-40	4		
30	-20	-50	5		
Skip lines : 0					
Skip columns : 0					
Insert he	ader line			Lancel	
 ⊡ Data in dB					

Skip lines - specified number of lines in the beginning to skip.
Skip columns - specified number of columns starting from the left to skip.
Insert header line – add header line "f(Hz), trace1, trace2 …".
Data in dB - a magnitude is dB.

Check traces and Click **OK** to confirm import.

LTSpice format (raw), QSPICE format (qrow).

List of traces (variables) available in the file will be shown in the **Select traces to import** window. Check traces and click **OK**:


Select traces	to import	
 V(n001) V(n002) V(n003) ✓ I(C1) 		
✓ I(C1) □ I(S1) ✓ I(V2) ✓ I(V1)		
Check all	Uncheck all	
Crieck all		Cancel

Check traces and Click **OK** to confirm import.

Import from clipboard - paste traces in text format from the clipboard. The same selection window as for **Import from file** command will be shown with data obtained from clipboard.

Both comma and Tab delimiters of the text are accepted.

For example, you can select a range with trace data in MS Excel, **Copy** data to clipboard, then **Import from clipboard** to NL5 AC window:



View/Export data • view trace data in the table and save in a file or copy to clipboard in text format. Specify export parameters:

View/E	xport data			— 🗆 X
1e-3	-171.449e-6	-359.995e-3	٨	Check all
1.14976e-3	-226.658e-6	-413.912e-3		
1.32194e-3	-299.643e-6	-475.902e-3		V(C1)
1.51991e-3	-396.125e-6	-547.174e-3		
1.74753e-3	-523.67e-6	-629.118e-3		
2.00923e-3	-692.275e-6	-723.33e-3		
2.31013e-3	-915.155e-6	-831.647e-3		
2.65609e-3	-1.20977e-3	-956.177e-3		
3.05386e-3	-1.59922e-3	-1.09935		
3.51119e-3	-2.11399e-3	-1.26394		
4.03702e-3	-2.79439e-3	-1.45315		Interval : All data 🗸 🗸
4.64159e-3	-3.69366e-3	-1.67066		
5.3367e-3	-4.88215e-3	-1.92068		1e-3 Left
6.13591e-3	-6.45275e-3	-2.20804		1e+3 Right
7.0548e-3	-8.52806e-3	-2.5383		
8.11131e-3	-11.2699e-3	-2.91781		100 Points
9.32603e-3	-14.8917e-3	-3.35383		100 Tomas
10.7227e-3	-19.6747e-3	-3.85465		Significant digits
12.3285e-3	-25.9892e-3	-4.42973		6 V Frequency
14.1747e-3	-34.3221e-3	-5.08982		o • Hequency
16.2975e-3	-45.3127e-3	-5.84706		6 🗸 Data
18.7382e-3	-59.7983e-3	-6.71515		
21.5443e-3	-78.8724e-3	-7.70938		Tab 🗸 Delimiter
24.7708e-3	-103.958e-3	-8.84671		
28.4804e-3	-136.896e-3	-10.1456		Copy Export Close
32.7455e-3	-180.061e-3	-11.6262	\mathbf{v}	Copy Export Close

Check traces to be exported in the list.

Interval – data interval to be exported.

Points – number of frequency points to view/export. AC data between calculated data points are linearly interpolated.


Significant digits - select significant digits for time and data.

Delimiter – select comma or Tab.

Click **Copy** to copy data to clipboard.

Click **Export** to save into the file. Select file name and extension (csv, txt).

To transfer data from NL5 to MS Excel, set **Tab** delimiter, **Copy** data to clipboard, then **Paste** data to Excel spreadsheet:



Copy selected traces • - copy selected traces with data to the clipboard.

Paste traces - paste traces with data from the clipboard.

Duplicate selected traces ^{••} - duplicate (**Copy/Paste**) selected traces with data.

Find component - show the component used for V/I/Z/Gamma/VSWR/Open loop trace on the schematic.

AC Tools

Smith chart

Select AC/AC tools $\stackrel{\scriptstyle{\swarrow}}{\sim}$ or click AC tools $\stackrel{\scriptstyle{\leftrightarrow}}{\sim}$ on the AC window toolbar, select Smith chart $\stackrel{\scriptstyle{\textcircled{}}}{\boxtimes}$. Click Tool settings $\stackrel{\scriptstyle{\frown}}{\top}$ to configure Smith chart.


Trc - Settings - Smith chart	×
🛞 - 🛩 🔂 🖬 🖍 🌬 😁 •	- X + + #
T 🗵 🔂 目	Check all Select all
50 Z0. Ohm	Z
Z and Gamma traces only	
Status	
B	
Phase	
Gamma	
Interval : All data 🗸	
0 Left	
0 Bight	
Apply	Check traces to be shown on the graph

Z0, Ohm - characteristic impedance of the Smith chart.

Z and Gamma traces only - if selected, show only Z (impedance) and Gamma (reflection coefficient) traces, otherwise show all traces interpreted as complex impedance.

Status - what to show on the window status bar. Values shown correspond to mouse pointer position. Select **Interval** of AC data to be shown in the Smith chart.

Check traces in the list to be shown on the graph.




Zoom, scroll, mouse, and mouse-wheel operations are the same as in AC window. **Double-click** to center screen.

Right-click on the graph to show context menu.


Show markers - show markers corresponding to active cursor in AC window.

Show annotations - show annotations defined in AC window.

Click **Screen** to see **Screen** tab of Settings window:



Grid – select grid type (or press Tab in Tool window to toggle grid type):




VSWR circles.

Show VSWR circles with specified VSWR values around selected point. Enter VSWR values in the VSWR field (comma-separated) or click Edit VSWR circles to enter values in the list.

- Click on the chart to center VSWR circles.

• Edit VSWR circles center. Enter the center in the X and Y circles center fields.




Nyquist plot

Select AC/AC tools $\stackrel{\text{red}}{\sim}$ or click AC tools $\stackrel{\text{red}}{\sim}$ on the AC window toolbar, select Nyquist plot $\stackrel{\text{led}}{\hookrightarrow}$. Click Tool settings $\stackrel{\text{red}}{\uparrow}$ to configure Nyquist plot.

Trc - Settings - Nyquist plot	×
T rc - Settings - Nyquist plot	
Apply	Check traces to be shown on the graph

Select **Interval** of AC data to be shown in the Nyquist plot. **Check** traces in the list to be shown on the graph.



Zoom, scroll, mouse, and mouse-wheel operations are the same as in AC window. **Double-click** to center screen.

Right-click on the graph to show context menu.

Press Tab to show/hide unity circle.

AC histogram


Select AC/AC tools $\stackrel{\checkmark}{\sim}$ or click AC tools $\stackrel{\leadsto}{\sim}$ on the AC window toolbar, select AC histogram $\stackrel{\textcircled{}_{\sim}}{\cong}$. Click Tool settings $\stackrel{\textcircled{}_{\sim}}{=}$ to configure AC histogram.


Trc - Settings - AC hi	stogram		×
Y Y			×
Slope			
	Apply	Check traces to be shown o graph	n the

Y - histogram will display data calculated in the interval specified for AC table (AC table does not need to be shown).

X:

- **Traces**: show data as function of traces:





- **Storage**: show data as function of storage:

Check traces in the list to be shown on the graph.


Zoom, scroll, mouse, and mouse-wheel operations are the same as in AC window. **Right-click** on the graph to show context menu.

On the Screen tab 🔁 of Settings window, select Trace type: Line or Histogram.

VI. Tools

Script

Script is a program written in C language. In addition to standard operators and mathematical functions, it may use NL5-specific script commands, to change schematic parameters, run simulation, analyze data, and save simulation results.



To get help on specific operator, function, or command place cursor on the word in the script text and press **F1** or click **Help** button:

🖹 rc - Tools	for
🖙 🖬 🔿 💥 🗙 🖌 🎽 😫	IOr
🖹 Script 🔟 Console 🏘 Sweep 불	for. Loop operator.
<pre>double tau; clear; fpr(tau=1; tau<=10; tau+=1)</pre>	<pre>for(i=0; i<10; ++i) { x[i]=1<<i; pre="" y+="x[i];" }<=""></i;></pre>
Place cursor on for operator Click Help button or press F1	Help on for operator is displayed

Click **Run script** to run the script. Click **Stop script** K to stop the script. Script is applied to the active document.


When transient simulation commands tran or cont are executed by the script, transient mode is automatically set to **Single**, so that transient will always pause at the end of the screen. The next script command will not be executed until transient simulation is paused.

When AC simulation command ac is executed by the script, the next script command will not be executed until AC simulation is complete.

Script log and error messages are displayed on the **Console** $^{\boxed{11}}$ tab.

Console

Console has a command line, which can be used as a calculator or execute some script commands.



Similar to **Script** tab, to get help on specific operator, function, or command place cursor on the word in the command line and press F1 or click **Help** 2 button.

Command line can be used to evaluate expressions. Expression may contain:

- Numbers (including complex numbers).
- Component parameters and schematic variables of active document.
- Arithmetic operators and functions.
- Some script commands.
- Trace data.

Enter expression in the command line and press Enter to evaluate:

1+1 :2

To change component parameters or variables of active document, enter parameter name followed by equal sign and expression:

```
R1=10 :10
R2=R1*5 :50
```

You can also execute script commands from command line (all commands except logdata and exit). In addition, pause command will pause transient simulation. Commands are applied to active document. For example:

```
open rc.nl5
tran 0,1m,.1u
store
cont
```

Previous expressions and commands can be retrieved from drop-down list or by pressing **Up** and **Down** arrow keys. Press **Esc** to clear command line.

Sweep

Sweep Refer tab can be used to change component parameter in specified range, perform transient and/or AC analysis, and stores traces into storage.

🖹 rc - Tools		×
Script III Console		Optimization
R2.R ~ 1 10 1	Name From To Step ✓	 ✓ Transient △ AC ✓ Clear storage
10 Loop List	Points	

Click **Run script** \Rightarrow to run the sweep. Click **Stop script** $\stackrel{\bigstar}{}$ to stop the sweep. Sweep is applied to the active document.

Name. Name of the parameter to be changed. Enter parameter name manually or select from drop-down list. The list shows all numerical parameters of the selected component.

Transient. Select to run transient.

AC. Select to run AC analysis.

Clear storage. Select to clear storage when sweep starts. If nor cleared, sweep runs will be added to existing storage.

There are two types of sweep: Loop and List.

Loop.

From. Start parameter's value.

To. End parameter's value.

Step type:

- Step. Parameter is incremented (or decremented) by Step value.
- Step, %. Parameter is changed by specified percentage.
- Step, X. Parameter is multiplied by specified value.

Points field shows total number of steps to be performed.

List. Enter parameter values in the text field, one value per line:

	R2.R	∨ Name
	1 2 5 10	< >
	Enter values, one pe	er line
Ŀ	oop List	

Sweep results will be saved into storage. Only traces with enabled storage will be saved.


Script 1 tab contains text of the script that was executed, and Console 1 tab contains log of the script execution.

Transient Sweep parameter 🏼 command opens sweep tool with Transient checkbox selected.

AC Sweep parameter 🔌 command opens sweep tool with AC checkbox selected.

Optimization

Optimization performs transient and/or AC analysis while manually iterating selected parameters.



Select up to 16 schematic parameters to iterate. Use \checkmark and \uparrow buttons to add and remove rows with parameter values. If all rows do not fit the window, warning message will show up in the status bar: *"Resize window to see more rows and controls"*.

Specify the following parameters:

Name - name of the parameters to be changed. Enter parameter's name and press **Enter** or select parameter from drop-down list. The list shows all numerical parameters of the selected component.

Value - current values of specified parameters.

Step - how the value will change when **Plus** + or **Minus** - button is clicked. If **Step** is a number, the number will be added to current value. If **Step** is a number with '%' character at the end, the value will be changed by specified percentage.


Click \checkmark to clean up and update optimization table. It removes rows with empty name field, moves rows up to fill up gaps, and fills in **Value** fields with current component values.

If **Run on click** is selected, specified analysis will be started immediately when **Plus** + or **Minus** - button is clicked, or when **Enter** key is pressed at the **Value** field. Otherwise, click **Run script** to run analysis.

HTTP link


HTTP link provides remote access to NL5 from external application. NL5 serves as a "server", running built-in HTTP server. External application is a "client". NL5 and a client application may run on the same computer or on different computers, communicating through local network or Internet.

Select Tools/HTTP Link or start NL5 in command line with -http or /http switch to open HTTP Link window:



Default **Port** number is 80, which is standard port for HTTP protocol. If this port is already used, select any other available port number. Make sure the client application uses the same port number as NL5 in URL request. Please note that port number can be changed only before HTTP link is started the first time. To change the port number after that, close NL5 application and start it again. If NL5 and client application are running on different computers, make sure that any existing firewalls and routers are properly configured to allow TCP communication through specified port.

Click **Start** to start HTTP server. While server is running, the window will display IP address of the client, command received, and result sent to the client:



To disable the HTTP log, uncheck **Show log** option on **HTTP server** tab of **Preferences** dialog box., **Right-click** on the text area and select **Clear log** to clear the HTTP log.

The window can be closed at any time without affecting server operation. Click **Stop** to stop HTTP server.

Sending URL request. Client applications can issue commands and obtain data from NL5 by sending URL request with parameters and receiving back response in the text format. The "URL read" function name, syntax, and parameters may vary for different applications. For example, in the MATLAB urlread function can be used:

s = urlread('url')

Please be aware that according to recent MATLAB guidance, function urlread is not recommended. Use webread instead.

URL string has the following general format:

http://host_name:port/?cmd=command

where:

- *host_name* is the name or IP address of the computer where NL5 is running. If client application is running on the same computer with NL5, *host_name* can be 127.0.0.1, or localhost.
- *port* is the port number. It should be the same as port number specified in NL5. If default HTTP port number (80) is used, it can be omitted, so that URL string will look as follows:

http://host_namet/?cmd=command

• *command* is a script command or an expression.

NL5 executes command or evaluates expression and responds with a text, which can be:

- "OK".
- result of the expression in text format.
- comma-separated string for trace data request.
- error message (text).

For example:

```
        Request:
        Response:

        http://localhost/?cmd=open rc.nl5
        "OK"

        http://l27.0.0.l/?cmd=R1
        "100"

        http://l92.168.0.l/?cmd=C1=2n2
        "2.2e-9"

        http://public025:2119/?cmd=V(C1)%200,1,.2
        "0,9.99999424754,9.9999944731,..."

        http://localhost/?cmd=open test.nl5
        "Error opening file test.nl5"
```

If client application allows, the following modifications can be applied to URL string:

- Text "http://" can be omitted.
- Text "cmd=" can be omitted.

For example:

Request: Response: 127.0.0.1/?open rc "OK" 192.168.0.101/?R1 "100e+3" http://public025:222/?store R1 "OK"

Please be aware that not all characters can be transmitted over Internet in the URL request. Some characters are "reserved" and have a special meaning. Being used in the NL5 command, those characters may be misinterpreted and result in wrong operation. For instance, character '+' is typically interpreted as a "space". This makes it impossible to use exponential form of a number: "1.23E+6" will be interpreted as "1.23E 6" and will produce HTTP server error.

To be used in the NL5 command, reserved characters should be converted into "URL safe" format, where the character is represented by '%' symbol followed by two-digit hexadecimal number: ASCII code of the character ("percent-encoding").

In many cases, the only reserved characters to be used in the NL5 commands would be *space* and '+'. To ensure correct operation replace *space* with its code %20, and '+' character with %2B. For instance, "1.23E+6" should be sent as "1.23E%2B6".

All reserved characters and their codes can be found in public Internet resources.

Running simulation. When transient simulation command tran (or cont), or AC simulation command ac is issued through HTTP link, NL5 sends "OK" response immediately without waiting for simulation to complete. This is done avoid time-out condition in case of long simulation time. The client should wait for simulation end by periodically sending command ready and checking NL5 response. Response "0" means that simulation is still running, response "1" means that simulation is completed, and a new command can be issued. If the error occurs during simulation, NL5 responds with error message.

Troubleshooting. If there are any problems with obtaining response from NL5 with HTTP link, please try the following:

- 1. Start NL5 "As administrator" it helps avoiding many problems related to Win 10 security.
- 2. Start HTTP server (Tools/HTTP Link, Start).
- 3. In Windows: open "Start menu," type "Command Prompt," then select "Run as administrator."
- 4. Type "netstat -ab" without quotes, then press "Enter.":

Administrator: Command Prompt	
<pre>/icrosoft Windows [Version 10.0.1904 (c) 2020 Microsoft Corporation. All</pre>	
::\Windows\system32:netstat -ab	

5. Wait for the results to load. Port names will be listed listed next to each local IP address. You should see some text which says that nl5.exe is listening port 80 (TCP X.X.X.80)

TCP	0.0.0.0:80	FTC-HYSJ7G3:0	LISTENING
[n15.e	xe]		

If there is no such line, then NL5 server probably is not running. Check the list to see if there is a line with port 80 used by another application. If so, close that application, or use another port in NL5 (**Tools/HTTP Link, Port**).

6. Open some browser and enter address 127.0.0.1, you should see response from NL5 server:


~	\rightarrow	С	۵	0 🗅 127.0.0.1
				, 01/11/2022) 2, A.Smirnov

If you don't see that, please contact us and provide information about what exactly is shown, any error/warning messages, etc.

7. Make sure there are no active firewalls, proxy servers, etc., which may restrict communication with HTTP server.

NL5-MATLAB link example


The following example shows using NL5 HTTP link with MATLAB. NL5 has HTTP server running, and schematic "link_example.nl5" loaded. Transient window shows schematic response on V1 step function for R1=1:



The code listed below has been loaded into MATLAB from the file "link example.m" and executed:

```
clear
clc
close all
R=logspace(-1,1);
Header='http://127.0.0.1/?';
Cmd2=[Header, 'tran'];
Cmd3=[Header, 'ready'];
Cmd4=[Header, 'V(out)%200,50,.1'];
for k=1:length(R)
    Cmd1=[Header, 'R1=', num2str(R(k))];
    urlread(Cmd1);
    urlread(Cmd2);
    Response='0';
    while strcmp(Response,'0')
        Response=urlread(Cmd3);
    end
    Graph(k,:)=str2num(urlread(Cmd4));
end
Graph=Graph';
surf(Graph)
shading flat
colormap jet
colorbar
ylim([0 400])
```

The code changes R1 in the range 0.1...10 with logarithmic step, calculates transient, reads V(out) trace data, and displays V(out) at 3-D graph as a function of time and R1 value:



Example schematic and MATLAB files are located in the Examples/MATLAB folder of the NL5 download package.

Scope

Scope tool provides access to popular models of oscilloscopes (Keysight Technologies, Tektronix, LeCroy). You can configure channels and modes, obtain measured traces, and configure Waveform Generator (Arbitrary Function Generator).

To communicate with the oscilloscope, NL5 is using National Instruments **NI-VISA** drivers, which can be downloaded at National Instruments website (www.ni.com). NL5 loads visa64.dll library when the Scope tool window opens first time. If library is not available, an error message will show up.

Select **Tools/Scope** or start NL5 in command line with -scope or /scope switch to open Scope window. Please note that the screenshots below are for illustration purposes only: a real screen view and controls may vary depending on a specific oscilloscope model.

Toolbar buttons perform the following operations:

Refresh resources. Show list of instruments, select instrument.

Update scope settings. Read settings from the oscilloscope. Should be used synchronize oscilloscope and NL5 settings, in case if anything was changed through the scope interface.

Read traces from the oscilloscope. NL5 will stop data acquisition, and read traces currently displayed on the oscilloscope. For Keysight Technology oscilloscope, click arrow-down button on the right to select the data record to be transferred from the oscilloscope:



Normal - the measurement record is retrieved.

Raw - the raw acquisition record is used.

Maximum - whichever record contains the maximum number of points is used.


Screenshot. Download and display a picture from the oscilloscope screen. To copy the picture into the clipboard, or to save into the file in different formats, click arrow-down button on the right to open drop-down menu, and select an operation:



Run the oscilloscope in **single** mode.

Run the oscilloscope in **continuous** mode. For LeCroy oscilloscope, click arrow-down button on the right to select triggering mode:





Send configudata data to the waveform generator.

T Settings. Open Scope settings dialog box:

Scope settings	×
Screenshot Black background Expand window if needed	Traces Overwrite existing Create new
Analog channels Use scope scale Use scope color	Close

Screenshot.

Black background. If selected, read screen picture with black background.

Expand window if needed. When screen picture is bigger than current size of the Scope window, expand the window so that the picture fits in properly.

Analog channels.

Use scope scale. When reading traces from the oscilloscope, set scale and offset of the trace in NL5 to a current scale of the trace on the oscilloscope (not used for LeCroy oscilloscopes).

Use scope color. When reading traces from the oscilloscope, set a color of the trace to a trace color on the oscilloscope.

Traces.


Override existing. When reading traces from the oscilloscope, if a trace with the same name already exists, delete existing data download new data into existing trace.

Create new. When reading traces from the oscilloscope, if a trace with the same name already exists, create a new trace.

Keep scope window on top. If selected, keep Scope window on top of other NL5 windows.

Working with oscilloscope

Configuring oscilloscope. When instrument is selected, NL5 reads some configuration information from the oscilloscope, and shows it on the **Scope** tab:



Depending on the oscilloscope model, there could be up to four tabs, describing analog, digital, bus, and segmented memory settings. If any of displayed settings were changed directly through the oscilloscope

controls, or any other oscilloscope interface, click **Update scope settings** to retrieve new settings, and update information in the Scope tool.

Check/uncheck **Show labels** checkbox to show/hide channel labels on the oscilloscope screen (Keysight Technologies only).

Analog tab displays analog channel settings. List of channels shows all available analog channels of the oscilloscope. State of the checkbox indicates whether the channel is visible on the oscilloscope. Color box indicates trace color on the oscilloscope screen. Enter new **Label**, **Scale**, or **Offset** and press **Enter** to submit (not available for LeCroy oscilloscopes).

Digital tab displays digital channel settings:

Analog Digital Bus Segm		Show labels
♥ 00 ♥ D1 ♥ D2 ♥ D3 ♥ D4 ♥ D5 ♥ D6 ♥ D7 ♥ D8 ♥ D9 ♥ D10 ♥ D11 ♥ D12 ♥ D13 ♥ D15	D0 Label Position 0	

List of channels shows all available digital channels of the oscilloscope. State of the checkbox indicates whether the channel is visible on the oscilloscope. Enter a new **Label** or **Position** value and press **Enter** to submit.

Bus tab displays bus channel settings:

Analog Digital Bus Segm		Show labels
■ B1 ♥ B2 ♥ B3 ♥ B4	B1 Label D3 D2 D1 D0 Position Save as: Signed	MSB D15 D14 D13 D12 D11 D10 D9 D9 D9 D8 Remove D7 D6 D5 D4 Clear
Check all Uncheck all		LSB

Bus configuration tab may vary depending on a specific oscilloscope model.

List of channels shows all available bus channels of the oscilloscope. State of the checkbox indicates whether the channel is visible on the oscilloscope. Enter a new **Label** or **Position** value and press **Enter** to submit. Select **Signed** or **Unsigned** mode from **Save As** drop-down list to specify how the bus value is converted into NL5 number representation. This will affect how the bus numbers will be displayed on the NL5 graph.

To configure bus bits, click Add , Remove , or Clear to fill in the left box with required bus bits. Right box consists of bits currently available for the bus. MSB and LSB labels indicate most-and least-significant bit of the bus.

Analog Digita	Bus Segm	🔲 Show labels
🔲 Segment	ed ON	
10	Number of segments	
1 2 3 4 5 6 7 8 9 10	Current segment	

Segm (or Fast frame) tab displays segmented memory operation settings:

Segmented memory configuration tab may vary depending on a specific oscilloscope model.

Select **Segmented ON** check box to enable segmented memory operation. Enter **Number of segments**, press **Enter** to submit. Select **Current segment** in the list, to display it on the oscilloscope.


Screenshot tab displays an oscilloscope screenshot. Click **Read screenshot** to download a screenshot and display it on the tab:



Depending on **Scope settings** the screenshot may be obtained with black or white background. Scope window size may also be expanded automatically to fit the image.

Please note that Tektronix 3000/4000 series requires a flash drive to be present at the E: drive USB port of the oscilloscope (usually located at front panel). It is used for storing an intermediate image file.

Log tab shows commands executed in the last operation:



It also has a command line option. Enter a command or select previously issued commands from the drop-down list, then press **Enter** to execute:

		_
\times	:DIG12:DISP?	•

Click **Clear log** \times to clear the log window.

Working with waveform generator


Wave Gen tab is used to create a signal for Waveform Generator (Arbitrary Function Generator), and send it to the oscilloscope:

🖬 Scope - None	×
'''''''''''' ''''''''''''''''''''''''	
Instruments Scope Screenshot Wave Gen Log	
🗖 Wave Gen ON	
🗖 Interpolate	
Source: Component	-
Component not selected	
ок	11.

Select **Wave Gen ON** check box to enable waveform generator. Select **Interpolate** checkbox to enable signal interpolation (Keysight Technologies only).

Select **Source** to use signal source. There are four source options available for Wave Generator.


Component. Use **Voltage source** or **Label** NL5 component settings to specify a waveform. The following models of the component are supported: **V**, **Pulse**, **Sin**, **PWL**, **Function**, **File**, **Trace**. Select the component in the schematic:



A preview of the waveform will be shown in the Scope window:


📑 Scope - None		×
물 등 중 💁 • 러 →	<u>★</u> 문 T	
Instruments Scope Screenshot Way	re Gen Log	_
I Wave Gen DN I Interpolate Source: Component I Name: V1		
	Wave Gen function: PULSE	
ОК		//

If component model and parameters allow, a built-in wave form generator function will be used (**DC**, **SIN**, **PULSE**). Otherwise, and arbitrary generator waveform **ARB** will be used. For example, the following signal will require an arbitrary function:




For arbitrary function, number of **Points** should be specified: enter the number and press **Enter**.

Trace. Select a trace in the NL5 transient window, and use cursors to specify a trace interval which will be used for the waveform. A preview of the waveform will be shown in the Scope window:




Specify number of **Points** and press **Enter**.

Function. Enter an arbitrary function for a waveform, use **t** parameter as a time. Also, enter number of **Points**, **Start**, and **End** time for the function:




List. Enter waveform points as a list of numbers in "time, amplitude" format:



Specify number of **Points** and press **Enter**. Please note that number of points is not number of points in the list: it is number of samples to generate waveform signal.

When waveform signal is ready, click **Send to scope** $\overline{\clubsuit}$ to send waveform points to the Waveform Generator.

Working with segmented memory




Here are two signals (pulse and sine) with small frequency difference:

Turn on segmented memory, enter number of segments, and press Enter:

Analog Digit	al Bus	Segm				
Segmented ON						
10	Number of segments					
1 2	Current	segment				
1		-				

Run the oscilloscope (in single or continuous mode):



Read traces \mathfrak{F} from the oscilloscope:




On this graph, segmented memory pieces are displayed according to their absolute time.


To display segments in "overlaid" mode (relative to the time when segment was triggered), go to **Transient settings** I window, **Storage** tab, unselect "**Use time shift** (**Scope**)" option:

\$₹	٠	***		٩٢			
☐ Store last Run ☐ Use time shift (Scope)							

Here is an "overlaid" view of the segmented memory data (you may need to auto-scale the graph horizontally by clicking **Fit the screen** ::



To see individual segments, select Selected only or Selected and dimmed storage display mode.



Look thought the segments on the graph by left-clicking on the storage list, and then pressing Up/Down keyboard keys:

