RADIANT HEATING SYSTEMS

MANUAL FOAM STAPLER

TECHNICAL BULLETIN



Application

The Manual Foam Stapler fastens ⅜", ½" and ⅝" PEX tubing to rigid insulation (e.g., extruded polystyrene). Use the 1½" Foam Staple (part number A7015050) for 1" foam insulation and the 2½" Foam Staple (part number A7015075) for 1½" or thicker foam insulation.

Part Number

E6025075

Inspection

Remove the Manual Foam Stapler from the box and check for any damage that may have occurred during shipping. Ensure the guide is straight and attached securely to the Manual Foam Stapler.

Operation

Slide the foam staples down the guide with the prongs facing away from the Manual Foam Stapler. Remove the adhesive tape from the staples.

Note: Failure to remove the tape from the staples will cause adhesive buildup which will obstruct the tool from operating properly.

Caution: The Manual Foam Stapler cannot stand upright. If it falls, the guide may bend and the Manual Foam Stapler will not work properly.

Uponor, Inc.
5925 148th Street West
Apple Valley, MN 55124
Tel: (800) 321-4739
Fax: (952) 891-1409
Web: www.uponor-usa.com
E-mail: learnmore@uponor-usa.com

Uponor Ltd.
655 Park Street
Regina, SK S4N 5N1
Tel: (888) 994-7726
Fax: (800) 638-9517
Web: www.uponor.ca
E-mail: info@uponor.ca

ManualFoamStapler_TB_9_06, Copyright © 2006 Uponor, Printed in the United States