

Druck DPI 705 and DPI 705 IS

Digital Pressure Indicators



Calibration Instructions

WARNING: CALIBRATE DPI 705 IS INSTRUMENTS IN A SAFE AREA.

The instrument performs a two-point compensation at ZErO and FS (full-scale.)

Preparation

1. Connect the instrument to a pressure source that has an accuracy three times better than the instrument.
Recommended:- Druck DPI 610 or DPI 610 IS Portable Calibrator.

2. Switch on the instrument and select the units of pressure measurement required for calibration.

Procedure

1. Press all three keys together to enter the CAL menu and proceed as shown:

Changing the PIN


Each digit can be changed in turn.

Pressing:

increases the value of the digit.

steps to next digit, left to right.

enters the PIN



Druck Incorporated, 4 Dunham Drive, New Fairfield, Connecticut 06812, U.S.A.

Tel: (203) 746 0400


Fax: (203) 746 2494

Email: sales@druckinc.com

Internet <http://www.druckinc.com>

Druck DPI 705 and 705 IS Digital Pressure Indicators

Configuration Instructions



The LOCKED pressure indicator only measures pressure/temperature in the selected units and does not process data. Alarm, leak and other process functions are not available.

Software Version These calibration and configuration instructions are for instruments with software version 1.02 onwards. Further changes to the instrument's software may require a change to the procedures and an issue number change to these instructions.