



A - ZERO ~ SPAN Increase
 CURVE-1: ZERO -, SPAN +;
 CURVE-2: ZERO 0, SPAN +;
 CURVE-3: ZERO +, SPAN +;
 B - ZERO ~ SPAN Decrease



CURVE-1: ZERO -, SPAN +;
 CURVE-2: ZERO 0, SPAN +;
 CURVE-3: ZERO +, SPAN +.



FUN

Press this key for show every function's value, (SPAN/ZERO/d.P/inP).

Press this key and hold 3 seconds for preset function value, When the what's function you show.

▶

Press this key for shift right of flash-digit (which one you can change data), When you are in changing data function.

▲

Press this key for increase 1 of flash-digit (which one you can change data), When you are in changing data function.

R

Press this key quit from for show every function's value.

In normal (show present value), Press this key with FUN-key for 3 seconds to preset zero point (the data under this point will be show 0).

0 FUN ▶ ▲ R

When the value was changed,
 you have to press R-key to save new value.

2.345

In normal press this key show every function, when press once will change to show next function value.

1 FUN ▶ ▲ R

Inter - Show SPn

1-1 FUN ▶ ▲ R

press for 3 seconds

1-2 FUN ▶ ▲ R

press for 3 seconds

1-3 FUN ▶ ▲ R

press for 3 seconds

2 FUN ▶ ▲ R

Inter - Show 5.000

2-1 FUN ▶ ▲ R

press for 3 seconds

2-2 FUN ▶ ▲ R

press for 3 seconds

2-3 FUN ▶ ▲ R

press for 3 seconds

3 FUN ▶ ▲ R

Inter - Show 2E0

3-1 FUN ▶ ▲ R

press for 3 seconds

3-2 FUN ▶ ▲ R

press for 3 seconds

3-3 FUN ▶ ▲ R

press for 3 seconds

4 FUN ▶ ▲ R

Inter - Show 00.00

4-1 FUN ▶ ▲ R

press for 3 seconds

4-2 FUN ▶ ▲ R

press for 3 seconds

4-3 FUN ▶ ▲ R

press for 3 seconds

5 FUN ▶ ▲ R

Inter - Show dP

5-1 FUN ▶ ▲ R

press for 3 seconds

5-2 FUN ▶ ▲ R

press for 3 seconds

5-3 FUN ▶ ▲ R

press for 3 seconds

6 FUN ▶ ▲ R

Inter - Show 0003

6-1 FUN ▶ ▲ R

press for 3 seconds

6-2 FUN ▶ ▲ R

press for 3 seconds

6-3 FUN ▶ ▲ R

press for 3 seconds

7 FUN ▶ ▲ R

Inter - Show 0

7-1 FUN ▶ ▲ R

press for 3 seconds

7-2 FUN ▶ ▲ R

press for 3 seconds

7-3 FUN ▶ ▲ R

press for 3 seconds

Press FUN-key once return normal (Show Present Value).