PRODUCT SAFETY & RELIABILITY DEPARTMENT



E: PRODUCTSAFETY@JLG.COM



Attn: Safety Manager or Service Manager

Subject: ANSI/SAIA Manual of Responsibilities

On August 15, 2021 the Scaffold & Access Industry Association (SAIA) announced that the American National Standards Institute (ANSI) Board of Standards Review has published and immediately made effective a new version of the following standards:

- ANSI/SAIA A92.20 2021 Design, Calculations, Safety Requirements and Test Methods for Mobile Elevating Work Platforms (MEWPs)
- ANSI/SAIA A92.22 2021 Safe Use of Mobile Elevating Work Platforms (MEWPs)

The revision to the standards listed above removes the requirement for manufacturers to provide, and for owners and users to maintain, the ANSI Manual of Responsibilities (MoR) on MEWPs. ANSI/SAIA A92.20 - 2021 Section 6.2.1 now requires that manufacturers provide notice of the requirements of dealers, owners, users, operators, lessors, lessees, and brokers to comply with the appropriate section(s) of applicable A92 standards.

To meet the requirement defined in section 6.2.1 of ANSI/SAIA A92.20 – 2021, JLG Industries, Inc. ("JLG") will continue to provide the MoR with every new ANSI Market MEWP. The MoR provides dealers, owners, users, operators, lessors, lessees, and brokers with their responsibilities and aids in the safe use of a MEWP.

ANSI/SAIA A92.22 - 2021 for the Safe Use of MEWPs, according to Section 1.1.2, provides responsibilities for manufacturers, dealers, owners, users, supervisors, operators, occupants, lessors, lessees, and brokers for both new and existing units delivered for sale, lease, rental or any form of beneficial use on or after that effective date.

To help those entities listed above ensure compliance with their responsibilities set forth in ANSI/SAIA A92.22 - 2021, JLG will continue to require as part of the Pre-Start Inspection that all existing ANSI Market MEWPs manufactured by JLG include the Operation and Safety Manual, AEM Safety Handbook, and the ANSI Manual of Responsibilities be located in the manual storage compartment on the machine.

According to ANSI, A92.20 and companion standards A92.22 and A92.24 have been developed to replace previous ANSI A92 Standards (including A92.3, A92.5, and A92.6). Each Manual of Responsibilities for A92.3, A92.5, and A92.6 have been replaced by *The Manual of Responsibilities for manufacturers, dealers, owners, users, supervisors, operators, occupants, lessors, lessees, and brokers of ANSI/SAIA A92.22 Safe Use and ANSI/SAIA A92.24 Training Requirements for the Use, Operation, Inspection, Testing and Maintenance of Mobile Elevating Work Platforms (MEWP).*

JLG has superseded each Manual of Responsibilities for A92.3, A92.5, and A92.6 to the Manual of Responsibilities for A92.22 referenced above. The MoR for A92.3, A92.5, and A92.6 are no longer available from JLG.