

Walter™ 3 Patch_090417 Guide



Step 1: Downloading the patch file


• Click on the link http://www.etllearning.com/wp-content/uploads/2017/08/ET-Activity-2-160817.bin_.zip to download the zipped file (ET-Activity 2 160817.bin).





Step 2: Extracting the patch file

 Unzipping the file by right clicking the file, mouse-over the name of your unzipping software (7-Zip/Winzip/Winrar), thereafter, you can choose the option of 'extract here' to successfully extracting the file.





Step 3: Connecting your Walter™


• Using the Micro-USB cable provided, connect your Walter™ 3 to your computer.





Step 4: Transferring of patch file

• Look for the connected Walter™ 3 (on either D: or E: drive)





Step 5: Delete the previous file

• Delete the file named (*ET-Activity 02.bin*)

Name	Date modified	Type	Size
English-LMA11.bin	3/20/2017 10:33 AM	BIN File	31,255 KB
English-suoyin.bin	3/20/2017 11:11 AM	BIN File	125,027 KB
ET-Activity 1.bin	3/29/2017 4:31 PM	BIN File	29,686 KB
ET-Activity 2	2:41 PM	BIN File	27,787 KB
Open with	1:49 AM	BIN File	21,333 KB
T-Zip	5:17 PM	BIN File	18,826 KE
ET-Activity CRC SHA	5:35 PM	BIN File	23,632 KE
ET-Activity 6 Scan with Windows Defender.	2:46 PM	BIN File	29,516 KE
ET-Activity 7 Send to	> 3:01 PM	BIN File	27,310 KE
ET-Activity & Cut	8:01 PM	BIN File	23,868 KE
ET-Activity S Copy	4:16 PM	BIN File	25,775 KE
ET-Activity 1	3:48 PM	BIN File	28,945 KB
ET-Reader0 Create shortcut	5:13 PM	BIN File	25,994 KE
ET-Reader02 Delete	5:25 PM	BIN File	22,762 KE
ET-Reader0: Rename	5:53 PM	BIN File	18,722 KE
ET-Reader04 Properties	5:54 PM	BIN File	20,282 KE
ET-Reader05.pm	3/28/2017 5:56 PM	BIN File	27,122 KE
Th ex n 1 2011	2 12 2 12 1 7 7 7 7 1 1	500 60	10 007 110



Step 6: Replace the patch files

• Copy the extracted file (ET-Activity 2 160817.bin) and the update is completed!

