

OLYMPUS

CAMEDIA

DIGITAL COLOR PRINTER

P-400


INSTALLATION GUIDE



ENGLISH

Using the parallel cable to connect the printer (Windows 95/98/2000 and NT4.0)

- 1 Turn the printer off. (Also turn the PC off.)
- 2 Connect the parallel cable to the P-400.



- 3 Connect the parallel cable to the PC.




Important
For information on connecting the cable to the PC, refer to your PC User's Manual.


Connecting the P-400 to a PC

•Make sure that you have an interface cable on hand.

- 1 Turn the printer off. (Also turn the PC off.)
- 2 Connect the USB cable to the P-400.



- 3 Connect the USB cable to the PC.



Important
For information on connecting the cable to the PC, refer to your PC User's Manual.

Using the USB cable to connect the printer (USB-compatible Windows 98/2000 PCs and Macintosh computers)



Conditions for using the USB cable

PCs with which the USB cable can be used are listed on the right.

- PCs pre-installed with Windows 98/Windows 2000
- PCs pre-installed with Windows 98/Windows 2000 that are USB-guaranteed by the manufacturer
- Macintosh computers that are USB-guaranteed and have a USB-compatible OS.

Setting up the printer


- 1 Turn the printer on.
- 2 Set the mode selector dial to the "INPUT" position.



- 3 Use the left or right arrow button to select the input method.

For a Windows PC, select USB or Parallel to comply with the input method you are using.
For a Macintosh, select USB.

Check that USB or Parallel is displayed at the top of the LCD panel.



Important
Each time you press the directional buttons the printer cycles through the settings in the following order: SmartMedia, PC card, Parallel, USB.

Windows 98 PC connected using a USB cable

Windows PC connected using a parallel cable

Installing a printer driver

Windows 2000 PC connected using a USB cable

Macintosh connected using a USB cable

Refer to "Installing the printer driver (p. 27)" for more information on printer driver hardware requirements.

Windows 98 PC connected using a USB cable
Windows PC connected using a parallel cable
Windows 2000 PC connected using a USB cable
Macintosh connected using a USB cable

1 Turn the PC on and start Windows.

The Add New Hardware Wizard appears automatically.


2 Click Next.



3 Select "Search for the best driver for your device. [Recommended]." and click Next.



4 Load the P-400 printer driver CD-ROM into the PC.



5 In the Specify Search Area drop-down box, specify the Driver folder in the English folder of the CD-ROM and click Next.




This screen shows the CD-ROM drive as the J drive. Change the letter "J" to match the CD-ROM drive of the computer you are using.

6 Click Next.



7 Click Finish.



A USB port will be installed.

8 Start the set-up program.


① Double click the Driver folder in the "English" folder of the CD-ROM.




② Double click "Setup.exe" in the Driver folder.



The set-up program starts and the following screens appear in the order shown.



9 Click Next.




10 Specify USB as the method of connection and click Next.



This screen does not appear for Windows NT 4.0 or Windows 2000.

11 Click Finish.



Installation of the P-400 printer driver is complete.

Windows 98 PC connected using a USB cable

Printer driver installation

Windows PC connected using a parallel cable


1 Turn the PC on and start Windows.

The Add New Hardware wizard appears automatically.

2 Click Cancel.



3 Load the P-400 printer driver CD-ROM into the PC.




4 Start the set-up program.

① Double click the Driver folder in the "English" folder of the CD-ROM.




② Double click "Setup.exe" in the Driver folder.




The set-up program starts and the following screens appear in the order shown.



5 Click Next.



6 Specify Parallel as the method of connection and click Next.



This screen does not appear for Windows NT 4.0 or Windows 2000.

7 Click Finish.



Installation of the P-400 printer driver is complete.

Windows 2000 PC connected using a USB cable

1 Install the printer driver.

For information on installing the printer driver, refer to "Windows PC connected with a parallel cable".

2 Double click the Printers folder in the Control Panel folder.



3 Right-click on the OLYMPUS P-400 icon in the Printers folder.




4 Click Properties in the menu that appears.



The OLYMPUS P-400 properties dialog box appears.

5 Select the Port tag, check USB001 in the Port list box and click OK.




If several USB printers are connected, they are displayed as "USB001", "USB002", etc. Select the port to which the P-400 is connected.

Installation of the P-400 printer driver is complete.

Macintosh computer connected using a USB cable

1 Start the Macintosh and load the P-400 printer driver CD-ROM.




2 Start the installation program.

① Double click the Driver folder in the English folder of the CD-ROM.



② Double click the installer icon in the Driver folder.



The installation program starts.

3 Click Continue.



4 Read the license agreement and if you agree to the terms, click Agree.




5 Click Install.



The printer driver will be installed.

6 Click Quit.



7 Select the "Chooser" from the Apple menu.


• Before using the Chooser to select the printer, check that the P-400 has been turned on and that a USB cable connects the P-400 and the Macintosh.




8 Click the P-400 printer driver icon.

• If the P-400 icon does not appear in the Chooser window, check the following.

• If the window contains more data than it can display, the icon may be hidden in the window. In this case, use the scroll bar to scroll in the window and display the icon.



9 From the Printer Select box, select the P-400 as the printer you want to connect and click Close.



• If the P-400 does not appear in the Select printer box when you click the printer driver icon, check that the USB cable is connected, that the printer is on, and that Select input is set to USB.

• If you check the On checkbox for Background printing, you can continue to work in other programs while printing is being carried out.

Installation of the P-400 printer driver is complete.